OMB Approval Number: 2050-0095
Approved for Use Through: 4/95



Site Name: GNB, Inc. CERCLIS ID No.: TXD007331879

Street Address: 1880 Valley View Lane City/State/Zip: Farmers Branch, TX 75234

Investigator: S. Bret Kendrick Agency/Organization: ICF Technology

Street Address: 750 N. St. Paul, Suite 700

City/State: Dallas, TX

Date: Feb. 1993

Page: 1

OMB Approval Number: 2050-0095 Approved for Use Through: 4/95

						veu 101			
	POTENTIAL HA2	ZADDOIIG				IDENTIFICATION			
	POIENTIAL NAZ	ARDOOS				State: CERCLIS Num			umber:
	WASTE SITE					TX	TX	D00733	1879
PRELIMINARY ASSESSMENT FORM						CERCLIS	Disc	overy	Date:
1. Gene	eral Site Info	rmation		·	<u>-</u>				
Name: GNB, Inc.				Street 1880		ess: y View L	ane		
City: Farmers Branch			State: TX			County Dallas		Co. Code:	Cong. Dist:
Latitude: Longitude: Approx. 35° 55' 12.0" 96° 54' 58.0"				. Area of Site: Status of Site: 10 acres Active					
2. Owne	er/Operator In	formation							
Owner: GNB, I	inc.			Operator: GNB, Inc.					
	Address: Valley View La	ine		Street Address:					
City: Farmers Branch				City:					
State: TX	Zip Code: 75234	Telephon 214-243		State:	Zip 7523	Code:		phone: -243-1	011
Type of Ownership: Private				How Initially Identified: RCRA/CERCLA Notification					

Page: 2

DOMENIMIA I HAZA	POTENTIAL HAZARDOUS					IDENTIFICATION		
WASTE SITE						CERCLIS TXD007	1	
PRELIMINARY AS	CERCLIS	Discovery	y Date:					
3. Site Evaluator Information								
Name of Evaluator: Agency, S. Bret Kendrick ICF Te				anization ology	1:	epared: 1993		
Street Address: 750 N. St. Paul, Suite 700			City: Dallas			State: TX		
Name of EPA or State Lonnie Ross	Agency Co	ontact:	Telephone: (214) 655-6665					
Street Address: 1445 Ross Ave., Alli	ed Bank l	Bldg.	Cit Da	ty: allas			State: TX	
4. Site Disposition (	for EPA 1	use only	)					
Emergency Response/Removal Assessment		ndation: Priority	СТ	Signatu	re:			
Recommendation: No	nigher	riforicy	51	Name:				
Date:	Date:			Positio	on:			

Page: 3

IDENTIFICATION POTENTIAL HAZARDOUS State: CERCLIS Number: WASTE SITE ТX TXD007331879 PRELIMINARY ASSESSMENT FORM CERCLIS Discovery Date: 5. General Site Characteristics Predominant Land Uses Within Years of Operation: Site Setting: 1 Mile of Site: Beginning Year: 1971 Industrial Suburban Ending Year: 1993 Type of Site Operations: Waste Generated: Manufacturing Onsite Other Manufacturing RCRA Waste Deposition Authorized Large Quantity Generator By: Present Owner Waste Accessible to the Public No Distance to Nearest Dwelling, School, or Workplace: 2000 Feet 6. Waste Characteristics Information Quantity Source Type Tier General Types of Waste: Surface impoundment 3.61e+03 cu yds V Metals Surface impoundment 3.61e+03 cu yds V Surface impoundment 1.27e+05 cu ft V Physical State of Waste as Deposited Sludge Tier Legend C = Constituent W = Wastestream V = Volume A = Area

Page: 4

DOMENTAL WARADO	POTENTIAL HAZARDOUS					
WASTE SITE	State:	CERCLIS TXD0073				
PRELIMINARY ASSES	CERCLIS	Discovery	Date:			
7. Ground Water Pathway						
Is Ground Water Used for Drinking Water Within 4 Miles: No Type of Ground Water Wells Within 4 Miles: None	Is There a Suspected Release to Ground Water: Yes  Have Primary Target Drinking Water Wells Been Identified: No	Population Ground Works From:		by		
Depth to Shallowest Aquifer: 5 Feet  Karst Terrain/Aquifer Present: No	Nearest Designated Wellhead Protection Area: None within 4 Miles	>2 - 3	Miles Miles Miles	0 0 0 0		

Page: 5

IDENTIFICATION POTENTIAL HAZARDOUS State: CERCLIS Number: WASTE SITE TX TXD007331879 PRELIMINARY ASSESSMENT FORM CERCLIS Discovery Date: 8. Surface Water Pathway Part 1 of 4 Type of Surface Water Draining Shortest Overland Distance From Any Site and 15 Miles Downstream: Source to Surface Water: Stream River 3000 Feet 0.6 Miles Is there a Suspected Release to Site is Located in: Surface Water: No Annual - 10 yr floodplain 8. Surface Water Pathway Part 2 of 4

Drinking Water Intakes Along the Surface Water Migration Path: No Have Primary Target Drinking Water Intakes Been Identified: No

Secondary Target Drinking Water Intakes: None

Page: 6

POTENTIAL HAZARDOUS

WASTE SITE

PRELIMINARY ASSESSMENT FORM

**IDENTIFICATION** 

State: TX

CERCLIS Number: TXD007331879

CERCLIS Discovery Date:

#### 8. Surface Water Pathway

Part 3 of 4

Fisheries Located Along the Surface Water Migration Path: Yes

Have Primary Target Fisheries Been Identified: No

Secondary Target Fisheries:

Fishery Name

Water Body Type/Flow(cfs)

Elm Fork

moderate-large stream/ >100-1000

Trinity large stream/river/ >1000-10000

#### 8. Surface Water Pathway

Part 4 of 4

Wetlands Located Along the Surface Water Migration Path? (y/n) No

Have Primary Target Wetlands Been Identified? (y/n) No

Secondary Target Wetlands:
None

Other Sensitive Environments Along the Surface Water Migration Path: No

Have Primary Target Sensitive Environments Been Identified: No

Secondary Target Sensitive Environments:

None

Page: 7

POTENTIAL HAZARDOUS

WASTE SITE

PRELIMINARY ASSESSMENT FORM

IDENTIFICATION

State: CERCLIS Number:
TX TXD007331879

CERCLIS Discovery Date:

#### 9. Soil Exposure Pathway

Are People Occupying Residences or Attending School or Daycare on or Within 200 Feet of Areas of Known or Suspected Contamination: No

Number of Workers Onsite: 101 - 1000

Have Terrestrial Sensitive Environments Been Identified on or Within 200 Feet of Areas of Known or Suspected Contamination: No

#### 10. Air Pathway

Total Population on or Wit	thin:	Is There a Suspected Release to Air:	No
0 - 1/4 Mile >1/4 - 1/2 Mile >1/2 - 1 Mile	5 33 95	Wetlands Located Within 4 Miles of the Site:	No
>2 - 3 Miles 297 >3 - 4 Miles 283	404 788 342 007	Other Sensitive Environments Located Within 4 Miles of the Site:	No

Sensitive Environments Within 1/2 Mile of the Site: None

#### WASTE CHARACTERISTICS

Waste Characteristics (WC) Calculations:

1 SWMU 5 and 6 Surface impoundment Ref: 1 WQ value maximum

Volume 3.61E+03 cu yds 1.44E+03 1.44E+03 SWMU 5 and SWMU 6 were hydraulically connected and together basically formed an inverted, truncated pyramid, approximately 120 feet x 120 feet at the base, by 12 feet deep, with side walls having a 33% slope. The volume of this pair of impoundments was estimated to be 3,612 cubic yards (Rer. 1, p. 37).

Ref: 1

2 SWMU 7 and 8 Surface impoundment Ref: 1 WQ value maximum

Volume 3.61E+03 cu yds 1.44E+03 1.44E+03 SWMU 7 and SWMU 8 were hydraulically connected and together formed basically an inverted, truncated pyramid, approximately 120 feet x 120 feet at the base, by 12 feet deep, with side walls having a 33% slope. The volume of this pair of impoundments was estimated to be approximately 3,612 cubic yards (Ref. 1, p. 37).

Ref: 1

3 SWMU 9 Surface impoundment Ref: 1 WQ value maximum

Volume 1.27E+05 cu ft 1.87E+03 1.87E+03

Volume of the dry waste pit was calculated by using a scale drawing of the site. The scale of the drawing was 1"=300'. The length of the impoundment was measured to be 15/16". The length in feet was then calculated to be 281.25' by the following formula:

15/16 x 300 = 281.25

The width was calculated in a similar manner. The width was measured to be 6/16". The width in feet was calculated by the following formula:

 $6/16 \times 300 = 112.5$ 

Ref: 1, 21

WQ total 4.76E+03

#### Ground Water Pathway Criteria List Suspected Release

Are sources poorly contained? (y/n/u)	Y
Is the source a type likely to contribute to ground water contamination (e.g., wet lagoon)? (y/n/u)	Y
Is waste quantity particularly large? (y/n/u)	Y
Is precipitation heavy? (y/n/u)	N
Is the infiltration rate high? (y/n/u)	Y
Is the site located in an area of karst terrain? (y/n)	N
Is the subsurface highly permeable or conductive? (y/n/u)	Y
Is drinking water drawn from a shallow aquifer? (y/n/u)	N
Are suspected contaminants highly mobile in ground water? (y/n/u)	N
Does analytical or circumstantial evidence suggest ground water contamination? (y/n/u)	Y
Other emiteria? (w/n)	

Other criteria? (y/n) N

SUSPECTED RELEASE? (y/n)

Summarize the rationale for Suspected Release:

GNB manufactures automotive batteries. The facility operated 4 settling ponds and a dry waste pit from 1972 to 1985. The settling ponds received treated wastewaters from neutralization pits. The slurry resulted from the neutralization of sulfuric acid and contained high levels of lead. The solids contained within the slurry were allowed to settle to the bottom of the impoundments, and the wastewater was eventually discharged to the sanitary sewer (Ref. 1, p. 37). Lead containing sludge was chemically fixed and transferred to the dry waste pit prior to eventual off-site disposal (Ref. 1, p. 37). None of the pits were lined (Ref. 1, pp. 37, 52). See Attachment A.

## **ATTACHMENT 1**

## ANALYTICAL RESULTS FOR GROUND WATER SAMPLING CONDUCTED ON MARCH 9, 1990\*

0-4-3-4		Ground	Water Monitor	ing Wells	
Contaminant	MW-1A	MW-2A	AC-WM	MW-S	MW-N
Lead	0.005	<0.005	0.006	<0.005	<0.005
Sulfate	468	960	298	568	476

<sup>\*</sup> All concentrations reported in parts per million (ppm)(Ref. 11).

## Ground Water Pathway Criteria List Primary Targets

N

Has any nearby drinking water well been closed? (y/n/u)

N

Has any nearby drinking water well user reported foul-testing or foul-smelling water? (y/n/u)

Is any drinking water well nearby? (y/n/u)

N

Does any nearby well have a large drawdown/high production rate? (y/n/u) N

Is any drinking water well located between the site and other wells that are suspected to be exposed to a hazardous substance? (y/n/u) N

Does analytical or circumstantial evidence suggest contamination at a drinking water well? (y/n/u) N

Does any drinking water well warrant sampling? (y/n/u)

N

N

Other criteria? (y/n)

PRIMARY TARGET(S) IDENTIFIED? (y/n)

N

Summarize the rationale for Primary Targets:

Farmers Branch, like most suburbs of Dallas, purchases its water directly from the City of Dallas. The City of Dallas receives its water from man-made reservoirs and lakes. Dallas does not withdraw water directly from aquifers in the area or directly from rivers (Ref. 1, pp. 21, 22; Ref. 12)

Ref: 1, 12

## Page: 4

### GROUND WATER PATHWAY SCORESHEETS

Pathway Characteristics				Ref.			
Do you suspect a release? (y/n) Yes							
Is the site located in karst terrain? (y/n) No							
Depth to aquifer (feet): 5							
Distance to the nearest drinking water well (feet): 25000							
LIKELIHOOD OF RELEASE	Suspected Release	No Suspected Release	Refe	rences			
1. SUSPECTED RELEASE	550						
		<del></del>	<b>(1</b> - 00000000000000000000000000000000000				
2. NO SUSPECTED RELEASE		o					

## Targets

TARGETS	Suspected Release	No Suspected Release	References
3. PRIMARY TARGET POPULATION 0 person(s)	0		
4. SECONDARY TARGET POPULATION Are any wells part of a blended system? (y/n) N	0	0	
5. NEAREST WELL	o	0	
6. WELLHEAD PROTECTION AREA None within 4 Miles	0	0	
7. RESOURCES	5	0	
T =	5	0	

WΔ	ਵਧਾਣ	CHA	Dλ	ᡣᡎᢑᢧ	TSTT	20
m A	OIL	LIDA		C. I P.R		

WC = 32 0
-----------

GROUND WATER PATHWAY SCORE:

### Page: 5

## Ground Water Target Populations

Primary Target Population Drinking Water Well ID	Dist. (miles)	Population Served	Reference	Value	
None					
*** Note: Maximum of 5 Wells Are Printed *** Total					

Secondary Target Population Distance Categories	Population Served	Reference	Value
0 to 1/4 mile	0	1	0
Greater than 1/4 to 1/2 mile	0	1	0
Greater than 1/2 to 1 mile	0	1	0
Greater than 1 to 2 miles	0	1	0
Greater than 2 to 3 miles	0	1	0
Greater than 3 to 4 miles	0	1	0
		Total	0

Apportionment Documentation for a Blended System

Farmers Branch purchases its water directly from the City of Dallas. The City of Dallas receives its water from man-made reservoirs and lakes. Dallas does not withdraw water directly from aquifers in the area or from rivers (Ref. 1, pp. 21, 22; Ref. 12).

Ref: 1, 12

## Surface Water Pathway Criteria List Suspected Release Is surface water nearby? (y/n/u) Y Is waste quantity particularly large? (y/n/u) Y Is the drainage area large? (y/n/u)Y Is rainfall heavy? (y/n/u) Y Is the infiltration rate low? (y/n/u)N Are sources poorly contained or prone to runoff or flooding? (y/n/u) Y Is a runoff route well defined(e.g.ditch/channel to surf.water)? (y/n/u) N Is vegetation stressed along the probable runoff path? (y/n/u) N Are sediments or water unnaturally discolored? (y/n/u) N Is wildlife unnaturally absent? (y/n/u)N Has deposition of waste into surface water been observed? (y/n/u) N Is ground water discharge to surface water likely? (y/n/u) U Does analytical/circumstantial evidence suggest S.W. contam? (y/n/u) N Other criteria? (y/n) N SUSPECTED RELEASE? (y/n) N

#### Summarize the rationale for Suspected Release:

GNB manufactures automotive batteries. The sources consisted of 4 settling ponds and 1 dry waste pit which were operated from 1972 to 1985 (Ref. 1, p. 18). The sources have since been excavated and backfilled (Ref. 20). Rawhide Creek is located approximately 3,000 feet south-southeast of the site and is considered the PPE. There is no defined drainage channel leading to the PPE. Surface runoff is believed to migrate to the PPE by overland flow.

During the time of operation of the impoundments, no documented case of an overflow or a surface water release was recorded (Ref. 1, p. 41).

Ref: 1, 20

Surface Water Pathway Criteria List Primary Targets	
Is any target nearby? (y/n/u) If yes:  N Drinking water intake Y Fishery U Sensitive environment	Y
Has any intake, fishery, or recreational area been closed? (y/n/u)	N
Does analytical or circumstantial evidence suggest surface water contamination at or downstream of a target? (y/n/u)	N
Does any target warrant sampling? (y/n/u) If yes: N Drinking water intake N Fishery N Sensitive environment	N
Other criteria? (y/n) N	
PRIMARY INTAKE(S) IDENTIFIED? (y/n)	N
Summarize the rationale for Primary Intakes:	
The City of Farmers Branch purchases its water directly from the City of Dallas. The City of Dallas receives its water from man-made reservoirs and lakes (Ref. 1, pp. 21, 22). No surface water intakes were identified within the 15-mile in-water segment.	
Ref: 1 continued	

Page:

continued -----

Other criteria? (y/n)

N

PRIMARY FISHERY(IES) IDENTIFIED? (y/n)

N

Summarize the rationale for Primary Fisheries:

The PPE is Rawhide Creek which is 3,000 feet south-southeast of the site. It is not known if the creek is a fishery. Rawhide Creek flows approximately 1.57 miles before it enters the Elm Fork of the Trinity River (Ref. 17). The Elm Fork of the Trinity River is a designated fishery (Ref. 14). The Elm Fork of the Trinity River flows approximately 11.24 miles before it enters the Trinity River (Ref. 17). The Trinity River is a fishery (Ref. 14).

Ref: 14, 17

Other criteria? (y/n)

N

PRIMARY SENSITIVE ENVIRONMENT(S) IDENTIFIED? (y/n)

N

Summarize the rationale for Primary Sensitive Environments:

No sensitive environments were identified along the 15-mile in-water segment.

Page: 10

SURFACE WATER PATHWAY SCORESHEETS

Pathway Characteristics					Ref.
Do you suspect a release? (y,	'n)			No	
Distance to surface water (fe	eet):			3000	17
Flood frequency (years):				1-10	1
What is the downstream distant a. the nearest drive b. the nearest fisher. the nearest sense.	nking wat nery?	er intal		N.A. 0.6 N.A.	17 17 17
LIKELIHOOD OF RELEASE		pected lease	No Suspected Release	15	rences
1. SUSPECTED RELEASE		0			
2. NO SUSPECTED RELEASE			500		
LR =	=	0	500		

Page: 11

0

## Drinking Water Threat Targets

TARGETS	Suspected Release	No Suspected Release	References
3. Determine the water body type, flow (if applicable), and number of people served by each drinking water intake.			
4. PRIMARY TARGET POPULATION 0 person(s)	0		
5. SECONDARY TARGET POPULATION Are any intakes part of a blended system? (y/n): N	0	0	
6. NEAREST INTAKE	o	o	
7. RESOURCES	0	5	
Т =	0	5	

## Drinking Water Threat Target Populations

Intake Name	Primary (y/n)	Water Body Type/Flow	Population Served	Ref.	Value
None					

Total Primary Target Population Value Total Secondary Target Population Value
\*\*\* Note: Maximum of 6 Intakes Are Printed \*\*\*

Apportionment Documentation for a Blended System

The City of Farmers Branch purchases its water directly from the City of Dallas. The City of Dallas receives its water from man-made reservoirs and lakes (Ref. 1, pp. 21, 22).

Ref: 1

Page: 13

0

## Human Food Chain Threat Targets

TARGETS	Suspected Release	No Suspected Release	References
8. Determine the water body type and flow for each fishery within the target limit.			
9. PRIMARY FISHERIES	0		
10. SECONDARY FISHERIES	0	12	
Т =	0	12	

## Human Food Chain Threat Targets

Fishery Name	Primary (y/n)	Water Body Type/Flow	Ref.	Value
1 Elm Fork	N	>100-1000 cfs	15	12
2 Trinity	N	>1000-10000 cfs	15	12
	Tota]	Primary Fisheries Val	10	

Total Primary Fisheries Value
Total Secondary Fisheries Value

\*\*\* Note: Maximum of 6 Fisheries Are Printed \*\*\*

## Page: 14

## **Environmental Threat Targets**

TARGETS	Suspected Release	No Suspected Release	References
11. Determine the water body type and flow (if applicable) for each sensitive environment.			
12. PRIMARY SENSITIVE ENVIRONMENTS	0		
13. SECONDARY SENSITIVE ENVIRONS.	0	O	
Т =	0	0	

## **Environmental Threat Targets**

Sensitive Environment Name	Primary (y/n)	Water Body Type/Flow	Ref.	Value
None				
*				
Total Primary Sensitive Environments Value Total Secondary Sensitive Environments Value			0	

\*\*\* Note: Maximum of 6 Sensitive Environments Are Printed \*\*\*

Surface Water Pathway Threat Scores

Threat	Likelihood of Release(LR) Score	Targets(T) Score	Pathway Waste Characteristics (WC) Score	Threat Score LR x T x WC / 82,500
Drinking Water	500	5	32	1
Human Food Chain	500	12	32	2
Environmental	500	0	32	0

Page: 15

Soil Exposure Pathway Criteria List

N

N

# Resident Population Is any residence, school, or daycare facility on or within 200 feet of an area of suspected contamination? (y/n/u) N Is any residence, school, or daycare facility located on adjacent land previously owned or leased by the site owner/operator? (y/n/u) N Is there a migration route that might spread hazardous substances near residences, schools, or daycare facilities? (y/n/u) N Have onsite or adjacent residents or students reported adverse health effects, exclusive of apparent drinking water or air contamination problems? (y/n/u)

Does any neighboring property warrant sampling? (y/n/u)

N

Other criteria? (y/n)

RESIDENT POPULATION IDENTIFIED? (y/n)

Summarize the rationale for Resident Population:

No residences, schools, or day-care facilities are located on or within 200 feet of the facility (Ref. 17). The area surrounding the acility is considered industrial (Ref. 4, p. 1).

Ref: 4, 17

## Page: 17

#### SOIL EXPOSURE PATHWAY SCORESHEETS

ay Characteristics		Ref
Do any people live on or within 200 ft of areas of suspected contamination? (y/n)	No	17
Do any people attend school or daycare on or within 200 ft of areas of suspected contamination? (y/n)	No	17
Is the facility active? (y/n):	Yes	20

LIKELIHOOD OF EXPOSURE		Suspected Contamination	References
1. SUSPECTED CONTAMINATION	LE =	550	

## Targets

2. RESIDENT POPULATION 0 resident(s) 0 school/daycare student(s)	0	17 17
3. RESIDENT INDIVIDUAL	0	
4. WORKERS 101 - 1000	10	2
5. TERRES. SENSITIVE ENVIRONMENTS	0	
6. RESOURCES	5	
T =	15	

WASTE CHARACTERISTI	.CS
---------------------	-----

WC	=	3	2	

RESIDENT POPULATION THREAT SCORE:

3

NEARBY POPULATION THREAT SCORE:

1

Population Within 1 Mile: 1 - 10,000

SOIL EXPOSURE PATHWAY SCORE:

4

Page: 18

## Soil Exposure Pathway Terrestrial Sensitive Environments

Terrestrial Sensitive Environment Name	Reference	Value
None		
Total Terrestrial Sensitive Environments Value		

\*\*\* Note : Maximum of 7 Sensitive Environments Are Printed \*\*\*

#### Air Pathway Criteria List Suspected Release

Are odors currently reported? (y/n/u)

N

Page: 19

Has release of a hazardous substance to the air

been directly observed? (y/n/u)

N

Are there reports of adverse health effects (e.g., headaches, nausea, dizziness) potentially resulting from migration of hazardous substances through the air? (y/n/u)

N

N

Does analytical/circumstantial evidence suggest release to air? (y/n/u)

Other criteria? (y/n)

N

SUSPECTED RELEASE? (y/n)

N

Summarize the rationale for Suspected Release:

The ponds contained liquids except when sludges were being transferred to the dry waste pit; therefore, a release from the ponds is remote due to the non-volatile nature of the lead contaminated sludges being processed (Ref. 1, p. 42). The dry waste it was used to contain chemically fixed waste removed from the ponds. Exposure of the dry wastes to the weathering process could have caused the waste to be broken into fine particulates which could have been carried by the winds of the area. There is no documented release from the surface impoundments to the air. The impoundments have been excavated and backfilled and are currently closed.

Ref: 1

Page: 20

## AIR PATHWAY SCORESHEETS

			Ref.
)	No	)	
Distance to the nearest individual (feet): 100			2
Suspected Release	No Suspected Release	Refe	rences
0		100000000000000000000000000000000000000	
	500		
0	500		
	Suspected Release	Suspected Release  0 500	Suspected Release Refer

## Targets

TARGETS	Suspected Release	No Suspected Release	References
3. PRIMARY TARGET POPULATION 0 person(s)	0		
4. SECONDARY TARGET POPULATION	O	63	
5. NEAREST INDIVIDUAL	0	20	
6. PRIMARY SENSITIVE ENVIRONS.	0		
7. SECONDARY SENSITIVE ENVIRONS.	0	0	
8. RESOURCES	0	5	
T =	0	88	

WASTE CHARACTERISTICS

WC =	0	32	

AIR PATHWAY SCORE: 17

Page: 21

Air Pathway Secondary Target Populations

Distance Categories	Population	References	Value
Onsite	340	2	52
Greater than 0 to 1/4 mile	5	17	1
Greater than 1/4 to 1/2 mile	33	17	1
Greater than 1/2 to 1 mile	95	17	0
Greater than 1 to 2 miles	9404	18	3
Greater than 2 to 3 miles	29788	18	4
Greater than 3 to 4 miles	28342	18	2
Total Secondary Population Value			63

Page: 22

## Air Pathway Primary Sensitive Environments

Value	Reference	Sensitive Environment Name
		None

Total Primary Sensitive Environments Value
\*\*\* Note: Maximum of 7 Sensitive Environments Are Printed\*\*\* Air Pathway Secondary Sensitive Environments

Sensitive Environment Name	Distance	Reference	Value
None			
	_		

Total Secondary Sensitive Environments Value

SITE SCORE CALCULATION	SCORE
GROUND WATER PATHWAY SCORE:	1
SURFACE WATER PATHWAY SCORE:	3
SOIL EXPOSURE PATHWAY SCORE:	4
AIR PATHWAY SCORE:	17
SITE SCORE:	9

## SUMMARY

OPERALL			
1.	Is there a high possibility of a threat to any nearby drinking wate well(s) by migration of a hazardous substance in ground water?	er No	
	If yes, identify the well(s).		
	If yes, how many people are served by the threatened well(s)? 0		
2.	Is there a high possibility of a threat to any of the following by hazardous substance migration in surface water?		
	A. Drinking water intake	No No	
	<ul><li>B. Fishery</li><li>C. Sensitive environment (wetland, critical habitat, others)</li></ul>	No	
	If yes, identity the target(s).		
3.	Is there a high possibility of an area of surficial contamination within 200 feet of any residence, school, or daycare facility?	No	
	If yes, identify the properties and estimate the associated populat	cion(s)	
4.	Are there public health concerns at this site that are not addressed by PA scoring considerations?	No	
	If yes, explain:		

## PA-SCORE DOCUMENTATION LOG SHEET

SITE: GNB INCORPORATED

**IDENTIFICATION NUMBER:** TXD007331879

CITY: FARMERS BRANCH

STATE: TEXAS

	DESCRIPTION OF THE REFERENCE	
REFERENCE NUMBER		
1	PR/VSI Report for GNB Incorporated. Prepared by A.T. Kearney, Inc. and Mittelhauser Corp. for EPA Region 6, August 1987.	
2	Record of Communication. Additional Information Concerning GNB, Inc. From: B. Kendrick, Geologist, ICF Technology, Inc. To: Bill Backus, Environmental Engineer, GNB, Inc. February 4, 1993. TXD007331879.	
3	Memorandum. Transmittal of RCRA Facility Assessment Evaluation. From: Bill Luthans, Technocal Section (6H-CT), EPA. To: William Honker, Chief, Permits Section (6H-CP), EPA. October 14, 1988. TXD007331879.	
4	Industrial Solid Waste Disposal Compliance Monitoring Inspection. Prepared by Jinny G. Menard, Inspector, Texas Department of Water Resources. April 20, 1984.	
5	Subsurface Investigation: Underground Effluent Pipeline. Prepared by Professional Service Industries, Inc. for GNB Battery, Inc. March 1984.	
6	Letter. From: E.C. Milton, Manager, Facilities Engineering, GNB, Inc. To: Mike Dick, Hazardous Wate Division, Texas Department of Water Resources. October 28, 1983.	
7	Nordstrom, Phillip L., Geologist, Texas Department of Water Resources. "Occurrance, Availability, and Chemical Quality of Ground Water in the Cretaceous Aquifers of North-Central Texas." Volume 1, Report 269. April 1982.	
8	Letter. HRS Net Precipitation Values. From: Andrew M. Platt, Group Leader, Hazardous Waste Systems. To: Lucy Sibold, U.S. Environmental Protection Agency. May 26, 1988.	

9 Groundwater Quality Assessment Plan. Prepared by NFS/National Soil Services, Inc. for GNB, Inc. December 14, 1983. 10 U.S. Environmental Protection Agency. Current and Proposed National Primary and Secondary Drinking Water Regulations and Health Advisories for Other Contaminants. January 18, 1991. 11 Texas Water Commission. Quarterly Ground Water Monitoring Report for Hazardous Waste Facilities. April 26, 1990. Record of Communication. Water Supply for the City of Farmers 12 Branch. From: B. Kendrick, Geologist, ICF Technology, Inc. To: Richard Cannon, City of Farmers Branch. February 2, 1993. TXD007331879. 13 Letter. Phase II Testing Project: Two-Year, 24-Hour Rainfall Map; GEMS Data. From: Lauren Ray, HQST, Ecology and Environment, Inc. To: Phase II Project Managers. August 5, 1988. Enclosure: 1961 Rainfall Frequency Atlas of the United States. U.S. Weather Bureau Technical Paper No. 40. 14 Texas Water Commission. Permanent Rule Changes for Chapter 307 -Texas Surface Water Quality Standards. July 10, 1991. 15 U.S. Department of the Interior. Water Resources Data - Texas Water Year 1989. Volume 1, U.S. Geological Survey Water-Data Report TX-89-1. 1989. 16 U.S. Department of Commerce, Bureau of the Census. Estimates of Households, for Counties: July 1, 1985. Issued March 8, 1988. Washington, D.C. 1985. 17 Memorandum. Measurements and Calculations for GNB. From: S. Bret Kendrick, Task Manager, ICF Technology, Inc. To: File. February 4, 1993. TXD007331879. U.S. Environmental Protection Agency, Geographical Exposure 18 Modeling System (GEMS) database, compiled from U.S. Census Bureau 1990 data, accessed February 2, 1993. 19 Record of Communication. Current Regulatory Status of GNB. From: B. Kendrick, Geologist, ICF Technology, Inc. To: Agetha Benjeman, RCRA Enforcement, EPA. February 4, 1993. TXD007331879. 20 Memorandum. On-Site Reconnaissance Inspection of GNB, Inc. From: S. Bret Kendrick, Task Manager, ICF Technology, Inc. To: File. February 4, 1993. TXD007331879. 21 Letter. From: Fred B. Woods, Chief, Administrative Branch, EPA. To:

Everett Milton, GNB, Inc. January 8, 1992.

## PA-SCORE REFERENCE 1

## PR/VSI REPORT

FOR

GNB INCORPORATED FARMERS BRANCH, TEXAS



U.S. ENVIRONMENTAL PROTECTION AGENCY REGION VI ALLIED BANK TOWER, 12TH FLOOR 1445 ROSS AVENUE DALLAS, TEXAS 75202-2733

UNDER

CONTRACT NO. 68-01-7374 WORK ASSIGNMENT NO. R26-01-19

### PREPARED BY:

A.T. KEARNEY, INCORPORATED

1 LAGOON DRIVE
REDWOOD CITY, CALIFORNIA 94605

and

MITTELHAUSER CORPORATION 1240 IROQUOIS DRIVE, SUITE 102 NAPERVILLE, ILLINOIS 60566

AUGUST 1987

#### Table of Contents

			Page
	EXEC	UTIVE SUMMARY	v
1.0	INTR	ODUCTION	1
	1.1	Purpose and Scope of RFA program	1
2.0	FACI	LITY DESCRIPTION	4
	2.1	Location	. 4
	2.3	Identification of Solid Waste Management Units	10
	2.4	Wastes Generated at the Facility	10
3.0	ENVI	RONMENTAL SETTING	14
	3.1 3.2	Meteorology and Air Quality	
	3.3	Geology and Soils	15
	3.4	Ground Water	
	3.5	Receptor Information	
4.0	RELE	ASE PATHWAYS	18
	4.1	Ground Water Pathway	
	4.2	Soil Pathway	
	4.4	Air Pathway	
	4.5	Subsurface Gas	19
5.0	DESC	RIPTIONS OF SOLID WASTE MANAGEMENT UNITS	20
	5.1	SWMU 1: Wastewater Pipe	20
		5.1.1 Information Summary	20
	5.2		
	J.2		
		5.2.1 Information Summary	23
	5.3	SWMU 3: First Neutralization Pit/Tank	25
		5.3.1 Information Summary	25

5.4	SWMU 4:	Second Neutralization Pit/Tank	28
	5.4.1 5.4.2	Information Summary	28 29
5.5	SWMU 5:	Pond 1	30
	5.5.1 5.5.2	Information Summary	30 35
5.6	SWMU 6:	Pond 4	36
	5.6.1 5.6.2	Information Summary	36 38
5.7	SWMU 7:	Pond 2	39
	5.7.1 5.7.2	Information Summary	39 41
5.8	SWMU 8:	Pond 3	42
	5.8.1 5.8.2	Information Summary	42 44
5.9	SWMU 9:	Dry Waste Pit	45
	5.9.1 5.9.2	Information Summary	45 46
5.10	SWMU 10:	Storage Trailer Area	47
	5.10.1 5.10.2	Information Summary	47 48
5.11	SWMU 11:	Dumpster Area 1	49
	5.11.1 5.11.2	Information Summary	49 49
5.12	SWMU 12:	Dumpster Area 2	50
	5.12.1 5.12.2	Information Summary	50 50
5.13	SWMU 13:	Dumpster Area 3	51
	5.13.1 5.13.2	Information Summary	51 51

	5.14	SWMU 14: I	Baghouse 1 (casting)	52
		5.14.1 5.14.2	Information Summary	52 52
	5.15	SWMU 15: 1	Baghouse 2 (vacuum)	53
		5.15.1 5.15.2	Information Summary	53 53
	5.16	SWMU 16:	Baghouse 3 (assembly)	54
		5.16.1 5.16.2	Information Summary	54 54
	5.17	SWMU 17:	Indoor WWT	55
		5.17.1 5.17.2	Information Summary	55 <b>5</b> 5
6.0	AREA	S OF CONCE	RN	56
	6.1	Low Area	(east)	56
	6.2	Low Area	(west)	56
	6.3	Drainage	Ditch (Off Site)	56
	6.4	Ponds A-D	•••••••••••	57
	6.5	Drainage	Ditch (On Site)	57
	6.6	Acid Spil	l Area	57
	6.7	Hose Brea	k Area	58
7.0		LUSIONS AN orcement S	D RECOMMENDATIONSensitive)	59
8.0	REFE	RENCES	••••••	66
APPE	XIDN	A VSI PHO	TOGRAPHIC LOG	
APPE	XIDN	B VSI LOG	i e e e e e e e e e e e e e e e e e e e	

#### List of Tables

Table 1: Solid Waste Management Units (SWMUs) and Areas of Concern (AOCs)	11
Table 2: Waste Materials Description	13
Table 3: Solid Waste Managgement Unit (SWMU) Summary and Release Information	21
List of Figures	
Figure 1: Facility Location	5
Figure 2: Process Flow Diagram (1972-1985)	6
Figure 3: Process Flow Diagram (1985-1986)	7
Figure 4: Process Flow Diagram (1986-present)	8
Figure 5: Facility Map	31
Figure 6: Detail of Four Ponds	32
Figure 7: Cross Section of a Typical Pond	33
List of Photographs	
Photograph A: Neutralization Pits	26

#### EXECUTIVE SUMMARY

This PR/VSI Report addresses the GNB Incorporated facility located in Farmers Branch, Texas. A total of seventeen solid waste management units (SWMUs) and seven areas of concern (AOCs) have been identified.

The facility was originally utilized by Morton Foods Company in the manufacturing and packaging of pickled food products. In 1971 the facility was purchased by Gould, Incorporated, for the purpose of manufacturing batteries. GNB, Incorporated purchased the facility from Gould, Incorporated, in March of 1984.

The main wastes generated by the facility are those derived from the treatment of acidic wastewaters that contain lead. Additional lead bearing wastes are collected in baghouses, or from the discarding of lead containing materials, mainly batteries. The facility generates only a small quantity of organics, from the cleaning of batteries and laboratory operations.

The facility has employed three methods of treating the acidic wastewaters over the years. Prior to 1985, the wastewaters were neutralized in two concrete neutralization pits. The neutralization results in precipitation of metals, including lead. The neutralized wastes were allowed to flow to a series of four unlined ponds (surface impoundments). The solids were allowed to settle, and the water was pumped to the sanitary sewer. The settled solids were either chemically stabilized using the Chemfix process, or sent directly off site for disposal. The Chemfix solids were allowed to remain in an on-site disposal pit area.

In 1985, the facility significantly changed their treatment system. Two 5,000-gallon polypropylene tanks were installed to replace the neutralization pits. The old neutralization pits served as secondary containment for the tanks. The facility also installed a filter press to dewater the sludges containing the the precipitated metals, and took the ponds out of service. A Closure Plan covering the ponds and the dry waste disposal area was submitted to the State. The facility also removed the waste materials from the ponds and the dry waste area, and is currently awaiting official approval of the Closure Plan by the Texas Water Commission.

The facility made minor changes to the wastewater treatment operation in 1986, including sending the filter cake to a company smelter in Frisco, Texas. Operations prior to 1985 resulted in a high probability of releases to soil and groundwater because of the unlined impoundments. The current wastewater operations result, with one exception, in a low probability of continuing releases to the environment. The one exception is the pipe which carries the wastewaters from the building to the neutralization tanks. The design is poor (bell and spigot), the materials of construction are poor (clay tile), and a crack was discovered in 1984. Therefore an RFI is recommended for this unit. Sampling of other areas is also recommended to insure that past management practices have not resulted in residual contamination.

Good management practices, which were observed during the VSI, should result in a low probability of continuing releases from the baghouses, rejected lead containing components, or solvent impregnated rags.

Significantly elevated levels of sulfates (up to 1,835 mg/l) have been found in RCRA ground water monitoring wells. The critical statistic for specific conductance has also been tripped. However, no lead has been detected (detection limit of .05 mg/l) during the last 4 quarterly samplings. There is a low probability of continuing releases to ground water, for the reasons stated above. The existing ground water contamination problem can be addressed as part of the closure approval process.

#### 1.0 INTRODUCTION

This section of the Preliminary Review (PR)/Visual Site Inspection (VSI) report covers the purpose and scope of the RCRA Facility Assessment (RFA) program. The contents of the other sections of this report also are described.

#### 1.1 Purpose and Scope of the RFA Program

The 1984 Hazardous and Solid Waste Amendments (HSWA) provide new authority to U.S. Environmental Protection Agency (EPA) to require comprehensive corrective actions on solid waste management units (SWMUs) and other areas of concern (AOC) at interim status hazardous waste management facilities, particularly those applying for RCRA permits. These corrective actions are intended to address unregulated releases of hazardous constituents to air, surface water, soil, and ground water, as well as the generation of subsurface gas.

One of the major segments of EPA's corrective action program consists of RCRA Facility Assessments (RFAs) to identify releases or potential releases requiring further investigation. According to EPA's RCRA Facility Assessment Guidance Document, the four purposes of an RFA are to:

- 1. Identify and gather information on releases at RCRA regulated facilities;
- 2. Evaluate SWMUs and areas of concern for releases to all media and regulated units for releases other than ground water;
- 3. Make preliminary determinations regarding releases of concern and the need for further actions and interim measures at the facility; and
- 4. Screen from further investigation those SWMUs which do not pose a threat to human health and the environment.

The three basic steps of an RFA consist of a preliminary review (PR) of available information, a visual site investigation (VSI) to obtain additional information on releases, and a sampling visit (SV) to fill the data gaps by obtaining field and analytical data.

#### 1.2 Contents of this Report

This report presents the results of the PR and VSI of the GNB

Batteries, Inc. (GNB) facility located in Farmers Branch, Texas. Information regarding hazardous and solid waste management units identified during the Preliminary Review (PR) was obtained from the following principal sources:

- o The facility's Part A Hazardous Waste Permit Applications, including revisions;
- o Texas Department of Water Resources. Various interoffice memorandums:
- o Various letters from EPA Region VI to the GNB facility;
- o Professional Service Industries, Inc. Ground water Elevations Report for GNB Batteries;
- o Groundwater Monitoring Reports for 1986 and 1987;
- o A telephone conversation with David Maiefski of EPA Region VI on July 7, 1987;
- o A telephone conversation with Charles Mauk of the Texas Water Commission on July 7, 1987;
- o A telephone conversation with Bill Backus, maintenance supervisor of GNB in Farmers Branch, on July 9, 1987;
- o A telephone conversation with Everett Milton of GNB on August 25, 1987;
- o The facility's Closure (and Post-Closure) Plan for surface impoundments, originally dated January 11, 1984, last modified March 14, 1986;
- o A USGS map of the Carrollton Quadrangle, Texas. 7.5 minute series (topographic); and
- o The <u>County and City Data Book 1983</u>, U.S. Department of Commerce, Bureau of the Census.

A visual site inspection (VSI) was performed on July 17, 1987 to verify the information obtained during the preliminary review and to identify any other SWMUs or areas of concern. The GNB representatives who were present included Mr. Everett Milton, Manager Environmental Engineering; Mr. Bill Backus, Maintenance Supervisor; Mr. Robert Wilson, GNB's attorney; and Mr. R. Clark George, GNB's consultant. The A.T. Kearney subcontractor representative was Mittelhauser Corporation.

Section 2.0 of this report contains a description of the GNB facility, including its historical and current operations. Individual SWMUs also are identified in Section 2.0, along with a summary description of the wastes managed by the facility. Section 3.0 provides an overview of the environmental setting at the facility, comprising meteorology and air quality, floodplain and surface water, geology and soils, ground water, and receptor information. In Section 4.0, a broad assessment of release pathways is made, covering the potential for releases to soil, ground water, surface water, and air. Section 5.0 contains detailed discussions of each SWMU, while Section 6.0 covers other areas of concern (i.e., releases from production areas, spills, and evidence of contamination of unknown origin). Section 7.0 provides conclusions and recommendations (enforcement sensitive). Section 8.0 provides a list of references. The VSI field log and VSI photograph log are presented as appendices to the report.

#### 2.0 FACILITY AND PROCESS DESCRIPTION

This section of the PR/VSI report covers the location of the GNB Batteries, Inc. (GNB) facility, historical and current operations, brief descriptions of the solid waste management units (SWMUs) that were identified, and a brief description of the wastes managed at the facility.

#### 2.1 Location [2, 23, 24]

GNB operates a facility located in the City of Farmers Branch, Dallas County, Texas, approximately 1.25 miles west of the intersection of Valley View Lane and Interstate 35E [2, 24]. The facility is at 96° 54' 58" longitude and 32° 55' 12" latitude [24]. The location of the facility is shown in Figure 1. Downtown Dallas is located approximately 12 miles southeast of the facility [24].


The areas to the north and south of the facility have been extensively mined for sand and gravel [2]. The facility is located within the Farmers Branch corporate limits, and is less than 2 miles west of the central business district along Valley View Lane. Farmers Branch has a population of approximately 25,000 [23].

#### 2.2 Historical and Current Operations [1, 2, 17, 22, 29, 30]

The facility was originally utilized by Morton Foods Company in the manufacturing and packaging of pickled food products [17, 29]. In 1971, the facility was purchased by Gould, Incorporated (Inc.) for the purpose of manufacturing batteries [29]. GNB Batteries, Inc. purchased the battery operation from Gould, Inc. in March of 1984 [29].

The basic manufacturing processes are described in 40 CFR 461. The specific processes employed by GNB are considered proprietary, but the above reference adequately describes the sources of the wastes [30]. Wastewaters are generated by spills of acids, or from cleaning of the outside of batteries. The wastewaters contain lead since the spilled materials have come into contact with the lead cells of the battery. The baghouses collect lead containing wastes to provide safety for the workers.

As discussed above, the battery manufacturing process generates wastewaters that are acidic and contain lead. The facility has changed wastewater treatment practices twice since operations began [1, 2, 29]. A process flow diagram from 1971 (beginning of operation) until May 1985 is shown in Figure 2 [1]. The facility then changed operations, as shown in Figure 3 [2]. These operations ran from May 1985 until March 1986. The facility then switched to their current process which is shown in Figure 4 [29].



## GNB Batteries, Inc.




Figure 2: Process Flow Diagram (1972-1985)

Mittelhauser Corporation August 1987

# GNB Batteries, Inc.




Figure 3: Process Flow Diagram (1985-86)

Mittelhauser Corporation August 1987

## GNB Batteries, Inc.




Figure 4: Process Flow Diagram (1986-)

Mittelhauser Corporation August 1987 Prior to 1985, acidic wastewater containing EP toxic levels of lead from the battery manufacturing process, floor wash drains, and truck wash sump (SWMU 2) was fed to the first of two concrete pits (SWMUs 3 and 4) in which treatment occurred [1, 2]. Lime and calcium carbonate were added to raise the pH to a suitable level for optimum precipitation of lead hydroxide [2]. The lime was added by means of flexible hoses. The discharge from the first pit went to a second pit where additional lime was added and the pH was adjusted. The discharge from the second pit fed one of two lagoons (SWMUs 5 and 7). Each lagoon was composed of two ponds (SWMUs 5 and 6, SWMUs 7 and 8). Solids were allowed to settle in the ponds and the effluent water was sent to the sanitary sewer.

A pH probe in the second pit prevented pumping into the pond system if the pH was less than 5.0. The settled solids were stabilized using the Chemfix process and left on site in a solids storage area (SWMU 9). The stabilized solids were sent off site for disposal until 1982. Solids from the ponds, which were not stabilized, were sent to the Rollins facility in Deer Park, Texas for disposal in 1984.

In 1985 (approximately May 22nd), the process was changed to eliminate the use of the neutralization pits and of the ponds. 5,000-gallon polypropylene tank was installed for the primary neutralization step inside the prior first neutralization pit. Therefore, the pit now serves as a secondary containment vessel. However, according to the facility [30], leaks in the tanks have not occurred and, therefore, it has not been used for secondary containment. A second polypropylene tank was also installed for supplemental lime addition. The amount of lime added was determined by pH measurements. This polypropylene tank was installed inside the former secondary neutralization pit. tank has not leaked [30]. The effluent from the second polypropylene tank was sent to a filter press (or to one of two fiberglass storage tanks before the filter press). The solids generated in the filter press were stored in a hazardous waste dumpster before being sent to a Chemical Waste Management facility for disposal as a hazardous waste. The effluent water was monitored and sent to the sanitary sewer.

In March of 1986, the process was again changed [29]. The wastewater is still pumped to the polypropylene tanks, but the limetreated effluent from these tanks is pumped back into the facility building (SWMU 17). A filter press is still used to separate the water from the solids, but now the treated effluent is recirculated through the process and the solids are sent to the company smelter in Frisco, Texas for reprocessing. The water which is not needed in the process is sent to the sanitary sewer system.

## 2.3 <u>Identification of Solid Waste Management Units (SWMUs)</u> [1, 16, 22, 29]

As a result of the PR and VSI, a total of seventeen Solid Waste Management Units (SWMUs) were identified. These units are listed in Table 1. This Table also describes the wastes managed, the operational dates, whether the units are RCRA regulated, and whether there is an existing ground water monitoring program for the unit.

Units 1 through 9 are directly related to treatment of wastewaters from the battery manufacturing process. The Wastewater Pipe (SWMU 1) and the Truck Wash Sump (SWMU 2) fed the two sequential Neutralization Pits/Tanks (SWMU 3 and 4). The effluent from the Neutralization Pits fed the Pond system (SWMU 5 through 8), as shown in Figure 2. Stabilized solids from the Ponds were placed in the Dry Waste Pit (SWMU 9). As previously discussed, SWMUS 3 through 9 have been taken out of service. A Closure Plan has been submitted [22]. The State prepared a letter approving the Plan, but the facility claims they have not received this letter [16].

The Storage Trailer Area has three trailers. One trailer contains hazardous wastes. There are also three dumpsters on the facility (SWMU 11 through 13), and one of these dumpsters (SWMU 11) contains hazardous wastes. In addition, there are three baghouses (SWMU 14 through 16), all of which handle hazardous wastes. The final SWMU, number 17, consists of the two 5,000-gallon fiberglass storage tanks and the filter, which are currently inside the building and are part of the wastewater treatment system (see Figure 4).

Table 1 also identifies 7 areas of concern, which are discussed further in Section 6.

#### 2.4 Wastes Generated at the Facility [3]

On April 9, 1987, GNB reported to the Texas Water Commission that the following wastes were generated by the facility [3]:

Scrap and Whole Batteries
Scrap Products (not otherwise specified) with Lead
Lead Oxide and/or Dust Collected Solids
(Rejected) Plastic Battery Cases and Covers
(Rejected) Rubber Battery Cases and Covers
Plastic Battery Cases and Covers (Contaminated)
Rubber Battery Cases and Covers (Contaminated)
Sludge with Lead
Epoxy

# TABLE 1 GNB BATTERIES, INCORPORATED SOLID WASTE MANAGEMENT UNITS (SWMUS) AND AREAS OF CONCERN (AOCS) FARMERS BRANCH, TEXAS

SWMU NO.	UNIT NAME	WASTES MANAGED	OPERATIONAL DATES	RCRA <u>REGULATED</u>	+ <u>GW</u>			
1	Wastewater Pipe	D008	1972-present	No	No			
2	Truck Wash Sump	D008	1978-present	No	No			
3	First Neutralization Pit/Tank	D008	1972-present	Yes	No			
. 4	Second Neutralization Pit /Tank	D008	1972-present	Yes	No			
5	Pond 1	D008	1972-1985	Yes	Yes			
6	Pond 4	D008	1972-1985	Yes	Yes			
7	Pond 2	D008	1972-1985	Yes	Yes			
8	Pond 3	D008	1972-1985	Yes	Yes			
9	Dry Waste Pit	D008	1972-1985	Yes	Yes			
10	Storage Trailer Area	D008	1971-present	No	No			
11	Dumpster Area 1	D008	1984-present	No	Ио			
12	Dumpster Area 2	NH*	1971-present	No	No			
13	Dumpster Area 3	NH	1971-present	No	Ио			
14	Baghouse 1 (casting)	D008	1984-present	ИО	ИО			
15	Baghouse 2 (vacuum)	D008	1971-present	No	No			
16	Baghouse 3 (assembly)	D008	1971-present	No	Ио			
17	Indoor WWT	D008	1986-present	No	ИО			
	AREAS_OF_CONCERN							
1	Low Area (east)	_	Unknown	No	No			
1	Low Area (west)	-	Unknown	No	No			
	Off-site Drainage Ditch	-	Unknown	No	No			
	Ponds (A-D)	-	Unknown	No	No			
	Dn-site Drainage Ditch	-	1971-present	No	No			
	Acid Spill Area	-	Nov. 3, 1980	No	No			
	lose Break Area	-	April 26, 1984	No	No			
+ GW = Ground Water Monitoring * NH = Not Hazardous								

<sup>- 11 -</sup>

Lead and lead containing wastes are shipped to the GNB Incorporated smelter in Frisco, Texas for recycling or processing.

A Notice of Registration, dated 11-13-86, also shows the generation and disposal of mineral spirits and a separate waste stream described as halogenated solvents [15]. These materials are derived from laboratory operations at the facility.

A wastewater is also generated from the filter press (see Figure 4). Most of this water is recirculated to the process, but some is discharged to a POTW.

Table 2 summarizes the waste materials generated at the GNB facility.

# TABLE 2 GNB BATTERIES, INCORPORATED WASTE MATERIALS DESCRIPTION FARMERS BRANCH, TEXAS

WASTE	DESCRIPTION USEPA	WASTE NUMBER
Lead Contaminated Sludge	Heavy metal sludge produced from the neutralization of acidic wastes from within the battery manufacturing plant.	D008
	The sludge contains approximately 55% water, 38% calcium sulfate, and 7% lead.	
Lead Contaminated Materials	Scrap and Whole Batteries. Scrap Products (Not otherwise specified). Contaminated Plastic and Rubber Battery Cases and Covers.	D008
Baghouse Dust	Miscellaneous lead containing dusts from hand vacuums and overhead ducts along assembly line.	D008
Contaminated Rags/Cloths	Miscellaneous rags and cloths soaked in solvents for cleaning batteries pricto shipping.	* or
Wood Pallets	Broken wood pallets.	*
Dry Batteries	Miscellaneous off-spec and mispunched batteries.	*

<sup>\* =</sup> Not Listed as a Hazardous Waste

#### 3.0 ENVIRONMENTAL SETTING

#### 3.1 Meteorology and Air Quality [2, 18]

Summers are hot in Dallas County with an average temperature of 84 degrees F, and an average daily maximum temperature of 94 degrees F. In winter the average temperature is 48 degrees F, and the average daily minimum temperature is 38 degrees F. Winters are cool as a result of occasional surges of cold air, which cause the otherwise mild temperatures to drop.

The total annual precipitation is 36 inches, while the annual average evaporation is 63-65 inches. Of the precipitation, 20 inches, or 57 percent, usually falls in April through September. Average seasonal snowfall is 2 inches.

The average relative humidity in midafternoon is about 55 percent. Humidity is higher at night, and the average at dawn is about 79 percent. The sun shines 75 percent of the possible time in summer and 55 percent in winter.

The prevailing wind is from the south. Average wind speed is highest, 13 miles per hour, in April.

#### 3.2 Floodplain and Surface Water [2,24,26,27]

The GNB facility is located approximately 1 mile to the west of the Elm Fork of the Trinity River, and approximately 7 miles to the southeast of North Lake. The Trinity River passes through downtown Dallas before discharging into the Gulf of Mexico.

The site is protected from flood waters of the Trinity River by earthen dikes constructed along both sides of the river by the Corp of Engineers.

Farmers Branch, like most suburbs of Dallas, purchases its water directly from the City of Dallas. The amount of water purchased varies daily, monthly, and seasonally. The maximum amount purchased in one day during June, 1987 was 11,662,000 gallons.

The City of Dallas receives most of its water from man-made reservoir/lakes. Dallas receives its water from the following sources: Lake Ray Hubbard, Grapevine Lake, Lewisville Lake, and Lake Tawakoni. It also has access to the Lake Fork Reservoir and Lake Palestine, when needed.

The City of Dallas has recently begun filling another reservoir (Lake Ray Roberts) for future use. It is estimated that this lake will be full in six years.

No water is taken directly from aquifers in the area, or directly from rivers. However, the Elm Fork of the Trinity River fills three of the reservoir lakes that Dallas uses for water (Grapevine Lake, Lewisville Lake, and Lake Ray Roberts). The Sabine River fills Lake Tawakoni and the Lake Fork Reservoir.

#### 3.3 Geology and Soils [2,17]

The GNB facility is situated, physiographically, on the Gulf Coastal Plain province. The original site soils have been stripped away by extensive sand and gravel mining in the vicinity of the GNB site. This sand and gravel mining has left fill over bedrock at the site composed of clay, sand, and gravel. This fill appears to be rather heterogenous in nature, as drastic lithologic changes occur in relatively short distances, as shown by the boring logs. The fill materials, however, have predominantly coarse-grained textures.

Regionally, alluvial sand and gravel deposits are extensive over the area, and range up to 300 feet thick. These thick Quaternary alluvial deposits are the target for local sand and gravel mining. The reworked alluvium at the GNB facility is approximately 10 to 15 feet in thickness. This reworked alluvial overlies shale bedrock of the Cretaceous Eagle Ford Group.

The Eagle Ford Group is typified by undivided shale, limestone, and sandstone deposits. Calcareous concretions with large, irregular, internal polygonal cracks are common. The Woodbine Formation underlies the Eagle Ford Group and forms the base of the Gulfian Series of the Cretaceous sediments. In general, the deposits of Cretaceous Age dip to the south-southeast.

#### 3.4 <u>Ground Water</u> [2,17,28]

The company installed a bentonite slurry wall and two monitoring wells in 1976 near the surface impoundments. Three additional wells were installed in March, 1983. All five wells are finished in the reworked alluvium above bedrock. Ground water saturates the reworked alluvium to form water table conditions at the site. The water table in the reworked alluvium fluctuates, but rises to approximately 5 feet from the surface grade. A compliance order was issued September 27, 1984, ordering, among other items, the development of a ground water assessment plan. This requirement was based on ground water sampling in 1982 which identified elevated concentrations of lead (0.09 mg/l and 0.15 mg/l) in the northern and southern wells, and sulfates in the northern and southern wells (890 mg/l and 645 mg/l).

Ground water monitoring results (28) for 1986 and 1987 were reviewed. Results were available for samples taken 2-27-86, 4-24-86, 8-27-86 and 3-31-87. No lead was found in any well (MW-1A, MW-2A, MW-3A, MW-N, MW-S). The detection limit was .05 mg/l. Significant levels of sulfates, however, were found in all wells. The lowest levels were found in well MW-3A, ranging from 75 to 140 mg/l. The highest levels were found in MW-S, ranging from 480 to 1,835 mg/l. Sulfates in the other wells generally ran between 790 and 980 mg/l. The secondary Maximam Contaminant level for sulfate is 250 mg/l (40 CFR 143.3). There was no apparent decrease in sulfates levels over time. Indeed, the highest levels in all wells, except MW-N, were observed on 3-31-87. A significant increase in the specific conductance data was reported for MW-S on 2-27-86, 4-24-86 and 3-31-87. No significant increases were reported, for any wells, for pH, TOC, or TOX.

As part of the ground water assessment monitoring plan, GNB has installed a total of five ground water monitoring wells, and nine piezometers. The tentative results of this assessment indicate that ground water flow direction is to the southeast, with a gradient that ranges from approximately 0.008 to 0.013. There is no information available concerning the hydraulic conductivity of the alluvium and, therefore, no ground water flow velocities or rates can be calculated.

The shales of the Eagle Ford Group should impede vertical migration of ground water in the vicinity of the GNB facility. The ground water could, however, migrate off site and actually create springs or seeps into the surrounding gravel pits and result in further releases to the environment. The ultimate fate of any contaminants that had migrated into the gravel pits would depend on the hydrogeologic environment in connection with the gravel pit itself.

#### 3.5 Receptor Information [23, 24]

The GNB facility is located just west of Farmers Branch, Texas and northwest of Dallas, Texas, in Dallas County. The area just to the south of the facility has been extensively mined for sand and gravel.

An April 1, 1980 census shows the population of Dallas County as 1,556,390, covering approximately 880 square miles. The census [23] also shows Farmers Branch with a population of 24,863, covering 12.5 square miles.

Dallas County contains approximately 980 farms (as of 1980) which cover about 41.5 percent of all land in the county. Of the land in Dallas County, 1.5 percent is irrigated.

The prevailing wind is from the south. Average wind speed is highest, 13 miles per hour, in April. There are no towns directly in the path of the prevailing wind in the immediate vicinity of the facility.

The major waterway in the area is the Elm Fork of the Trinity River which passes just to the west of the facility. The river passes directly through downtown Dallas before actually discharging into the Gulf of Mexico. Rawhide Creek passes south of the facility before discharging into the Elm Fork of the Trinity River.

#### 4.0 RELEASE PATHWAYS

#### 4.1 Ground Water Pathway [2]

The ground water levels appear to fluctuate greatly but reach levels as high as 5 feet below grade.

The major sources of concern for ground water contamination were the four settling ponds. However, the ponds are RCRA regulated and are currently undergoing closure. All wastes have been removed and soils have been tested to insure that there is no contamination. Therefore, once the ponds are properly closed and certified, there is a low potential for future releases. Prior to closure, these ponds were unlined, but the company installed a bentonite slurry wall designed to prevent ground water releases. The wall was installed in 1976, five years after the battery The manufacturing operations began. wall was installed approximately eight feet into the bedrock. Lead and sulfate contamination were detected at company installed ground water monitoring wells located outside the slurry wall. Therefore, the potential for past releases from these ponds is high.

#### 4.2 Soil Pathway [2]

The soils in the area are rather heterogenous in nature, due to extensive mining, and drastic changes in soil texture occur in relatively short distances. The soils are predominantly coarse-grained and are, thus, moderately permeable. Therefore, there is a moderate potential for migration of hazardous wastes or hazardous waste constituents through the soils.

Due to the extensive mining in the nearby area, the route of the ground water through the soils is unknown but could possibly connect to many of the nearby lakes from which Dallas receives its water supply.

#### 4.3 Surface Water Pathway [13, 19, 24]

The GNB facility is located near the Elm Fork of the Trinity River. The facility maps show six areas that are labeled as either depressed areas or ponds. During the VSI these areas were all dry, but it is assumed that these areas collect water during rainstorms. There is also a drainage channel just south of the property line which is labeled as having 3 feet of water. A 2 foot concrete main from at least one of the ponds to this drainage channel was found [19]. However, according to the facility, this main is left over from when Morton Foods owned the property and has been plugged since operation of the ponds by Gould, Inc. began in 1972.

The drainage channel eventually discharges into the Elm Fork of the Trinity River and the 2 foot concrete main presented a potential direct connection between the ponds and the river in the event that the plug developed leaks.

It has been documented that the company did not maintain an adequate freeboard in the ponds when they were in operation [13]. If the water level in the ponds overtopped during a heavy rainstorm, the depressed areas could have retained wastes and presented another release pathway for surface water contamination during subsequent rainfalls.

The ponds are RCRA regulated and are currently undergoing closure. All wastes have been removed and soils have been tested to insure that there is no contamination. Therefore, once the ponds are properly closed and certified, there is a low potential for future releases to surface waters.

#### 4.4 Air Pathway [18]

The prevailing wind is from the south. Average wind speed is highest, 13 miles per hour, in April. There are no towns located directly in the path of the prevailing wind. However, downtown Farmers Branch is located less than 1.5 miles directly to the east of the facility, and the Dallas city boundary is less than a mile to the southeast.

There is a school and a park approximately 1.25 miles to the east of the facility.

The major waste handled at the facility is acidic lead contaminated wastewaters generated from battery manufacturing. The non-volatile nature of lead presents little possibility of air emissions.

The only units identified as having a realistic potential for air releases were the hazardous waste dumpster (SWMU 11) and the casting baghouse (SWMU 14).

The only volatile wastes handled at the facility are naphtha and acetone. These are contained in rags which are used to clean the completed batteries prior to shipment. The rags are stored in drums within an enclosed trailer located on SWMU 10 and present a low potential for air releases.

#### 4.5 Subsurface Gas Pathway

The potential for release of subsurface gas is low due to the nature of the wastes being handled at the facility (non-volatile lead contaminated wastewaters with no organics).

#### 5.0 DESCRIPTION OF SOLID WASTE MANAGEMENT UNITS (SWMUs)

This section provides an assessment of the 17 SWMUs located at the GNB facility that were identified during the PR and VSI. The following descriptions contain information on each SWMU including a unit description, dates of operation, wastes managed, release controls, history of releases, and potential for releases to ground water/soils, surface water, and air, plus the potential for generation of subsurface gas.

Table 3 presents a summary of the SWMUs. The table shows the wastes managed, operating dates, release controls, and history of releases from the units.

#### 5.1 SWMU 1: Wastewater Pipe

#### 5.1.1 Information Summary

This unit is an underground pipeline that Unit Description: carries the wastewaters from within the plant building out to the All the floor drains within the facility neutralization tanks. are consolidated into one pipe before leaving the plant building. While installing a shut-off valve for the pipe, facility representatives noted a crack on the top of the pipe, improperly sealed feeder line into the pipe. This incident took place on January 24, 1984. There were no visual signs of leaks, but soil samples were taken and sent to the State. The State did not respond to the submission of sample data. Therefore, no further action was taken. The pipe is clay tile of the bell and spigot design. The pipe has no leak detection, and any cracks which have developed might not be found for a long period of time. The unit is buried under a concrete paved area and was not able to be inspected during the VSI.

<u>Dates of Operation</u>: The line has been utilized since 1972. It is currently in use.

<u>Wastes Managed</u>: The pipeline carries wastewater from the plant processes to the neutralization tanks. The wastewater is acidic and contains lead.

Release Controls: There are no release controls.

History of Releases: The only documented potential release was the uncovering of the crack and feeder line situation in January 1984. No action was pursued by the State after GNB reported the information along with sample data.

TABLE 3

GNB BATTERIES, INCORPORATED

SOLID WASTE MANAGEMENT UNIT (SWMU) SUMMARY AND RELEASE INFORMATION
FARMERS BRANCH, TEXAS

		Waste	Operating	Release	History of
SWMU #	Name	Managed	Dates	Controls	Releases
1	Wastewater Pipe	B000	1972-present	None	Crack found in pipe in 1984.
2	Truck Wash Sump	8000	1978-present	None	No Known Releases
3	First Neutralization Pit/Tank	D008	1972-present	None	No Known Releases
4	Second Neutralization Pit/Tank	8000	1972-present	None	No Known Releases
5	Pond 1	D008	1972-1985	Slurry Wall	Lead and Sulfates detected in ground water monitoring wells located outside of slurry wall
6	Pond 4	B000	1972-1985	Sturry Wall	(See SWMU 5 Comment)
7	Pond 2	D008	1972-1985	Sturry Wall	(See SWMU 5 Comment)
8	Pond 3	B008	1972-1985	Slurry Wall	(See SWMU 5 Comment)
9	Dry Waste Pit	B000	1972-present	None	No Known Releases
10	Storage Trailer Area	D008 NH(+)	1971-present	Concrete Paved Area	No Known Releases
11	Dumpster Area 1	<b>800</b> 0	1984-present	Concrete Paved Area	No Known Releases
12	Dumpster Area 2 (pallets)	NH	1971-present	Concrete Paved Area	No Known Releases
13	Dumpster Area 3 (trash)	NH	1971-present	Concrete Paved Area	No Known Releases
14	Baghouse 1 (casting)	8000	1971-present	Concrete Paved Area	No Known Releases
15	Baghouse 2 (vacuum)	B008	1971 - present	Inside Plant	No Known Releases
16	Baghouse 3 (assembly)	B000	1971 - present	Inside Plant	No Known Releases
17	Indoor WVT	D008	1986-present	Inside Plant	No Known Releases

<sup>+</sup> NH= Not Listed as a Hazardous Waste

#### 5.1.2 Release Potential

Ground Water/Soils: The unit has a high potential for releases to ground water, both past and continuing. The pipe is not well suited for carrying wastewater, and there is a good chance that leaks have developed or will develop. The pipe is of the bell and spigot design and is composed of clay tile which is easily cracked.

Surface Water: The unit displays low potential for a past or continuing release to surface water because it is underground. The only source of surface water contamination would be through the ground water.

<u>Air</u>: This unit has a low potential for past or continuing air releases due to the fact that it is buried underground.

Subsurface Gas: The unit has a low potential for past or continuing generation of subsurface gas due to the types of wastes being handled (acidic, lead contaminated wastewater with no organics).

#### 5.2 SWMU 2: Truck Wash Sump (VSI Photo 2)

#### 5.2.1 Information Summary

Unit Description: This SWMU is a 3 foot x 3 foot x 8 feet deep reinforced concrete collection sump which is used to collect wastewater resulting from the washing down of the trailers, trucks, and floor scrubbing machines used within the facility. The sump feeds the first neutralization tank directly by means of a gravity drain from the top of the sump. The VSI discovered no cracks or evidence of overflows which would indicate potential releases. The unit is not lined or provided with any secondary containment features. The concrete pad is sloped towards the grate and the sides of the pad are curbed. There is a seam in the concrete pad surrounding the grate. This may afford a potential pathway for contaminant migration into soils. There was no evidence to suggest that the sump had ever overflowed.

<u>Dates of Operation</u>: The unit was installed in 1978. It is currently active.

<u>Wastes Managed</u>: This unit is used to collect wash water from the cleaning of truck trailers and plant maintenance (dust collection) equipment. Some of this material may contain lead.

Release Controls: There are no release controls.

History of Releases: There is no documented history of releases for this unit.

#### 5.2.2 Release Potential

Ground Water/Soils: During the VSI, the unit appeared to be in good condition and no cracks were noted. A slight potential for contaminant migration exists from the seam in the concrete pad. Therefore, there is a low potential for the occurrence of past or continuing releases to ground water or soils.

Surface Water: The potential for past or continuing releases to surface water is low. The unit discharges wastes directly to the first neutralization tank and is designed to handle heavy rainstorms without overflowing.

Air: The potential for a past or continuing release to the air is low due to the non-volatile nature of lead. Release of sulfuric acid vapors could, potentially, be a concern for people in the immediate vicinity of the sump, but not for the population at large. Subsurface Gas: The potential for past or continuing subsurface gas generation is low due to the types of wastes being handled and the nature of the sump.

#### 5.3 SWMU 3: First Neutralization Pit/Tank (VSI Photos 2 and 3)

#### 5.3.1 <u>Information Summary</u>

Unit Description: This neutralization pit received untreated wastewaters from the floor drains within the plant, the truck wash sump, and the manufacturing process until approximately May 22, 1985, when the facility switched waste handling procedures. Lime for neutralization, and calcium carbonate to improve lead removal, were added into this pH monitored, concrete pit. The pit was equipped with air agitation and lime addition. Addition of chemicals into the pit was accomplished by means of a flexible hose so that the point of addition was not fixed. After the primary neutralization and precipitation process was complete, the neutralized wastes flowed to the Second Neutralization Pit (SWMU 4) via riser pipes from the bottom of the first pit.

This neutralization pit is constructed of concrete. The unit is partially underground and had no means of inspection while in operation because there was continuous flow [9].

A picture of the first neutralization pit, as it existed on November 4, 1982, is shown as Photo A [8].

A pit liner was installed in 1984 [14]. The liner was fabricated from a UV protected PVC sheet material (grey, 60 mil) and laid loose over the pit. Attachment was via booting with backing plates at 8-12 inch intervals around the top perimeter. However, during the VSI, Everett Milton of GNB indicated that this facility liner leaked and the decided to abandon the neutralization pit in favor of a polypropylene tank. The pit is currently being used as secondary containment for the tank. Also, according to Mr. Milton, there have been have been no known leaks from the pit [30].


The tank has a 5,000-gallon capacity. It is used in the same manner as the neutralization pit. The tank was installed in 1985.

Any cracks would be the major avenues for migration out of this unit. During the VSI, the pit appearred to be in sound condition with no signs of cracks.

Dates of Operation: The pit was used from 1972 to 1985. The tank has been in use since 1985. The pit itself is currently used for secondary containment.



First Neutralization Pit Influent on Left - CaCO3 Addition on Far Wall



Second Neutralization Pit

Texas Department of Water Resources - District 4

Gould Inc Neutralization Pits

11/4/8 -

D17ax.

Wastes Managed: The waste handled by this SWMU is the wastewater from plant processes. This waste is acidic and contained lead.

Release Controls: There was an attempt at lining the pit at one time. This did not prove successful so, the tank was installed. The pit provides secondary containment.

<u>History of Releases</u>: There is no documented history of releases from this unit.

#### 5.3.2 Release Potential

Ground Water/Soils: The neutralization pit was unlined until 1984. It had no means of inspection because it was partially underground, and there was continuous flow. Due to the acidic nature of the wastes, there is high potential for past releases to ground water or soils from this unit, although none have occurred [30]. The unit is presently being used as secondary containment for wastes being treated in the first polypropylene tank. Thus, the potential for continuing releases is low.

Surface Water: The design and location of the unit give it a low potential for past releases to surface water. The unit discharges to the second neutralization pit and there is no evidence that the unit has ever overflowed. The unit is in operation as secondary containment presently. The potential for continuing releases is low.

<u>Air</u>: The potential for a past or continuing release to the air is low due to the non-volatile nature of the lead and calcium sulfate wastes being processed.

Subsurface Gas: The potential for past or continuing subsurface gas generation is low due to the types of wastes (acidic, lead containing materials with no organics) being handled.

#### 5.4 SWMU 4: Second Neutralization Pit/Tank (VSI Photos 2 and 3)

#### 5.4.1 <u>Information Summary</u>

Unit Description: This unit received treated wastewaters via riser pipes from the first neutralization pit (SWMU 3). Air agitation continued in this pit and a second pH reading was taken. If necessary, additional lime was added. The pH probe in this second pit also controlled a safety override by sounding an alarm and preventing the pump from starting if the pH was below 5.0. If the pH was acceptable, automatic level controls pumped the treated wastes into the pond system (SWMUs 5 through 8) for settling prior to discharge.

This neutralization pit is constructed of concrete. The unit is partially underground and had no means of inspection while in operation because there was continuous flow [9].

A picture of the second neutralization pit, as it existed on November 4, 1982, is shown as Photo A [8].

A pit liner was installed in 1984 [14]. The liner was fabricated from a UV protected PVC sheet material (grey, 60 mil) and laid loose over the pit. Attachment was via booting with backing plates at 8-12 inch intervals around the top perimeter. However, during the VSI, Everett Milton of GNB indicated that this liner leaked and the facility decided to abandon the neutralization pit in favor of a polypropylene tank. The pit is currently being used as secondary containment for the tank. Also, according to Mr. Milton, there have been no known releases from this pit [30].

The tank has a 5,000-gallon capacity. It is used in the same manner as the neutralization pit. The tank was installed in 1985.

Any cracks would be the major avenues for migration out of this unit. During the VSI, the pit appeared to be in sound condition with no signs of cracks.

Dates of Operation: The pit was used from 1972 to 1985. The tank has been in use since 1985. The pit itself is currently used for secondary containment.

<u>Wastes Managed</u>: The waste handled by this SWMU is the wastewater from plant processes. This waste is acidic and contained lead.

Release Controls: There was an attempt at lining the pit at one time. This did not prove successful, so the tank was installed. The pit provides secondary containment.

<u>History of Releases</u>: There is no documented history of releases from this unit.

#### 5.4.2 Release Potential

Ground Water/Soils: The neutralization pit was unlined until 1984. It had no means of inspection because it was partially underground, and there was continuous flow. Due to the acidic nature of the wastes, there is high potential for past releases to ground water or soils from this unit, although no releases have occurred [30]. The unit is presently being used as a secondary basin for wastes being treated in the first polypropylene tank. Thus, the potential for continuing releases is low.

Surface Water: The design and location of the unit give it a low potential for past releases to surface water. The unit discharges to the second neutralization pit and there is no evidence that the unit has ever overflowed. The unit is in operation as secondary containment presently. The potential for continuing releases is low.

Air: The potential for a past or continuing release to the air is low due to the non-volatile nature of the lead and calcium sulfate wastes being processed.

Subsurface Gas: The potential for past of continuing subsurface gas generation is low due to the types of wastes (acidic, lead containing materials with no organics) being handled.

# 5.5 SWMU 5: Pond 1 (VSI Photos 4, 6, 8, and 10)

# 5.5.1 <u>Information Summary</u>

Unit Description: Pond 1 was one of four surface impoundments that received neutralized acidic wastes from the second neutralization pit. Figure 2 shows the treatment process before discharge to the surface impoundments. Figure 5 shows the location of Pond 1, as well as Ponds 2, 3, and 4 and the dry waste pit. Figure 6 shows greater details of the four ponds. Figure 7 shows a cross section of a typical pond. Pond 1 was approximately 135 feet by 89 feet and was located in the northwest corner of the four ponds. All four ponds were unlined.

Ponds 1 and 4 were hydraulically connected and together formed what is basically an inverted, truncated pyramid, approximately 120 feet x 120 feet at the base, by 12 feet deep, with the side walls having a 33% slope. The volume of this pair of impoundments was estimated at 3,612 cubic yards [10]. Ponds 2 and 3 formed a similar inverted pyramid with approximately the same volume (3,612 cubic yards). The dikes within the impoundment system were all about 10 feet wide, as can be seen from Figure 6. The dike between Pond 1 and Pond 4 was composed of a porous material which acted as a filter between the two ponds and helped separate the wastewater.

Since approximately May 22, 1985, the ponds have not been used due to a change in the disposal process at the GNB facility. Prior to this change, Ponds 1 and 2 received treated wastewater from the neutralization pits. The slurry resulted from the neutralization of sulfuric acid and contained high levels of lead. The solids contained within the slurry were allowed to settle to the bottom of the pond, and the wastewater flowed into Ponds 3 and 4 from where it was eventually discharged into the sanitary sewer. The sludge was then retrieved and chemically fixed on site (at least until 1982). The fixed materials were retained in the disposal pit prior to eventual off-site disposal.

The facility claims [5] that the composition of the sludge in the surface impoundments was uniform throughout the lagoon, since there is only one source of waste and the manufacturing and wastewater treatment processes are consistent. The sludges are a mixture of non-flammable solids and water. The solids are primarily calcium sulfate and water [5]. The sludges are not ignitable, corrosive, or reactive, but contain E.P. Toxic levels of lead.




Figure 6: Detail of four ponds




Figure 7: Cross section of a typical pond

The estimated composition of the sludge is 55% water, 38% calcium sulfate, and 7% lead [15]. Other estimated constituents include antimony (20 ppm), arsenic (0.01 ppm), cadmium (5 ppm), total chromium (200 ppm), copper (50 ppm), mercury (0.6 ppm), nickel (20 ppm), selenium (100 ppm), silver (2.0 ppm), thallium (6.0 ppm), zinc (6.0 ppm), and beryllium (70 ppm).

The sludge ponds began operation on May 15, 1972 [8]. Both installation of liners and a slurry wall were recommended during the early 1970's. The facility chose to only install the slurry wall which, according to company letters, was completed on May 28, 1976. The integrity of this wall is in question because ground water contamination has been detected in company installed monitoring wells outside the slurry wall. A 2 foot concrete main connecting some of the ponds with a drainage channel located off company property also existed. However, according to the facility, this channel is left over from when Morton Foods owned the property and has been plugged since operation of the ponds by Inc. began. The drainage channel discharges into the Gould. Trinity River. There are also low areas in the vicinity that could accept surface run-off from this pond had it ever occurred.

The ponds have not always maintained two feet of freeboard. For instance, during an inspection on February 29, 1984, there was only 9 inches of freeboard in one pond [13]. There are no records of overflowing of the pond.

<u>Dates of Operation</u>: The unit was in operation from 1972 to 1985.

The company has submitted a Closure Plan for the ponds and removed wastes from this area [22].

<u>Wastes Managed</u>: The unit accepted treated wastewaters from the neutralization system. These wastewaters contained lead and were originally acidic.

Release Controls: There were no release controls. The facility installed a bentonite slurry wall designed to prevent ground water contamination.

History of Releases: There is no documentation of releases from this unit. Inadequate freeboard had been noted; however, no instances of overflowing have been recorded. The integrity of

the slurry wall is in question because company installed monitoring wells have detected sulfate contamination outside the wall.

# 5.5.2 Release Potential

Ground Water/Soils: There is a high potential that past releases have occurred. Monitoring wells on site have shown elevated levels of sulfates. Also, the ponds were not lined. There is a low potential for continuing releases once closure has been completed.

Surface Water: The proximity of the low areas, the inadequately maintained freeboard, and uncertainty about whether the 2 foot main was properly sealed result in a moderate potential for past releases to surface water. The facility has submitted a Closure Plan for these ponds, and wastes and contaminated soils have been removed [22]. Therefore, there is a low potential for continuing releases to surface water.

Air: There is a low potential for past releases to the air due to the non-volatile nature of the lead contaminated sludges being processed. Once closure is completed, the potential for continuing releases will be even less.

Subsurface Gas: There is a low potential for past generation of subsurface gas due to the nature of the sludge being processed. Once closure is completed, the potential will be even less for continuing releases.

# 5.6 SWMU 6: Pond 4 (VSI Photos 4, 6, 8, and 10)

# 5.6.1 <u>Information Summary</u>

Unit Description: Pond 4 was one of four surface impoundments that received neutralized acidic wastes from the second neutralization pit. Figure 2 shows the treatment process before discharge to the surface impoundments. Figure 5 shows the location of Pond 4, as well as Ponds 1, 2, and 3 and the Dry Waste Pit. Figure 6 shows greater details of the four ponds. Figure 7 shows a cross section of a typical pond. Pond 4 was approximately 126 feet by 50 feet and is located in the northeast corner of the four ponds. All four ponds were unlined.

Ponds 1 and 4 were hydraulically connected and formed what is basically an inverted, truncated pyramid, approximately 120 feet x 120 feet on the base, by 12 feet deep, with the side walls having a 33% slope. The volume of this pair of impoundments was estimated at 3,612 cubic yards [10]. Ponds 2 and 3 formed a similar inverted pyramid with approximately the same volume (3,612 cubic yards). The dikes within the impoundment system were all about 10 feet wide, as can be seen from Figure 6. The dike between Pond 1 and Pond 4 was composed of a porous material which acted as a filter between the two ponds and helped separate the wastewater.

Since approximately May 22, 1985, the ponds have not been used due to a change in the disposal process at the GNB facility. Prior to this change, Ponds 1 and 2 received treated wastewater from the neutralization pits. The slurry resulted from the neutralization of sulfuric acid and contained high levels of lead. The solids contained within the slurry were allowed to settle to the bottom of the pond, and the wastewater flowed into Ponds 3 and 4 from where it was eventually discharged into the sanitary sewer. The sludge was then retrieved and chemically fixed on site (at least until 1982). The fixed materials were retained in the disposal pit prior to eventual off-site disposal.

The facility claims [5] that the composition of the sludge in the surface impoundments was uniform throughout the lagoon, since there is only one source of waste and the manufacturing and wastewater treatment processes are consistent. The sludges are a mixture of non-flammable solids and water. The solids are primarily calcium sulfate and water [5]. The sludges are not ignitable, corrosive, or reactive, but contain E.P. Toxic levels of lead.

The estimated composition of the sludge is 55% water, 38% calcium sulfate, and 7% lead [15]. Other estimated constituents

include antimony (20 ppm), arsenic (0.01 ppm), cadmium (5 ppm), total chromium (200 ppm), copper (50 ppm), mercury (0.6 ppm), nickel (20 ppm), selenium (100 ppm), silver (2.0 ppm), thallium (6.0 ppm), zinc (6.0 ppm), and beryllium (70 ppm).

The sludge ponds began operation on May 15, 1972 [8]. Both installation of liners and a slurry wall were recommended during the early 1970's. The facility chose to only install the slurry wall which, according to company letters, was completed on May 28, 1976. The integrity of this wall is in question because ground water contamination has been detected in company installed monitoring wells outside the slurry wall. A 2 feet concrete main connecting some of the ponds with a drainage channel located off company property also existed. However, according to the facility, this channel is left over from when Morton Foods owned the property and has been plugged since operation of the ponds by Gould, Inc. began. The drainage channel discharges into the Trinity River. There are also low areas in the vicinity that could accept surface run-off from this pond had it ever occurred.

The ponds have not always maintained two feet of freeboard. For instance, during an inspection on February 29, 1984, there was only 9 inches of freeboard in one pond [13]. There are no records of overflowing of the pond.

<u>Dates of Operation</u>: The unit was in operation from 1972 to 1985.

The company has submitted a Closure Plan for the ponds and removed wastes from this area [22].

<u>Wastes Managed</u>: The unit accepted treated wastewaters from the neutralization system. These wastewaters contained lead and were originally acidic.

Release Controls: There were no release controls. The facility installed a bentonite slurry wall designed to prevent ground water contamination.

History of Releases: There is no documentation of releases from this unit. Inadequate freeboard had been noted; however, no instances of overflowing have been recorded. The integrity of the slurry wall is in question because company installed monitoring wells have detected sulfate contamination outside the wall.

# 5.6.2 Release Potential

Ground Water/Soils: There is a high potential that past releases have occurred. Monitoring wells on site have shown elevated levels of sulfates. Also, the ponds were not lined. There is a low potential for continuing releases once closure has been completed.

Surface Water: The proximity of the low areas, the inadequately maintained freeboard, and uncertainty about whether the 2 foot main was properly sealed result in a moderate potential for past releases to surface water. The facility has submitted a Closure Plan for these ponds, and wastes and contaminated soils have been removed [22]. Therefore, there is a low potential for continuing releases to surface water.

<u>Air</u>: There is a low potential for past releases to the air due to the non-volatile nature of the lead contaminated sludges being processed. Once closure is completed, the potential for continuing releases will be even less.

Subsurface Gas: There is a low potential for past generation of subsurface gas due to the nature of the sludge being processed. Once closure is completed, the potential will be even less for continuing releases.

# 5.7 SWMU 7: Pond 2 (VSI Photos 7, 8, 10, 12, and 13)

#### 5.7.1 Information Summary

Unit Description: Pond 2 was one of four surface impoundments that received neutralized acidic wastes from the second neutralization pit. Figure 2 shows the treatment process before discharge to the surface impoundments. Figure 5 shows the location of Pond 1, as well as Ponds 2, 3, and 4 and the Dry Waste Pit. Figure 6 shows greater details of the four ponds. Figure 7 shows a cross section of a typical pond. Pond 2 is approximately 140 feet by 105 feet and is located in the southwest corner of the four ponds (Figure 6). All four ponds are unlined.

Ponds 2 and 3 were hydraulically connected and formed what is basically an inverted, truncated pyramid, approximately 120 feet x 120 feet on the base, by 12 feet deep, with the side walls having a 33% slope. The volume of this pair of impoundments was estimated at 3,612 cubic yards [10]. Ponds 1 and 4 formed a similar inverted pyramid with approximately the same volume (3,612 cubic yards). The dikes within the impoundment system were all about 10 feet wide, as can be seen from Figure 6. The dike between Pond 2 and Pond 3 was composed of a porous material which acted as a filter between the two ponds and helped separate the wastewater.

Since approximately May 22, 1985, the ponds have not been used due to a change in the disposal process at the GNB facility. Prior to this change, Ponds 1 and 2 received treated wastewater from the neutralization pits. The slurry resulted from the neutralization of sulfuric acid and contained high levels of lead. The solids contained within the slurry were allowed to settle to the bottom of the pond, and the wastewater flowed into Ponds 3 and 4 from where it was eventually discharged into the sanitary sewer. The sludge was then retrieved and chemically fixed on site (at least until 1982). The fixed materials were retained in the disposal pit prior to eventual off-site disposal.

The facility claims [5] that the composition of the sludge in the surface impoundments was uniform throughout the lagoon, since there is only one source of waste and the manufacturing and wastewater treatment processes are consistent. The sludges are a mixture of non-flammable solids and water. The solids are primarily calcium sulfate and water [5]. The sludges are not ignitable, corrosive, or reactive, but contain E.P. Toxic levels of lead.

The estimated composition of the sludge is 55% water, 38% calcium sulfate, and 7% lead [15]. Other estimated constituents

include antimony (20 ppm), arsenic (0.01 ppm), cadmium (5 ppm), total chromium (200 ppm), copper (50 ppm), mercury (0.6 ppm), nickel (20 ppm), selenium (100 ppm), silver (2.0 ppm), thallium (6.0 ppm), zinc (6.0 ppm), and beryllium (70 ppm).

The sludge ponds began operation on May 15, 1972 [8]. Both installation of liners and a slurry wall were recommended during the early 1970's. The facility chose to only install the slurry wall which, according to company letters, was completed on May 28, 1976. The integrity of this wall is in question because ground water contamination has been detected in company installed monitoring wells outside the slurry wall. A 2 foot concrete main connecting some of the ponds with a drainage channel located off company property also existed. However, according to the facility, this channel is left over from when Morton Foods owned the property and has been plugged since operation of the ponds by Gould, Inc. began. The drainage channel discharges into the Trinity River. There are also low areas in the vicinity that could accept surface run-off from this pond had it ever occurred.

The ponds have not always maintained two feet of freeboard. For instance, during an inspection on February 29, 1984, there was only 9 inches of freeboard in one pond [13]. There are no records of overflowing of the pond.

Dates of Operation: The unit was in operation from 1972 to 1985.

The company has submitted a Closure Plan for the ponds and removed wastes from this area [22].

<u>Wastes Managed</u>: The unit accepted treated wastewaters from the neutralization system. These wastewaters contained lead and were originally acidic.

Release Controls: There were no release controls. The facility installed a bentonite slurry wall designed to prevent ground water contamination.

History of Releases: There is no documentation of releases from this unit. Inadequate freeboard had been noted; however, no instances of overflowing have been recorded. The integrity of the slurry wall is in question because company installed monitoring wells have detected sulfate contamination outside the wall.

## 5.7.2 Release Potential

Ground Water/Soils: There is a high potential that past releases have occurred. Monitoring wells on site have shown elevated levels of sulfates. Also, the ponds were not lined. There is a low potential for continuing releases once closure has been completed.

Surface Water: The proximity of the low areas, the inadequately maintained freeboard, and uncertainty about whether the 2 foot main was properly sealed result in a moderate potential for past releases to surface water. The facility has submitted a Closure Plan for these ponds, and wastes and contaminated soils have been removed [22]. Therefore, there is a low potential for continuing releases to surface water.

 $\overline{\text{Air}}$ : There is a low potential for past releases to the  $\overline{\text{air}}$  due to the non-volatile nature of the lead contaminated sludges being processed. Once closure is completed, the potential for continuing releases will be even less.

Subsurface Gas: There is a low potential for past generation of subsurface gas due to the nature of the sludge being processed. Once closure is completed, the potential will be even less for continuing releases.

# 5.8 SWMU 8: Pond 3 (VSI Photos 7, 8, 10, 12, and 13)

# 5.8.1 <u>Information Summary</u>

Unit Description: Pond 3 was one of four surface impoundments that received neutralized acidic wastes from the second neutralization pit. Figure 2 shows the treatment process before discharge to the surface impoundments. Figure 5 shows the location of Pond 3, as well as Ponds 1, 2, and 4 and the Dry Waste Pit. Figure 6 shows greater details of the four ponds. Figure 7 shows a cross section of a typical pond. Pond 3 was approximately 131 feet by 48 feet (Figure 6) and is located in the southeast corner of the four ponds. All four ponds were unlined.

Ponds 2 and 3 were hydraulically connected and formed what is basically an inverted, truncated pyramid, approximately 120 feet x 120 feet on the base, by 12 feet deep, with the side walls having a 33% slope. The volume of this pair of impoundments was estimated at 3,612 cubic yards [10]. Ponds 1 and 4 formed a similar inverted pyramid with approximately the same volume (3,612 cubic yards). The dikes within the impoundment system were all about 10 feet wide, as can be seen from Figure 6. The dike between Pond 2 and Pond 3 was composed of a porous material which acted as a filter between the two ponds and helped separate the wastewater.

Since approximately May 22, 1985, the ponds have not been used due to a change in the disposal process at the GNB facility. Prior to this change, Ponds 1 and 2 received treated wastewater from the neutralization pits. The slurry resulted from the neutralization of sulfuric acid and contained high levels of lead. The solids contained within the slurry were allowed to settle to the bottom of the pond, and the wastewater flowed into Ponds 3 and 4 from where it was eventually discharged into the sanitary sewer. The sludge was then retrieved and chemically fixed on site (at least until 1982). The fixed materials were retained in the disposal pit prior to eventual off-site disposal.

The facility claims [5] that the composition of the sludge in the surface impoundments was uniform throughout the lagoon, since there is only one source of waste and the manufacturing and wastewater treatment processes are consistent. The sludges are a mixture of non-flammable solids and water. The solids are primarily calcium sulfate and water [5]. The sludges are not ignitable, corrosive, or reactive, but contain E.P. Toxic levels of lead.

The estimated composition of the sludge is 55% water, 38% calcium sulfate, and 7% lead [15]. Other estimated constituents

include antimony (20 ppm), arsenic (0.01 ppm), cadmium (5 ppm), total chromium (200 ppm), copper (50 ppm), mercury (0.6 ppm), nickel (20 ppm), selenium (100 ppm), silver (2.0 ppm), thallium (6.0 ppm), zinc (6.0 ppm), and beryllium (70 ppm).

The sludge ponds began operation on May 15, 1972 [8]. Both installation of liners and a slurry wall were recommended during the early 1970's. The facility chose to only install the slurry wall which, according to company letters, was completed on May 28, 1976. The integrity of this wall is in question because ground water contamination has been detected in company installed monitoring wells outside the slurry wall. A 2 foot concrete main connecting some of the ponds with a drainage channel located off also existed. company property However, according to the facility, this channel is left over from when Morton Foods owned the property and has been plugged since operation of the ponds by Gould, Inc. began. The drainage channel discharges into the Trinity River. There are also low areas in the vicinity that could accept surface run-off from this pond had it ever occurred.

The ponds have not always maintained two feet of freeboard. For instance, during an inspection on February 29, 1984, there was only 9 inches of freeboard in one pond [13]. There are no records of overflowing of the pond.

<u>Dates of Operation</u>: The unit was in operation from 1972 to 1985.

The company has submitted a Closure Plan for the ponds and removed wastes from this area [22].

<u>Wastes Managed</u>: The unit accepted treated wastewaters from the neutralization system. These wastewaters contained lead and were originally acidic.

Release Controls: There were no release controls. The facility installed a bentonite slurry wall designed to prevent ground water contamination.

History of Releases: There is no documentation of releases from this unit. Inadequate freeboard had been noted; however, no instances of overflowing have been recorded. The integrity of the slurry wall is in question because company installed monitoring wells have detected sulfate contamination outside the wall.

## 5.8.2 Release Potential

Ground Water/Soils: There is a high potential that past releases have occurred. Monitoring wells on site have shown elevated levels of sulfates. Also, the ponds were not lined. There is a low potential for continuing releases once closure has been completed.

Surface Water: The proximity of the low areas, the inadequately maintained freeboard, and uncertainty about whether the 2 foot main was properly sealed, result in a moderate potential for past releases to surface water. The facility has submitted a Closure Plan for these ponds, and wastes and contaminated soils have been removed [22]. Therefore, there is a low potential for continuing releases to surface water.

Air: There is a low potential for past releases to the air due to the non-volatile nature of the lead contaminated sludges being processed. Once closure is completed, the potential for continuing releases will be even less.

Subsurface Gas: There is a low potential for past generation of subsurface gas due to the nature of the sludge being processed. Once closure is completed, the potential will be even less for continuing releases.

# 5.9 SWMU 9: Dry Waste Pit (VSI Photos 5, 9, 10)

# 5.9.1 <u>Information Summary</u> [6, 13, 22, 25, 29]

Unit Description: This unit is RCRA regulated. The unit consists of an earthen pit which was created when the soils were removed for the unit's dikes. Based on topographical maps [22], the pit is approximately four feet deep. The southern end of the pit is located adjacent to a drainage channel.

The dry waste pit was used twice prior to 1980. The exact dates of processing are unknown. The fixed materials from the fixation process were placed in this unit.

During the time period between November 1981 and March 1982, materials from Ponds 1, 4, 2, and 3 (SWMUs 5 through 8, respectively) were also chemically processed to render them a Class II waste. These wastes were stored in the dry waste pit until May or June of 1982. During this time they were taken to a Class II landfill.

In late 1983, the fixed materials were added to a Class I waste (to dewater the waste) and the combined wastes were taken to a hazardous waste disposal site. The estimated total quantity of Chemfixed waste taken to Louisiana for disposal as a hazardous waste is 600 truckloads [13].

Dates of Operation: The unit was used two times prior to 1980. The exact dates of processing prior to 1980 are unknown; however, the start-up date is assumed to be 1972. The pit ceased operating in 1985.

The company has submitted a Closure Plan for the ponds (SWMUs 5, 6, 7, and 8) which included this unit, and removed wastes from this area [22].

Wastes Managed: Materials from the ponds (SWMUs 5 through 8) were chemically processed in this unit. In documents used to get the waste reclassifed as a Class II water-based sludge, the facility showed the Chemfix process to be 97% effective [25].

Release Controls: There are no release controls.

History of Releases: According to a 1984 Texas Department of Water Resources interoffice memorandum [13], "Removal of the Chemfixed material created the pit below ground water level. At the time of the inspection, the company was pumping the ground water collected in the pit into their surface impoundment."

# 5.9.2 Release Potential

Ground Water/Soils: This unit had a moderate potential for past releases to the ground water and soils because the unit was unlined, even though the fixation process was shown to be 97% effective. The potential for continuing releases is low because all wastes and contaminated soils have been removed during closure.

Surface Water: This unit had a moderate potential for past releases to surface water since the unit is located adjacent to a drainage channel. The potential for continuing releases is low since wastes and contaminated soils have been removed during closure.

<u>Air</u>: There was a moderate potential for release to the air since the process may have resulted in generation of fine particulates that were small enough to be carried by the winds of the area. The potential for continuing releases is low since all wastes and contaminated soils have been removed during closure.

Subsurface Gas: There was a low potential for past generation of subsurface gas due to the nature of the wastes being stored in the pit. The potential for continuing generation of subsurface gas is low since all wastes and contaminated soils have been removed during closure.

# 5.10 SWMU 10: Storage Trailer Area (VSI Photos 20, 21)

#### 5.10.1 Information Summary[29]

<u>Unit Description</u>: The VSI revealed that this unit is a typical truck dock which has a reinforced concrete pad. The pad appeared to be in good condition with no evidence of any cracks during the VSI. The storage trailer area is located at the southeast corner of the plant building.

Three (3) enclosed semi-trailers are kept at this area. Each trailer stores various wastes in 55-gallon drums. The trailers are stored for less than 90 days at this unit.

Dates of Operation: 1971 to present.

Wastes Managed: Three trailers containing different wastes are loaded and stored at this unit.

The first trailer is used to store mispunched or off-spec plastic battery casings. The casings stored are shipped for recycling to a Frisco, Texas, GNB smelter.

The second trailer is used to store drums of recyclable lead contaminated materials. The drums are sent back to the Frisco plant to be recycled. The contents of the drums vary from miscellaneous lead contaminated parts from within the plant (e.g. dust from the baghouses) to the filter cake from the wastewater filter press (SWMU 17). Miscellaneous rags and clothes, which are dipped in naphtha or acetone to clean the batteries before shipping, are also stored in the drums. This is the only place within the facility where volatile compounds are stored.

The third trailer is used to store whole junk batteries. The batteries are shipped to Frisco for recycling. All the batteries are shipped dry.

Release Controls: The unit consists of a reinforced concrete pad. There is no containment curbing surrounding the pad. Observations during the VSI indicated the concrete appeared to be in good condition and was free of cracks.

All three trailers appeared to be in good condition, and no signs of cracks or defects were observed. No leakage or spillage was observed around the trailers. Wastes were stored in 55-gallon drums. Drums that contained rags soaked with volatile solvents were closed. No free liquids in the drums were observed during the VSI.

<u>History of Releases</u>: There is no documented history of releases for this unit.

# 5.10.2 Release Potential

Ground Water/Soils: This unit has a low potential for releases to ground water and soils due to the types of wastes being handled and the reinforced concrete pad.

<u>Surface Water</u>: The storage area has a low potential for releases to surface water due to the way the wastes are handled and stored (e.g., contained in 55-gallon drums and placed in an enclosed trailer).

<u>Air</u>: The storage area has a low potential for releases to the air due to the types of wastes being stored.

Subsurface Gas: This unit has a low potential for subsurface gas generation due to the types of wastes stored and unit operation.

# 5.11 SWMU 11: Dumpster Area 1 (VSI Photo 11, 15, 16)

# 5.11.1 Information Summary

Unit Description: This unit is a plastic lined, 30-cubic yard dumpster that sits on a concrete pad. The dumster is located on the east side of the wastewater treatment building. The dumpster is adjacent to the east wall of the the building. The dumpster is under an aluminum lean-to which encloses the top and east side of the dumpster. The north and south ends of the lean-to are open for loading and unloading.

This unit stores waste for less than 90 days.

<u>Dates of Operation</u>: This unit started up in 1984 and is currently being used by the facility.

Wastes Managed: The sludge which was separated from the wastewater by a filter press from 1985 to 1986 was collected in this 30-cubic yard dumpster for off-site disposal at a Chemical Waste Management facility in Louisiana. Since the facility eliminated the off-site disposal by reprocessing the sludge, the dumpster has been used to store hazardous wastes generated within the plant. These wastes include gloves, clothes, pipes, etc. All the wastes stored in the dumpster are solid materials.

Release Controls: The dumpster is plastic lined and is situated on a concrete pad. The dumpster is under an aluminum lean-to which encloses the top and east side of the dumpster.

History of Releases: There is no documented history of releases from this unit.

#### 5.11.2 Release Potential

Ground Water/Soils: The potential release to ground water and soils is low due to the nature of the storage unit and the wastes being stored.

Surface Water: The potential release to surface water is low due to the nature and design of the storage unit.

Air: There is a low potential for release to the air from the dumpster due to the nature of the wastes being stored and the structural design of the dumpster.

Subsurface Gas: There is a low potential for generation of subsurface gas due to the nature of the wastes being stored and the structural design of the unit.

# 5.12 SWMU 12: Dumpster Area 2 (VSI Photo 17)

#### 5.12.1 Information Summary

<u>Unit Description</u>: This dumpster is used to store broken pallets and other non-hazardous wood refuse. It is located in a concrete paved area to the east of the plant near the cap/vent storage area.

Dates of Operation: 1971 to present.

<u>Wastes Managed</u>: This unit stores broken pallets and other non-hazardous wood refuse.

Release Controls: The dumpster is located on a concrete paved area.

<u>History of Releases</u>: There is no documented history of releases for this unit.

#### 5.12.2 Release Potential

Ground Water/Soils: The dumpster presents a low potential for releases to ground water and soils due to its design, location, and the types of wastes being stored.

<u>Surface Water</u>: The dumpster presents a low potential for releases to surface water due to its design, location, and the types of wastes being stored.

<u>Air</u>: The dumpster presents a low potential for air releases due to the nature of the wastes being stored (e.g., wood pallets).

Subsurface Gas: The dumpster has a low potential for subsurface gas generation due to the nature of the wastes being stored (e.g., wood pallets).

# 5.13 SWMU (15) Dumpster Area 3 (VSI Photo 19)

# 5.13.1 Information Summary

Unit Description: This dumpster is used to store miscellaneous office and plant trash. All the trash stored within the dumpster is non-hazardous, and the dumpster is enclosed. The dumpster is directly connected to a trash compactor and is situated upon a concrete paved pad. The dumpster is located on the south side of the plant west of the shipping area. During the VSI, some black stains were noted on the concrete near the head of the dumpster, but these stains appeared to be simply those associated with a normal dumpster handling office materials.

Dates of Operation: 1971 to present.

<u>Wastes Managed</u>: General facility wastes (e.g., lunch room and office wastes) which are non-hazardous.

Release Controls: The area has a reinforced concrete pad.

History of Releases: There are no documented history of releases for this unit. However, during the VSI, some black stains were noted on the concrete near the head of the dumpster, but these stains appeared to be simply those associated with a normal dumpster handling office materials.

# 5.13.2 Release Potential

Ground Water/Soils: This area has a low potential for releases to ground water and soils due to the concrete pad and the types of wastes being stored (e.g., non-hazardous office and plant trash).

Surface Water: This area has a low potential for releases to surface water due to the concrete paved area and the types of wastes being stored (e.g., non-hazardous office and plant trash).

Air: This area has a low potential for air releases due to the enclosed dumpster and the types of wastes being stored (e.g., non-hazardous plant and office trash).

Subsurface Gas: This area has a low potential for generating subsurface gas due to its design and the types of wastes being stored (e.g., non-hazardous plant and office trash).

#### 5.14 SWMU 14: Baghouse 1 (casting) (VSI Photo 22)

#### 5.14.1 Information Summary

<u>Unit Description</u>: This baghouse is located outside at the northwest corner of the plant building. The baghouse abuts the west wall of the building. This unit collects the miscellaneous dusts produced during the casting process of battery manufacture. It is approximately 25 feet high and is situated on a 12-foot by 12-foot pad. The casting dust collects in a 55-gallon drum at the base of the baghouse which is stored in a trailer at the storage trailer area (SWMU 10) before being shipped to the smelter in Frisco for recycling. During the VSI there were no signs of any releases from the baghouse. The area around the baghouse is covered with concrete.

Dates of Operation: 1984 to present.

<u>Wastes Managed</u>: Miscellaneous dusts produced during the casting process of battery manufacture which are considered D008 (lead) waste.

Release Controls: The unit's design and operation procedures.

<u>History of Releases</u>: There is no documented history of releases for this unit.

# 5.14.2 Release Potential

Ground Water/Soils: This unit has a low potential for releases to ground water and soils since the area around the baghouse is covered with concrete, and the baghouse showed no signs of any releases.

Surface Water: This unit has a low potential for releases to surface water since the area around the baghouse is covered with concrete, and the baghouse showed no signs of any releases.

Air: This unit has a moderate potential for releases due to the type of unit operation. The release potential would be high in the event the unit should develop leaks or suffer structural damage which could cause an air release of lead particulates.

Subsurface Gas: This unit has a low potential for generation of subsurface gas due to the design of the unit and the types of wastes being handled (e.g., non-volatile lead contaminated dusts with no organics).

#### 5.15 SWMU 15: Baghouse 2 (vacuum)

#### 5.15.1 Information Summary

Unit Description: This unit is located within the facility plant, and is fed by various hand vacuums located along the battery assembly line. The unit contains a 55-gallon, plastic-lined drum which is stored in a trailer at the storage trailer area (SWMU 10) before being sent to the Frisco plant smelter for recycling.

Dates of Operation: 1971 to present.

Wastes Managed: D008 (lead) dust.

Release Controls: The unit's design and operation procedures.

History of Releases: There is no documented history of releases for this unit. The VSI discovered no signs of releases.

## 5.15.2 Release Potential

Ground Water/Soils: This unit has a low potential for releases to ground water and soils due to its design and location.

Surface Water: This unit has a low potential for releases to surface water due to its design and location.

Air: This unit has a low potential for air releases due to its design.

Subsurface Gas: This unit has a low potential for generation of subsurface gas due to its location (e.g., inside the plant), and the types of wastes being handled (e.g., lead dust with no organics).

#### 5.16 SWMU 16: Baghouse 3 (assembly)

#### 5.16.1 Information Summary

Unit Description: This unit is fed by the various overhead ducts along the battery manufacturing assembly line. The unit is very similar to SWMU 15. It contains a 55-gallon, plastic-lined drum which is stored in a trailer at the storage trailer area (SWMU 10) before being sent to the Frisco smelter for recycling. The VSI did not discover any signs of releases or leaks in the unit.

Dates of Operation: 1971 to present.

Wastes Managed: D008 (lead) dust.

Release Controls: The unit's design and operation procedures.

History of Releases: There is no documented history of releases for this unit. The VSI discovered no signs of releases.

#### 5.16.2 Release Potential

Ground Water/Soils: This unit has a low potential for releases to ground water and soils due to its design and location.

<u>Surface Water</u>: This unit has a low potential for releases to surface water due to its design and location.

Air: This unit has a low potential for air releases due to its design.

Subsurface Gas: This unit has a low potential for generation of subsurface gas due to its location (e.g., inside the plant), and the types of wastes being handled (e.g., lead dust with no organics).

NOTE: In addition to the baghouses listed above, there is a baghouse which is part of the pasting process operation. This baghouse collects the miscellaneous dusts produced during this process and feeds them directly back into the assembly system. This unit was not viewed during the VSI. Due to the fact that the unit is truly a process unit rather than a SWMU, it was not included in the above listing of SWMUs. Since the baghouse is part of the process, and is inside the plant, it has a very low potential for release to any medium.

#### 5.17 SWMU 17: Indoor Wastewater Treatment (WWT)

# 5.17.1 Information Summary[29]

<u>Unit Description</u>: Facility personnel were reluctant to discuss this unit during the VSI. This unit has a patent pending according to facility personnel.

The wastewaters that feed this unit originate from the 5,000-gallon tank that is contained by the first neutralization pit (SWMU 3). The wastewaters flow from the 5,000-gallon tank to this unit by an encased (secondary containment), underground pipeline. Once the pipe line enters the plant, it is brought above ground. The wastewater then undergoes the several step wastewater treatment process. The sludge that is generated from the process is fed to a filter press for dewatering. The resulting solids are sent to a smelter in Frisco, Texas for reprocessing. The effluent can be recirculated to the process or discharged to the public owned treatment works (POTW).

Dates of Operation: March ,1986 to present.

<u>Wastes Managed</u>: Wastewater containing EP toxic levels of lead (D008) from the battery manufacturing process.

Release Controls: The unit's design and operation procedures, and the unit's location inside the plant building.

<u>History of Releases</u>: There is no documented history of releases from this unit.

#### 5.17.2 Release Potential

Ground Water/Soils: This unit has a low potential for releases to ground water and soils due to the unit's design and location.

Surface Water: This unit has a low potential for releases to surface water due to the unit's design and location.

<u>Air</u>: There is a low potential for releases to air due to the types of wastes handled by the unit.

Subsurface Gas: There is a low potential for subsurface gas generation due to the types of wastes handled by the unit.

#### 6.0 AREAS OF CONCERN

This section of the PR/VSI report describes seven areas of concern (AOCs) that were identified during the PR and were observed during the VSI.

#### 6.1 Low Area (East) [9, 24]

There are low areas to the east and west of the pond/pit area of the facility. These areas are labeled as being dry on some maps and as lakes on others. The areas are presumably retention basins which collect rainwater. Based on topographical maps of the facility [24], the east low area is approximately seven feet below the top of the ponds. The on-site drainage channel would prevent overflow from the ponds from reaching this area, but any spills or leaks from the eastern part of the facility would have a good chance of collecting in this area. The area could contain lead, and as such is included as an area of concern. However, the VSI did not discover any signs of contamination or releases (stressed vegetation, stained soils, etc.).

# 6.2 Low Area (West) [9, 24]

There is also a low area to the west of the pond/pit area. However, based on topographical maps of the facility [24], any overflow from the ponds would be intercepted by the dry waste pit and could not directly reach this area. The area still could receive overflow if the dry waste pits filled up (they are only four feet deep) and discharged into the low area. The area could also receive wastes from the western part of the plant if an undiscovered release has occurred. For this reason, the area could contain lead. Therefore, the low area is included as an area of concern. However, the VSI did not discover any signs of contamination or releases (stressed vegetation, stained soils, etc.).

# 6.3 Drainage Channel (off-site) [9, 24]

There is a drainage channel located just south of the company border in close proximity to the facility ponds. The prior owners of the facility (Morton Foods) had built a 2' concrete main which connected at least some of the settling ponds with this channel to prevent overflow when the ponds were in operation. This main was plugged by Gould when they bought the plant, but if it wasn't completely plugged or developed leaks, could have presented a direct connection between the settling ponds and the drainage channel. It is also known that the

facility did not maintain the required 2' of freeboard in the ponds [13], and based on topographic maps [24], any overflow from the ponds would flow directly into the drainage channel. Any water being discharged into this channel would have contained high quantities of lead resulting from the neutralization of wastewaters from battery manufacturing. However, the VSI did not note any signs of contamination or releases (stained soils, stressed vegetation, etc.).

## 6.4 Ponds (A-D) [2, 17, 24]

A map of ground water contours by Professional Service Industries, Inc. (17) shows four more areas of concern. These areas are labeled as Ponds A, B, C, and D in Figure 8 of their report. During the VSI these areas were dry, and it is assumed that they are simply low areas (probably left over from the mining in the area) which collect rainwater when it storms. These low areas could collect any undetected spills or releases. Therefore, they present areas of possible concern. However, the VSI did not discover any signs which would indicate any contamination (stressed vegetation, stained soils, etc.).

# 6.5 Drainage Channel (on-site) [13, 29]

There is a drainage channel located just to the east of the plant building which runs basically north/south and eventually connects with the off-site drainage channel. This ditch would collect any overflow or spills from much of the facility grounds and could contain high quantities of lead if any undetected spills or leaks have occurred. The channel would have collected wastes from the ponds if the ponds had ever overflowed. It is known that the facility did not maintain the required 2' of freeboard when the ponds were in operation [13], so overflow may have occurred. The VSI did not discover any signs which would indicate that contamination has occurred (stressed vegetation, stained soils, etc.).

# 6.6 Acid Spill Area [6]

On November 3, 1980, a pipe to an acid storage tank broke and overflowed the containment area. The overflow collected in a lagoon left by surface mining. The acid spill was neutralized in the lagoon and pumped to the treatment ponds. Soil tests were taken after the treatment was completed to verify the clean-up procedure. These results were provided to the State. No further action was deemed necessary by the facility, and the State required no further action. The estimated quantity of the spill was 7,880 gallons.

# 6.7 Hose Break Area [6]

A hose break occurred on the pump moving liquid from the ponds to the sanitary sewer during dike refurbishing on April 26, 1984. The quantity of liquid lost was reported to be less than 150 gallons. Analyses (two samples) of the liquid lost showed the pH was in the range of 8.9 to 9.4, and the lead ranged from .19 to .21 ppm. No corrective action was deemed necessary by the facility or required by the State.

#### 7.0 CONCLUSIONS AND RECOMMENDATIONS

This section of the PR/VSI report provides suggested further actions and their reasons for each of the Solid Waste Management Units (SWMUs). Suggested actions and reasons are also provided for the Areas of Concern (AOCs).

#### 7.1 SWMU 1: Wastewater Pipe

Suggested Further Action: The EPA should consider requiring GNB to develop an alternate transfer system. One option could be to install a new pipeline constructed of materials better suited to carry this type of waste stream. The facility should also consider an above ground construction. The area surrounding the existing pipeline should be examined for potential contamination from leaking wastewaters. These items should be addressed as part of an RFI.

Reasons: The design of the pipeline leading from the plant is such that leakage is highly probable. It is constructed of clay, bell and spigot tile. In 1984, a section of the pipe was exposed in an excavation and found to be cracked and a feeder line improperly sealed.

# 7.2 SWMU 2: Truck Wash Sump

Suggested Further Action: No further action should be taken at this time. Periodic inspections of the unit should be conducted by GNB to check for integrity loss of the walls, seams, and connections.

Reasons: The nature of the unit construction and the amount and concentration of the wastes handled are the basis for these recommendations.

#### 7.3 First Neutralization Pit/Tank

<u>Suggested Further Action</u>: No further action is suggested for this unit.

Reasons: The pit is no longer used to hold waste materials. There are no previous indications of past releases. VSI observations indicated that the pit appeared in sound condition. The pit is presently not being used and is only serving as a secondary containment for the polypropylene mixing tank. The tank appeared to be of sound construction.

# 7.4 Second Neutralization Pit/Tank

<u>Suggested Further Action</u>: No further action is suggested for this unit.

Reasons: The pit is no longer used to hold waste materials. There are no previous indications of past releases. VSI observations indicated that the pit appeared in sound condition. The pit is presently not being used and is only serving as a secondary containment for the polypropylene mixing tank. The tank appeared to be of sound construction.

#### 7.5 SWMU 5: Pond 1

Suggested Further Action: No further action is suggested for this SWMU at this time.

Reasons: The pond is RCRA regulated, and is currently undergoing closure. All wastes have been removed, and the soils have been tested for contamination. Once closure is completed and certified, there will be a low potential for releases to any medium.

# 7.6 SWMU 6: Pond 4

<u>Suggested Further Action</u>: No further action is suggested for this SWMU at this time.

Reasons: The pond is RCRA regulated, and is currently undergoing closure. All wastes have been removed, and the soils have been tested for contamination. Once closure is completed and certified, there will be a low potential for releases to any medium.

## 7.7 SWMU 7: Pond 2

Suggested Further Action: No further action is suggested for this SWMU at this time.

Reasons: The pond is RCRA regulated, and is currently undergoing closure. All wastes have been removed, and the soils have been tested for contamination. Once closure is completed and certified, there will be a low potential for releases to any medium.

#### 7.8 SWMU 8: Pond 3

<u>Suggested Further Action</u>: No further action is suggested for this SWMU at this time.

Reasons: The pond is RCRA regulated, and is currently undergoing closure. All wastes have been removed, and the soils have been tested for contamination. Once closure is completed and certified, there will be a low potential for releases to any medium.

# 7.9 SWMU 9: Dry Waste Pit

Suggested Further Action: No further action is suggested for this unit at this time.

Reasons: The Dry Waste Pit is included in the closure plan for the ponds. All wastes have been removed and the soils have been tested for contamination. Once closure is completed and certified, there will be a low potential for releases to any medium.

# 7.10 SWMU 10: Storage Trailer Area

Suggested Further Action: No further action is suggested for this unit at this time. Periodic inspections by GNB are suggested to insure that the trailers do not develop leaks, and the pad is in good condition.

Reasons: The waste materials are enclosed in truck trailers and certain materials (e.g., dust from baghouses, filter cake) are containerized in 55-gallon drums. The area is paved and appeared to be in good condition during the VSI.

#### 7.11 SWMU 11: Dumpster Area 1

Suggested Further Action: No further action is suggested for this unit at this time.

Reasons: The area is paved and protected by a lean-to shed. The dumpster was properly labeled and lined during the VSI.

#### 7.12 SWMU 12: Dumpster Area 2

Suggested Further Action: No further action is suggested for this unit at this time.

Reasons: Only non-hazardous waste materials (wood pallets) were disposed of in this unit. The area is paved.

## 7.13 SWMU 13: Dumpster Area 3

Suggested Further Action: No further action is suggested for this unit at this time.

Reasons: The area is used for the disposal of office and lunchroom wastes. These materials are non-hazardous. The dumpster is connected to a compactor and is, therefore, enclosed.

# 7.14 SWMU 14: Baghouse 1 (casting)

<u>Suggested Further Action</u>: No further action is suggested for this unit at this time. Periodic inspections will insure that this unit continues to operate without fugitive emissions to the workplace.

Reasons: The unit is located outside the facility building. The area is paved. There is no history of operational problems with this unit.

# 7.15 SWMU 15: Baghouse 2 (vacuum)

<u>Suggested Further Action</u>: No further action is suggested for this unit at this time. periodic inspections will insure that this unit continues to operate without fugitive emissions to the workplace.

Reasons: The unit is located inside the facility building. The floors are all concrete. All floor drains are connected to the WWT system.

#### 7.16 SWMU 16: Baghouse 3 (assembly)

Suggested Further Action: No further action is suggested for this unit at this time. Periodic inspections will insure that this unit continues to operate without fugitive emissions to the workplace.

Reasons: The unit is located inside the facility building. The floors are all concrete. All floor drains are connected to the WWT system.

# 7.17 SWMU 17: Indoor WWT

<u>Suggested Further Action</u>: No further actions recommended at this time. (Knowledge of process information is limited due to facility involvement with patent acquisition.)

Reasons: Outfall of excess treated wastewater to POTW is monitored. Other waters are recirculated back into plant processes. Leakage or spills within the plant would be collected by floor drains and routed back through the WWT system.

# 7.18 AOC: Low Area (east)

Suggested Further Action: No further action is suggested at this time.

Reasons: There is no evidence of contamination of this area. The major source of potential contamination has been removed (Ponds and Dry Waste Pit).

# 7.19 AOC: Low Area (west)

Suggested Further Action: No further action is suggested at this time.

Reasons: There is no evidence of contamination of this area. The major source of potential contamination has been removed (Ponds 1-4 and Dry Waste Pit).

# 7.20 AOC: Off-site Drainage Ditch

Suggested Further Action: No further action is suggested at this time.

Reasons: The ditch will have little potential for contamination from the facility based on the closure of Ponds 1-4 and the Dry Waste Pit.

# 7.21 AOC: Ponds A-D

Suggested Further Action: No Further action is suggested at this time.

Reasons: These areas are remanents of mining activities and were never associated with facility processes.

#### 7.22 AOC: Acid Spill Area

Suggested Further Action: No further action is suggested at this time.

Reasons: The spill was cleaned-up at the time of occurrence. A report and data were supplied to the State. The State did not proceed with any action.

# ENFORCEMENT SENSITIVE Page 7 of 7

# 7.23 AOC: Hose Break Area

Suggested Further Action: No further action is suggested at this time.

Reasons: The amount of material released was small (150 gallons) and the situation was adequately addressed at that time.

#### 8.0 REFERENCES

- 1. Texas Department of Water Resources. Interoffice Memorandum from Christopher Swan, Environmental Quality Specialist, District 4, to Bryan Dixon, P.E., Chief, Solid Waste and Spill Response Section, May 29, 1985.
- 2. Texas Water Commission. Comprehensive GW Monitoring Evaluation (CME) Report, GNB Batteries, Inc., Farmers Branch, Texas, May 23, 1986.
- 3. GNB Incorporated, Automotive Battery Division. Letter from E. C. Milton, Manager, Environmental Engineering, to Allan Seils, Texas Water Commission, Technical Support Unit, April 9, 1987.
- 4. United States Environmental Agency, Region VI. Letter from David Cohen, Attorney, Office of Regional Counsel, to Robert Wilson, Esq., McGinnis, Lockridge & Kilgore, July 30, 1985.
- 5. GNB Incorporated. Hazardous Waste Management Plan, Volume II, Section II (All Locations), Sampling and Testing Manual, April 1, 1984.
- 6. GNB Batteries Incorporated, Automotive Battery Division. Hazardous Waste Management Plan, Volume II, Section II (Farmers Branch, Texas), Operating Record, January 11, 1984.
- 7. Environmental Protection Agency. Notification of Hazardous Waste Activity, Gould Inc., August 14, 1980.
- 8. Texas Department Of Water Resources. Interoffice Memorandum from Charles D. Gill, P.E., Supervisor, District 4, to Gary D. Schroeder, P.E., Chief, Solid Waste and Spill Response Section, November 9, 1982.
- 9. Texas Department Of Water Resources. Interoffice Memorandum from Don C. Eubank, Environmental Quality Specialist, District 4, to Gary D. Schroeder, P.E., Chief, Solid Waste and Spill Response Section, September 27, 1983.
- 10. GNB Incorporated. Hazardous Waste Management Plan, Volume II, Section II (Frisco, Texas) Appendix E Exhibit 6 Closure Plan, April 1, 1984.
- 11. GNB Inc., Automotive Battery Division. Memorandum from E. C. Milton, Manager, Facilities Engineering, to Texas Hazardous Waste Management File, Report. Vol. II, Sec. II, Appendix C, Exhibit 1, Subject: Incident/Spill Report January 21, 1984.

- 12. GNB Inc., Automotive Battery Division. Letter (Certified Mail P291 847 615) from E. C. Milton, Manager, Facilities Engineering to Mr. Charles E. Nemir, Executive Director, Texas Department of Water Resources, October 22, 1985.
- 13. Texas Department of Water Resources. Interoffice Memorandum from Jenny Gredell Menard, Environmental Quality Specialist, District 4, to Bryan Dixon, Acting Section Chief, Solid Waste and Spill Response Section, April 20, 1984.
- 14. GNB Inc. Office Memorandum from D. W. Groff, to E.C. Milton, Manager, Facilities Engineering, Subject: Neutralization Sump Liner at Dallas, March 30, 1984.
- 15. Waste Management, Inc. Generator's Waste Material Profile Report (Generator: GNB Batteries, Inc.), June 26, 1984.
- 16. Texas Water Commission. Letter to E. C. Milton of GNB from Bryan W. Dixon, May 22, 1986. Facility says this letter was never received.
- 17. Professional Service Industries, Inc., National Soil Services Division. Groundwater Elevations Report, GNB Batteries, Inc., Farmers Branch, Texas, November, 1984.
- 18. United States Department of Agriculture, Soil Conservation Service in cooperation with Texas Agricultural Experiment Station, soil survey of Dallas County, Texas.
- 19. Telephone call between Dr. Mittelhauser of Mittelhauser Corp. and David Maiefski of EPA Region VI, July 7, 1987.
- 20. Telephone call between Dr. Mittelhauser of Mittelhauser Corp. and Charles Mauk of the Texas Water Commission, July 7, 1987.
- 21. Telephone call between Dr. Mittelhauser of Mittelhauser Corp. and Bill Backus of GNB Incorporated, July 9, 1987.
- 22. Closure (and Post-Closure) Plan (for Surface Impoundments), originally dated January 11, 1984, last modified March 14, 1986. Prepared by GNB Incorporated.
- 23. County and City Data Book 1983, U.S. Department of Commerce, Bureau of the Census (updated every 5 years).
- 24. USGS map of the Carrollton Quadrangle, Texas. 7.5 minute series (topographic). 1959, photorevised in 1981.

- 25. GNB Incorporated, November 4, 1984. Hazardous Waste Management Plan, Volume IV, Section III, Subsection 6: Analysis for reclassification of Chemfixed waste at Farmers Branch facility.
  - 26. Telephone log of conversation between Jeff Leifer of Mittelhauser Corporation and Nola Bauer, Secretary for Utilities, City of Farmers Branch, Utilities Department.
  - 27. Telephone log of conversation between Jeff Leifer of Mittelhauser Corporation and Steve Lindley, Public Information Representative, Dallas Water Utilities.
  - 28. Groundwater monitoring results provided to Mittelhauser Corporation on August 6, 1987 by E.C. Milton of GNB Incorporated. Information provided by GNB included individual papers of reports submitted to the Texas Department of Water Resources.
  - 29. Visual Site Inspection of July 17, 1987.
  - 30. Telephone conversation between Dr. Mittelhauser of Mittelhauser Corporation, and Everett C. Milton of GNB, August 25, 1987.

# PA-SCORE REFERENCE 2

TYPE:

Telephone Call

DATE:

2/4/93

TIME:

3905

1035

TO:

William Backus, Environmental Engineer, GNB, Inc. (214) 243-

FROM:

B. Kendrick, Geologist, ICF

Technology, Inc. (214) 979-

1011

SUBJECT: Additional Information Concerning GNB, Inc.

#### **SUMMARY OF COMMUNICATION:**

Mr. Backus stated that GNB owns a total of 43 acres for the plant located in Farmers Branch. He also stated that the actual facility covers 10 acres.

Mr. Backus stated that there are an average of 340 workers at the facility.

The facility is completely fenced with an on-duty guard 24 hours a day. The area where the impoundments were located is not currently fenced, but was fenced during their operation.

Mr. Backus stated that a letter of clean closure for the impoundments has not been received from either the Texas Water Commission (TWC) or from the EPA. He also stated that GNB is in the final stages of closure of the impoundments which would meet certification under TWC and EPA regulations.

# PA-SCORE REFERENCE 3



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VI 1445 ROSS AVENUE, SUITE 1200 DALLAS, TEXAS 75202

October 14, 1988

#### MEMORANDUM

SUBJECT: Transmittal of RCRA Facility Assessment Evaluation

FROM:

Bill Luthans

Technical Section (6H-CT)

TO:

William K. Honker, Chief Permits Section (6H-CP)

renaits section (on-cr)

Attached please find a copy of the following RCRA Facility Assessment Evaluation:

° Facility Name: GNB Incorporated

° EPA ID Number: TROOTS

Please advise us if more information is required and/or if you need further assistance.

Attachment

cc: Sam Becker (6H-C)

## RCRA FACILITY ASSESSMENT SUMMARY

## PRELIMINARY REVIEW AND VISUAL SITE INSPECTION

Region VI, Technical Compliance Section

FACILITY'S NAME(S): GNB Incorporated
EPA ID NUMBER: TXD007331879
ADDRESS: 1880 Valley View Lane, Farmers Branch, Texas 75234
LOCATION: 1.25 Miles West of I35E on Valley View Lane.
SITE DESCRIPTION: Automotive lead/acid storage battery manufacturing facility
DATE OF INSPECTION: July 17, 1987 VSI CONDUCTED BY: Mittelhauser Corp
A.T. Kearney, Inc./ PREPARED BY: Mittelhauser Corp. DATE PREPARED: 8/87 - 10/87
REVIEWED BY: Van R. Cammack DATE REVIEWED: 4/11/88 - 8/29/88
FACILITY STATUS: Operating - LD Closure CLOSURE PLAN APPROVED DATE: 12/1/87
ANY ON-GOING STATE/FED 264, 265, OR 270 CORRECTIVE ACTION OR CERCLA ACTION:
State issued compliance order in 1984 for groundwater assessment plan. Closure of Surface Impoundments (Ponds 1-4) and dry waste pit pending.
DOES FACILITY HAVE A CERCLA FILE? YES NO _X
DOES FACILITY HAVE UIC WELL? YES NO X
TYPE OF DRINKING WATER SUPPLY WITHIN A 3-MILE RADIUS:
Dallas, Texas; Surface Water Impoundments.
TARGET POPULATION WITHIN A 3-MILE RADIUS:
Within incorporated area of Farmers Branch having population of about 25000.
RECOMMENDATIONS: X R.F.I. I.M. No Further Action under RFA
(Indicate only one unless I.M. is marked)
3004(u) 3007
Possible Enforcement Action: 3008(a) X 3008(h)

## I. EVALUATION

# A. NUMBER OF SWMU(s)/AOC(s) INVESTIGATED DURING THE PR/VSI: 17 SWMUs + 7 AOCs

## 1. NUMBER OF SWMU(s) INVESTIGATED DURING PR/VSI: 17

	/	SWMU NO.	LIST OF SWMU(s)	REGULATED BY RCRA*	STATUS**
		1	Wastowaton Dino	(SUBTITLE C)	
	/	Ţ	Wastewater Pipe	IN	А
	/	2	Truck Wash Sump	N	Α ΄
	1	3	First Neutralization	Pit/Tank Y	Α
	(	4	Second Neutralization	Pit/Tank Y	Α
	/	5	Pond 1	Υ	С
		6	Pond 4	Υ	С
<b>A</b>		7	Pond 2	Y	С
MA		8	Pond 3	Υ	С
	/	9	Dry Waste Pit	Υ	C
	/	10	Storage Trailer Area	N	Α
	/	11	Dumpster Area 1	N	Α
	- [	12	Dumpster Area 2	N	Α.
	1	13	Dumpster Area 3	N	·A
		14	Baghouse 1 (Casting)	N -	Α
	1	15	Baghouse 2 (Vacuum)	N	Α
	\	16	Baghouse 3 (Assembly)	· N	Α
		17	Indoor WWT	N	Α

\*Y-Yes, N-No
\*\*Active, Inactive, Closed (A,I,&C)

#### 2. AREAS(s) OF CONCERN: 7

## LIST OF AOC(s):

AOC 1	Low Area (East)
AOC 2	Low Area (West)
AOC 3	Off-site Drainage Ditch
AOC 4	Ponds (A-D)
AOC 5	On-site Drainage Ditch
AOC 6	Acid Spill Area
AOC 7	Hose Break Area

#### B. SAMPLING VISIT - 7/20/87

SWMU OR AOC SAMPLING LOCATION	SAMPLE/MEDIA SAMPLE TYPE (GRAB.COMPOSITE)	PARAMETERS	Pb	RESULTS mg/kg Cd	Sulfates
AOC 5 - Onsite Drainage Ditch (D-1)	Soil/Grab	Pb,Cd,Sulfates	8650	6.1	8360
SWMU 9 Dry Waste Pit (WP-1)	Sediment/Composite	Pb,Cd,Sulfates	392	2.70	19700
SWMU 9 Dry Waste Pit (WP-2) Dup. of (WP-1)	Sediment/Composite	Pb,Cd,Sulfates	323	2 <b>.</b> 7U	9170
Background (BKG)	Soil/Grab	Pb,Cd,Sulfates	37	2.10	547
Equipment Blank	Water/Grab	Pb,Cd,Sulfates	5U	<b>4</b> U	3U

<sup>&</sup>quot;U" indicates element was analyzed for but not detected.

- C. NUMBER SWMU TO BE INCLUDED IN THE RFI: 1 SWMU + 1 AOC (Except RCRA units subject to Subpart F refer to Section D)
  - 1. NUMBER OF SWMU/AOC AT WHICH RELEASES HAVE BEEN IDENTIFIED: 1

AUC NU.	LIST OF SWMO	KELEASE TO	NUTED DUCUMENTATION OF RELEASE
5	Onsite Drainage Ditch	Soil/G.W.	Drainage channel just east of the plant building. Would collect overflow or spills from facility grounds. Soil sample taken during SV indicated high lead level (8650 mg/kg).

2. NUMBER OF SWMU AT WHICH A RELEASE IS HIGHLY POSSIBLE: 1

SWMU NO.	LIST OF SWMU	MEDIA	RATIONALE
1	Wastewater Pipe	Soil/G.W.	Clay tile drain line of bell & spigot design and buried under concrete. All facility flow drains empty into this line. Crack found in pipe 1/24/84 while installing a valve. No visible signs of release. Acidwater and DOO8 waste managed. Operated 1972-present.

3. NUMBER OF SWMU WHERE A DETERMINATION OF RELEASE CAN NOT BE MADE DUE TO LACK OF INFORMATION: 0

## D. NUMBER OF SWMU FOR WHICH AN RFI IS NOT RECOMMENDED: 9 SWMUs/6 AOCS

SWMU NO.	LIST OF SWMU	RATIONALE
2	Truck Wash Sump	Reinforced concrete collection sump catching washwater from truck trailers and plant maintenance. No visible signs of release. Unit in good condition.
10	Storage Trailer Area	Reinforced concrete pad used as truck dock, good condition, no evidence of cracks. Three semitrailers for storing mispunched plastic battery casings, drums of recyclable lead materials, junk batteries. No visible signs of releases.
11	Dumpster Area 1	Plastic lined, 30-cubic yard dumpster on concrete pad, under aluminum lean-to. Stores hazardous waste from within plant such as gloves clothing, pipes. Stored less than 90 days. No documented releases.
12	Dumpster Area 2	Dumpster sets on concrete paved area. Stores non-hazardous, broken-wood refuse. No documented releases.
13	Dumpster Area 3	Dumpster sets on reinforced concrete pad. Stores non-hazardous office waste after compaction.
14	Baghouse 1	Baghouse standing about 25' high mounted on steel legs. Collects dust produced during casting process of battery manufacture. Dust contains lead (DOO8). No history of releases.
15	Baghouse 2	Baghouse located inside facility building on concrete floor. Fed by various hand vacuums along assembly line. Dust classified D008 wastes. No documented releases.
16	Baghouse 3	Baghouse located inside facility building. Concerns same as Baghouse 2 (SWMU 15).

		5	
	SWMU NO.	LIST OF SWMU	RATIONALE
	17	Indoor Wastewater Treatment (WWT)	Unit sets inside plant building. Receives effluent from first neutralization tank (SWMU 3) via underground pipe (Encased). Patent pending and personnel would not discuss unit. No documented releases.
	AOC 1	Low Area (East)	Retention basin (presumably) to catch rainwater. Lower than facility impoundments and could catch spills or leaks from Eastern part of facility. No signs of contamination or releases.
	AOC 2	Low Area (West)	Low area West of facility that could catch water from facility if dry waste pit ever overflowed from flooding. No signs of contamination or releases.
	AOC 3	Offsite Drainage Ditch	Drainage channel just south of company border, near facility ponds. Pond overflow could release D008 waste to ditch. No indications of releases.
	AOC 4	Ponds (A-D)	Low areas left over from sand & gravel mining in area. Never associated with facility processes.
·	AOC 6	Acid Spill Area	Lagoon left by surface mining. Caught overflow from acid spill from break in storage Tank on 11/3/80. Spill was neutralized. Soil samples sent to State. No further action required by State.
	AOC 7	Hose Break Area	Hose broke 4/26/84 while moving liquid from ponds to sanitary sewer. About 150 gal lost, having pH in range 8.9 - 9.4 and lead of 0.19 - 0.21 ppm. No action taken.

E. SUPPLEMENTAL INFORMATION ON RCRA REGULATED UNITS: 7
(Describe any problems identified or suspected from regulated units including identified releases to groundwater)

	including identified releases to	groundwater)
SWMU NO.	LIST OF SWMU	CONCERNS
3	First Neutralization Pit/Tank	This is a concrete pit, partially underground, which received wastewaters from plant floor, truck drain and plant process prior to May 1985 when a polypropelene tank was installed inside the pit. The pit now serves as secondary containment. Wastes are treated with CaCO <sub>3</sub> for neutralization. Pit operated from 1972-1985, Tank since then. Pit and Tank appear to be in good condition. No releases have occurred.
4	Second Neutralization Pit/Tank	Receives effluent from first Pit/Tank and discharges into Pond system. Otherwise same as first Pit/Tank. No releases have occurred.
5	Pond 1	One of four unlined surface impoundments. About 135'x 89'x 12' deep. Received neutralized acid water from second Pit (SWMU 4). Solids settled in Pond 1. Contaminants included calcium sulfate and lead. A bentonite slurry wall surrounding all four Pits was installed in May

1976. High sulfate and lead levels were detected in monitoring wells outside the wall in 1982. Monitoring in 1986 & 1987 did not indicate lead contamination but high sulfates were still present with no apparant decrease indicated. No releases have been reported. Use of the pond was terminated in May 1985. Materials were removed to a depth sufficient to attain background levels of contaminating substances, refilled with clean soils and revegetated. The facility has been trying to clean closed this unit at this time, GNB has submitted the closure certification to TWC.

SWMU_NO.	LIST OF SWMU	CONCERNS
6	Pond 4	Unlined surface impoundment about 126'x 50'x 12' deep. Hydraulically connected with Pond 1 via permeable dike. Not used since May 1985. Concerns and closure process same as pond 1 (SWMU 5).
7	Pond 2	Unlined surface impoundment 140'x 105'x 12' deep. Hydraulically connected with Pond 3 via permeable dike. Received effluent from second Pit (SWMU 4). See concerns for Pond 1 (SWMU 5). Not used since May 1985. Concerns and closure process same as pond 1 (SWMU 5).
.8	Pond 3	Unlined surface impoundment 131'x 48'x 12' deep. Hydraulically connected with Pond 2 (SWMU 7) via permeable dike. Not used since May 1985. Concerns same as Pond 1 (SWMU 5).
9	Dry Waste Pit	Unlined, earthern pit about 4' deep. Class II waste stored and later moved. Pit ceased operation in 1985. Closure is pending. Soil samples indicate high lead concentration. See sampling visit (Section C, this report). Pit closed in same manner and process as Pond 1 (SWMU 5).

## II. FINDINGS

A. RECOMMENDATIONS: (EPA, STATE and/or CONTRACTOR)

**EPA** recommends the following units be included in an RFI:

SWMU No. 1 Wastewater Pipe

AOC 5 - On-site Drainage Ditch

#### Contractor

The contractor recommends that EPA consider requiring GNB, Inc., to develop an alternate transfer system to replace the wastewater pipe (SWMU 1) with pipeline constructed of more suitable material. They recommend additional information on SWMUs 5,6,7 & 8 (Ponds 1-4) be submitted by GNB to confirm that contaminated materials have been removed and further that additional soil samples be taken on SWMU 9 (Dry Waste Pit) and AOC 5 (On-Site Drainage Ditch) to determine further action. However, since contractor's report was received, it was learned by phone conversation with Richard Clark, TWC, Ducanville, TX., that SWMUs 5, 6, 7, 8, & 9 seems to be clean closing under State authority. Waste material and soil was removed to a depth sufficient to attain background levels of contaminants, units were then filled with clean soil and revegetated.

#### B. ADDITIONAL COMMENTS:

This facility was originally used by Morton Foods in manufacturing and packaging pickled food products. Gould, Inc., purchased the facility in 1971 for manufacturing batteries and sold it to GNB, Inc., in 1984 who continued to use it for battery manufacture. The primary contaminants in the process are acid and lead. The facility contained four unlined surface impoundments and a dry waste pile that was used until May 1985. The impoundments received neutralized wastewater containing high levels of sulfate and lead.

The impoundments began operation on May 15, 1972. Ponds 1 and 2 received treated wastewater from the neutralization pits. Solids were allowed to settle and wastewater flowed into Ponds 3 and 4 and on into the sanitary sewer. Sludge was removed from ponds 1 and 2, chemically fixed and stored in the Dry Waste Pit until 1982 and eventually shipped offsite for disposal. A slurry wall was placed around the impoundments in May 1976. However, its integrity is questionable since a compliance order was issued by the State in 1984 requiring development of a groundwater assessment plan because monitoring via five monitoring wells outside the wall had indicated 0.09 and 0.15 mg/l of lead and sulfate in 1982. High lead was no longer indicated by monitoring in 1986 and 1987 but sulfate remained high with no apparent decline.

Groundwater flow direction is to the southeast and extensive surface mining of sand and gravel has occurred to the South. It is therefore possible that contaminated water could cause seeps and springs in the area.

To address these and perhaps other issues, the facility is trying to close the ponds and the pit (SWMUs 5-9) under State authority. The units were excavated to a depth sufficient to remove all contamination to a background level, filled with clean soil and revegetated. The closure process has been completed and certified by the facility according to Richard Clark, TWC. Duncanville, TX.

CONCUR: Lydia M. Boada-Clista DATE: 10/7/88

# PA-SCORE REFERENCE 4

IEXAS DEPARTMENT OF WATER RESOURCES  Industrial Solid Waste Disposal Compliance Monitoring Inspection
Inspection Cover Sheet (see reverse side for checklist use and general instructions)
Compliant Texas Permit/Reg. No. 31691
Noncompliant EPA I.D. No. TXDCX713318
Site Operator Information:
Name of Company Gould, Inc. (GNB Bodteries, Inc.)
Company's Address 1880 Valley Vew Love, Farmers Branch, Texas 75
Phone No. (219) 293 · 101
Site Address <u>See above</u>
Phone No. see above County Dailas
Type of Industry manufacture batteries
Indicate below Classes of Waste managed (Hazardous-H, Class I nonhazardous-NH, Class II-I
Generator H, II Transporter Small Quantity Generator
Treatment H Disposal Storage H; 90 Day Exemption
Site Information (T.S.D. facilities only)
1. Are facilities located outside the 100 year flood plain area?
2. Describe land use within one mile industrial
3. Closed or abandoned facilities <u>none</u>
Inspection Information:
1. Inspector's Name & Title Jenny Gredell, Formonomental Quality Specialis
2. Inspection Date February 29, 1984; April 11, 1984
3. Inspection Participants Hr. William Brickus, Mr. Everett Milton
Approved: Signed: Jinuy Diedell Mineral
Date:

# CONTENTS

, ac ,	iicy	Reg. # 31697
<u>\times</u>	1. 1 <i>6</i>	CM&E Code Sheet 0814 f Memo
	2.	Contents Sheet (if included)
$\checkmark$	3.	Major Group I Checklist or Non Major Checklist
_	4.	*Facility Checklists
		ሊ/A A. Landfills
		✓ B. Surface Impoundments
		N/A C. Land Treatment
		D. Tanks
		N/A E. Chemical, Physical, Biological Treatment
		N/A F. Waste Piles
•		N/A G. Incinerators
		N/A H. Thermal Treatment
$\sqrt{}$	5.	Closure and Post-Closure Compliance Review Checklist
** 	6.	Ground Water Monitoring Program Checklist
_	7.	Financial Assurance, Closure and Post Closure Worksheet
	8.	Major Facilities Status Sheet (Not Required for Non Majors)
N/A	9.	Generator/Facility/Transporter (GFT) Status (Not Required for Majors)
		* If a Required Checklist is Omitted, Explain Below:
		* Treatment occur in tamps (see Tanks checklist)
	<b>*</b>	* Groundwater manifering program is currently being
		- reviewed by Karen Thacker as part of a previous
		referral to flustin

# COMMITTANCE MONITORING INSPECTION RELIGIOR Generators Checklist

# Section A - Hazardous Waste Determination 335.6(e) and 335.62

			-		
1.	was	etermination has been made that the solid te(s) generated is either hazardous or non-ardous.	Yes 📈	No	
2.	If use	the answer to #1 is yes, check the method d for determination:			
	a.	Listed as a hazardous waste in Title 40 CFR Part 261, Subpart D			
	b.	Process or materials knowledge			
	c.	Tested for characteristics as identified in Title 40 CFR Part 261, Subpart C $\checkmark$ . (If equivalent test method used, attach a copy)			
3.	The tes	following wastes, if generated, have been ted to determine nonhazardous characteristics:		ò	
	a.	Class I nonhazardous	Yes	No	N/A <u>ر</u>
		Class II	Yes	No	N/A_
1	<u>.</u>	P( +storage)	Yes	No	N/A ✓
4 Sect	<u>see</u>	no, est a the comments sheet those wastes med what rdous or processes from which non-ard was produced.  Laste stream changes are lasted to or or random hazarous was ested.	Yes <u>/</u>	No	N/A
	Re	Been Hed was to	Yes	No	N/A
		Sign Solve Bill	Yes	No	N/A_
		d V se de 3	<u>Ses</u>	No	N/A <u></u>
				- 5 <del></del>	
	1 ed				

•				•		
Secti	ion C - Record Keeping and Reports 335.9 and 335.70-	·			• •	
1.	Generator maintains the required records and reports for 3 years.	,	Yes	No		
	At the facility	ute	copi	es no	et on-site ts not d	٢
	Elsewhere (note location in comments sheet)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	subn	nittee	d non	
2.			Yes 📈			
3.	Spills or unauthorized discharges are reported as required (335.453). delayed uporting	7	Yes	No 🗸	N/A	
	OT COMPLETE SECTION D IF GENERATOR DISPOSES OF HAZAR ON-SITE ONLY.	DOUS	AND/OR	NONHAZ#F	RDOUS	
Sect	ion D - Pretransport and Manifest Requirements 335.6	569				
1.	Identify primary off-site disposal facility(s). Use comments sheet or add registration waste list properly annotated.	i	:nilkS	s - Wa	ste 003	
2.	TDWR manifest shipping control ticket is properly completed.		Yes <u> </u>	No	N/A	
3.	Generator receives return (white) copy of shipping control ticket.		Yes	No 🗸	N/A	
4.	Generator is familiar with DOT packaging requirements identified in Title 49 CFR Parts 173, 178 and 179.		Yes_ <u>√</u>	No		
5.	Containers used to temporarily store waste before transport meet the DOT packaging requirements of Ti 49 CFR Parts 173, 178 and 179.	itle	Yes	No	N/A hu	į
6.	Generator labels and marks each package in accordance with Title 49 CFR Part 172.		Yes	No	N/A bu	<b>^</b> \ 1
7.	Each container of 110 gallons or less is marked with the required hazardous waste warning label.		Yes	No	N/A <u>,</u>	
8.	Hazardous wastes are accumulated for more than 90 days and the generator (is/vill be) a permitted storage facility.		Yes_ <b>√</b>	No	N/A	

No

No

Yes

TDWR-Page 2 of 10 of Group I

9. Generator inspects containers for leakage or corrosion at least weekly (335.245).

If leaking or bulging container is found,

operator transfers waste into a usable container properly lined not to react with the waste.

11.	Generator locates containers holding ignitable or reactive waste at least 15 meters (50 feet) from the facility's property line (335.246).	Yes	No	N/A_
12.	Containers holding incompatible wastes are kept apart by physical barrier or sufficient distance (335.118).	Yes	No	N/A_
NOTE	: If tanks are used, complete checklist for tanks.			
13.	Storage area has containment protection as set forth in Title 40 CFR Part 264.175, Use and Management of Containers.	Yes	No <sup>1</sup>	N/A
	NOTE 1: This will be a future permit requirement.			

14. Describe drum or container storage area. Use photos and/or comments sheet.

# Calliance Monitoring Inspection R PRT Facilities Checklist TAC 335.111-.118

### Section A - General Facility Standards

1.			deed recordation of on-site disposales has been provided to the agency.	Yes <u></u>	No	N/A
2.	show well pert land	wing l ls, dr tinent dfill(	of facilities, general site orientation landfills, surface impoundments, injection rainage routes, water bodies/courses and other t features (separate sketch or diagram of (s) etc.) should be attached to this and other checklist(s).	SLL	atte diag	ichea
NOTE	re ch	emaind neckli	I nonhazardous and noncommercial facilities do moder of this Facilities Checklist. Proceed to spists and complete one checklist for each disposits on a single checklist.	pecific	type fac	ility
Sect	ion E	3 - Wa	aste Analysis 335.114			
1.	Faci	ility	has a waste analysis plan.	Yes	No <u>i√</u>	. •
2.	Wast	te pla	an is maintained at the facility.	Yes	No_✓	
3.	Wast	te pla	an includes the following:			
	a.	Param	neters for which each waste will be analyzed.	Yes	No	
	b.	Test	methods used to test for these parameters.	Yes	No 🗸	
	с.	Samp	ling method used to obtain sample.	Yes	No 🗸	
	d.	•	uency with which the initial analysis will be ewed or repeated.	Yes	No 🗸	
		NOTE	: Frequency includes requirement to repeat whenever waste stream or process(es) is changed.			
;	*e.	Waste supp	e analyses that generators have agreed to ly.	Yes	No	N/A_
,	*f.		edures which are used to inspect and analyze movement of hazardous waste including:			
		(1)	Procedures to be used to determine the identity of each movement of waste.	Yes	No <u>√</u>	N/A
		(2)	Sampling method to be used to obtain representative sample of the waste to be identified.	Yes	No 🗸	N/A
TOUR						

TDWR-

Page 4 of 10 of Group I

\*Note: Applies to off-site commercial facilities only

4.	the facility provid adequate security (335.115).	res	140	
	a. √24-hour surveillance system (e.g. television monitoring or guards).			
	OR			
	b. $\frac{1}{\sqrt{\frac{1}{2}}}$ Artificial or natural barrier around facility (e.g. fence or fence and cliff).			
	Describe fence			
	181102	<del></del>		
•				
	c. Means to control entry through entrances (e.g. attendant, television monitors, locked entranc controlled roadway access).	е,		
	Describe guards at intrance			
	7 2000 600 600 600 600			
		<del></del>		
		<del></del>	į	٠
5.	Facility has a sign with the legend "Danger -		·	
	Unauthorized Personnel Keep Out".	Yes	No	N/A
Sec	tion C - General Inspection Requirements 335.116			
1	Facility has a written inspection schedule			
٠.	(and plan).	Yes 🗸	No	
	✓ Plan is maintained at the facility  Elsewhere (note location in comments sheet)			·
2.	Inspection schedule (plan) provides for inspecting the following:			
	a. Monitoring equipment.	Yes	No	
	b. Safety and emergency equipment.	Yes 🗸		
	c. Security devices.	Yes <u>·</u>	NO	
	d. Operating and structural equipment.	Yes 🗸	No	
3.	Schedule or plan identifies the types of problems to be looked for during inspection:			
	a. Malfunctions and deterioration.	Yes	No	
			— ź	

TDWR-Page 5 of 10 of Group I

				. •
	b. Operator error.	Yes	No	
	c. Discharge or threat of discharge.	Yes_ <u>√</u>	No	
4.	The owner/operator maintains an inspection log which includes:			
	a. Date and time of inspection.	Yes	No	
	b. Name of inspector.	Yes	. No	
	c. Notation of observations.	Yes 🗸	No	
	d. Date and nature of repairs or remedial action.	Yes <u>√</u>	No	
5.	Malfunctions or other deficiencies noted in the inspection log have been rectified.	Yes	No	N/A .J
6.	Inspection log records are maintained for 3 years.	Yes	No	
Sect	ion D - Personnel Training 335.117			
1.	Owner/operator maintains Personnel Training Records at the facility.	Yes_ <u>v</u>	No_ <u>i</u> _	
2.	Personnel Training Records include:		-	
	<ul> <li>Job Title and written job description of each position.</li> </ul>	Yes_ <u>√</u>	No	·
	b. Description of type and amount of training.	Yes 🗸	No	
	<ul> <li>Records of training given to facility personnel.</li> </ul>	Yes	No	
3.	Personnel Training Records are maintained for the appropriate length of time.	Yes <u>√</u>	No	
Sect	ion E - Requirements for Ignitable, Reactive or Incompa	tible Was	te 335	<u>. i 18</u>
1.	Owner/operator is familiar with proper separation and safeguards needed to prevent ignition or reaction of ignitable or reactive waste.	Yes	No	N/A
	<ul> <li>Use comments sheet to describe separation and confinement procedures.</li> </ul>			
	<ul> <li>Use comments sheet to describe any potential sources of ignition or reaction.</li> </ul>			
2.	Smoking and open flame are confined to specifically designated locations.	Yes	No	N/H
3.	"No Smoking" signs are posted in hazardous areas.	Yes	No	N/A
TDWR Page	R- e 6 of 10 of Group I			• • •

#### Section F - Preparedness and Prevention 335.131-.137

1. Describe any evidence of fire, explosion, or contamination of the environment in the comments sheet.

<ol><li>Facility is equipped with</li></ol>	2.	Faci:	lity	is	equipped	with:
---	----	-------	------	----	----------	-------

a. Internal communication or alarm system within easy access.

Yes / No N/A\_\_\_

b. Telephone or two-way radio to call emergency response personnel.

Yes ✓ No N/A

c. Portable fire extinguishers, fire control equipment, spill control equipment and decontamination equipment tested regularly to assure proper operation.

Yes ✓ No N/A

d. Water volume adequate for hoses, sprinklers or water spray system.

Yes √ No N/A

3. Aisle space is sufficient to allow unobstructed movement of personnel and equipment.

Yes V No N/A

4. Owner/operator has attempted to make arrangements with the local hospitals to familiarize them with the layout of the facility, properties of hazardous waste handled and associated hazards, places where facility personnel would normally be working, entrances to roads inside facility, and possible evacuation routes.

Yes ✓ No N/A

 In the case that more than one police and fire department might respond, a primary authority has been designated.

Yes No N/A ✓

6. Owner/operator has attempted to make agreements with State emergency response teams, emergency response contractors and equipment suppliers.

Yes / No N/A

7. Owner/operator has attempted to make arrangements with local hospitals to familiarize them with the properties of hazardous waste handled and types of injuries that could result from fires, explosions, or releases at the facility.

Yes No N/A

8. State or local authorities have entered into the necessary arrangements.

'es ✓ No N/A

9. State or local authorities have declined arrangements.

Yes No N/A 🏑

Sect	ion	G - Contingency Flan and Emergency Procedures 335. 3	1157		
1.	A c	ontingency plan is maintained at the facility.	Yes <u></u>	No	
2.	Con	tingency plan is: a. a revised SPCC Plan b. a separate document c. adequate to meet emergency procedures requirements	Yes	No	
3.		rgency coordinator is on-site or on call all times.	Yes <u></u>	No	
Sect	ion	H - Manifest System, Recordkeeping and Reporting 335	.17117	7	
1.		er/operator complies with manifest uirements.	Yes <u>√</u>	No	N/A
	NOT	E: If 1 is N/A, go to question 6 below.			
2.	shi	te received from a rail or water (bulk pment) transporter are accompanied by a perly executed shipping paper.	Yes	No	N/A
3.		shipments of waste received have been sistent with the manifest.	Yes	No.	N/A
4.		anifested waste was reported to the Executive ector [335.15(b)].	Yes	No	N/A
5.		crepancies have been reconciled with the erator and transporter.	Yes	No	N/A
6.		er/operator keeps a written operating ord at the facility.	Yes	No <u>√</u>	
7.	0pe	rating record reflects the following:			
	a.	Description, quantity of each hazardous waste received and method(s) and date of T.S.D. at the facility.	Yes	No_✓	
	b.	Location and quantity of each hazardous waste within the facility (for disposal facilities, quantity on a map or diagram of each cell or disposal area, for all facilities cross-reference to shipping ticket Nos.).	Yes	No :/	
	с.	Records and results of waste analyses and	162	NO_ <u>17</u> _	
		trial tests.	Yes	No 🗸	
	d.	Summary Reports of all incidents that require implementing the contingency plan.	Yes	No 🗸	
	e.	Closure cost estimates for all facilities (335.232).	Yes	No <u></u>	٠
	f.	Post closure cost estimates for disposal facilities (335.233).	Yes	No	N/h_

8.		er/operator maintains an adequate closure n for all facilities.	Yes	No_ <u>√</u>	N/A
9.	Own clo	er/operator maintains an adequate post sure plan for disposal facilities.	Yes	No	N/A_
10.	fin	the owner/operator is required to furnish ancial assurance (owner/operator of a hazardous te treatment, storage or disposal facility),			
	Wha	t is the estimated closure cost?			
		no estimate (*1 million for in	adequ	iuti	dosure,
	Wha	t is the estimated post closure cost?	U		plan!
		no estimate	_		
11.		sure (and post closure) costs have been perly adjusted for inflation.	Yes	No <u>√</u>	·
12.	for	er/operator established financial assurance "current" closure (and post closure) cost(s) h TDWR by July 6, 1982.	Yes	No 🕡	
<b>-</b> .	а.	If no, but financial assurance was established at a later date, specify when:			
		no adequate viosure ass	<u>u</u> cani	ce (ir	radequat
	b.	Specify the method(s) of assurance of financial fresponsibility for these costs:	inanc	ration	test <sup>o</sup>
		y Coverage Requirements 265.147			
1.	COV	ility owner/operator had sudden accidental erage (1 million per occurrence with annual regate of 2 million) demonstrated by July 15, 1982.	Yes	No <u>√</u>	N/A
	a.	If no, but sudden coverage was established at a later date, specify when:			
		no coverage			
	b.	Specify the method(s) of liability coverage and amount(s) demonstrated:	_		
		for(coverage)			

TDWR-Page 9 of 10 of Group I

# Coverage for Non-Sudden Accidental Occurrence

١.	Specify total sales or revenues for the fiscal year preceding July 15, 1982.		
	Owner		
	Operator unknown	<del></del>	
2.	Date by which coverage must be demonstrated (check one).		
	Jan. 16, 1984 1985		
3.	Letter to Executive Director has been sent (unless demonstrated earlier) stating the date he plans to have coverage.	Yes	No ./

#### INDUSTRIAL SOLID WASTE

	Compliance Monitoring Inspection Report Surface Impoundments Checklist (TAC 335.281288)	Class of Waste (_
1.	Are surface impoundments presently used to treat or store waste?  Yes   Yes	No
**2.	<ul><li>If yes, inspect the impoundments.</li><li>Does the impoundment appear to maintain at least</li><li>feet (60 cm) of freeboard?</li></ul>	Yes No
**3.	Check for evidence of overtopping of the dike. Is the facility compliant?	Yes No
**4.	Check for evidence of seepage. Is the facility compliant?	Yes No
5.	Containment system for dyked or dammed impoundments (335.283)	i
*	*a. Does the earthen dike have a protective cover (e.g. grass, shale, rock) to minimize wind and water erosion?	Yes No
6.	What wastes are treated or stored in the impoundment? heavy bearing dudge is settled in The impour	metals.
7.	Are waste analyses and trial tests conducted on these wastes (chemical processing of a different	YesNo
	a. If not, does the owner/operator have written documented information on similar treatment of similar wastes?	YesNo
8.	Is this information retained in the operating record?  N/A	Yes No
9.	Is the impoundment inspected daily to check freeboard level?	Yes/ No
10.	Is the impoundment, dikes and vegetation surrounding the dike inspected weekly to detect leaks, deterioration or failures?	Yes V No

TDWR-

Page 3 of 30 of Group II

\*\*See Note on Page 1

<sup>\*(</sup>Changed 9/10/82, response format realigned, other minor changes)

<sup>\*\*\*</sup>This response column indicates noncompliance.

D	es the impoundment have a liner?	Yes	No <u>√</u>	
a	If Yes, what type?	· · · · · · · · · · · · · · · · · · ·		
b	If Yes, does it have a leachate collection and removal system?	Yes	No	
	there evidence of ignitable or reactive wastes aced in the impoundment?	Yes	No 🗸	
a	If Yes, explain in comments sheet [review 335.118(	(a)];		
b	If Yes, is the impoundment used solely for emergencies?		Yes	No_
	there evidence of incompatible wastes placed in e impoundment [if yes, review 335.118(b)]?	Yes	No.	
	e monitor wells required for this site? (Refer to le 335.191195 - Ground Water Monitoring)	Yes√	No	
a	Has owner/operator installed, operated and maintain a ground water monitoring system (unless waived) prior to 11/19/81?	ined	Yes	No_1
N	TE 1: Attach Ground Water Monitoring Report if answ	ver to que	estion 14	isy
ď	scribe impoundment(s) site and indicate plat map, losing signation(s). Also describe each impoundment's dimecre-feet):	ensions ar	nd capaci	
تـ	he facility.	U		

NOTE 2: If the answer is No for Nos. 5a, 7a, 8, 9, 10 and No. 14 after 11/19/81, explain in comments sheet.

TDWRPage 4 of 30 of Group II
\*(Changed 9/10/82, response formal realigned)
\*\*See Note on Page 1
\*\*\*See Note Page 3

#### INDUSTRIAL SOLID WASTE

# Compliance Monitoring Inspection Report Tanks Checklist (Rule 335.261-.267)

Sect	ion /	4 - General			***
1.	Are	tanks presently used to treat or store waste?	Yes_ <u>√</u>	No	
	a.	If no, do not complete rest of form.		·	
	b.	If yes, check tanks. (Describe type of tank and in above ground, or on-ground in comments sheet).	ndicate <u>u</u> Subsic	ndergrou	nd,
	с.	Is there evidence that incompatible wastes have been placed in the tank?	Yes	No	
		(1) If yes, refer to 335.118(b) and explain in com	nments sh	eet.	
	d.	Check tank(s) for evidence of any ruptures, leaks or corrosion. Is facility compliant [335.264(a)(4)	]?	Yes	No
2.	Are	there any uncovered tanks?	Yes <u>√</u>	No	
	a.	If no, do not complete b e.			
	b.	If yes, do they have 2 feet (60 cm) freeboard? or	N/A	Yes 🗸	No 1
•	с.	A containment structure? (e.g. dike or trench equal to volume of 2 feet of tank) or	N/A	Yes	No <sup>1</sup>
	d.	A drainage control system?	N/A	Yes	No <sup>1</sup>
	e.	A diversion structure? (e.g. standby tank) NOTE 1: The structure in c, d or e must have a cap equals or exceeds the volume of the top 2 feet (60 tank; any one yes answer for 2b, c, d or e indicate	cm) of t	he	No <sup>1</sup> ✓
3.	Are	any of the tanks continuous feed?	Yes	No	
	a.	If yes, is it equipped with a means to stop inflow waste feed cutoff or bypass to a stand-by tank)?	(e.g.	Yes	No
Sect	ion	B - Waste Analysis			•
١.	Is	the tank used to store one waste exclusively?	Yes	No	
	a.	If no, what are the different wastes stored in the	tank?		
				<del></del>	
TOUD					

Page 9 of 30 of Group II

<sup>\*(</sup>Changed 9/10/82, added \*\*\* note and reworded some questions)

\*\*Note checklist questions to be noted or completed during on-site inspection

\*\*\*No checked in this column indicates noncompliance.

	b.	Are waste analyses and trial treatment or storage tests done on these different wastes? N/A_NOTE 1: Not applicable for less than 90 day storage [335.69(a)(2)].	✓ Yes	No
		(1) If no, does he have written, documented information on similar storage or treatment of similar wastes?  N/A	Yes	No
	с.	Are there records available of these wastes analyses in the operating record?  N/A		No
Sect	ion	C - Inspections (Where Present) 335.264		
1.		the records indicate the owner/operator inspects, re present, the following at least daily:		
	а.	Discharge control equipment (e.g. waste feed cut-off, bypass and/or drainage system)?	Yes	No
	b.	Monitoring equipment (e.g. pressure and temperature gages)?		No N//
	с.	Level of waste in each uncovered tank?	Yes	No
2.		the records indicate the owner/operator pects the following at least weekly:		
	a.	Construction materials of tanks for corrosion or leaks?	Yes	No
	b.	Construction materials of and area surrounding discharge confinement structures for erosion or signs of leakage?	Yes	No N/A
3.	Is	there a written inspection schedule (Rule 335.116)?	Yes 🗸	No
	a.	If yes, is the schedule kept at the site?	Yes	No
	ь.	If no for 3 or 3a, explain in the comments sheet.		
4.	Is	there evidence of ignitable wastes placed in tanks? Yes_	No 🏑	
	a.	If yes, do records indicate that they are treated, rendered, or mixed before or immediately after placement in the tank so it no longer meets the definition of ignitable? or	Yes	No <sup>2</sup>
**	<b>b</b> .	Is the waste protected from sources of ignition?	Yes	No. <sup>2</sup>
		(1) If yes, use comments sheet to describe separation and confinement procedures.	·	
		(2) If no, use comments sheet to describe sources of ignition. or		
TDWR Page		of 30 of Group II		

TDWRPage 10 of 30 of Group II
\*(Changed 9/10/82, added \*\*\* note and 2 notes added)
\*\*See Note on Page 9
\*\*\*See Note on Page 9

		1.		
	c.	Is the tank used solely for emergencies? NOTE 2: Only one of the three questions 4a, b, c answered yes indicates compliance.	Yes	No <sup>2</sup>
5.	Is	there evidence of reactive wastes placed in tanks? Yes	No V	
	a.	If yes, do records indicate that they are treated rendered, or mixed before or immediately after placement in the tank so it no longer meets the definition of reactive? or	Yes	No 1
**	т́Ь.	Is the waste protected from sources of reaction?	Yes	No 1
		(1) If yes, use comments sheet to describe separation and confinement procedures.		
		(2) If no, use comments sheet to describe sources of reaction. or		
	с.	Is the tank used solely for emergencies? NOTE 1: Only one of the three questions 5a, b, c answered yes indicates compliance.	Yes <u>;</u>	No 1
6.		the records indicate that incompatible wastes placed in the same tank? Yes	No_ <u></u> /	
	SF.	If s, review 335.118(b) and explain in the comments s	heet.	
7.		a was is be placed in a tank that previously d an composite waste do operating records tested tank was washed?	No	
The second secon		335.118(b) and describe Washing procedur	es	<del></del>
	b	esi de sissible for il comme le Waste to b	e placed in	the same
	2			
Cul .			~	
NOTI			and lc, and	
0			comments she	
0. <u>*</u>	ASSI		designation	
	es.			
J DUR Page				
**\$@ **\$@	230	terrore to the second s		

31 ° 14.

; ·

#### INDUSTRIAL SOLID WASTE

# \*Closure and Post-Closure Compliance Review Checklist (TAC Section 335.211-.220

Note:			ach type of hazardous waste T, S, D famments sheet.	acilit	y, numbe	r and vo	lume in		
ī.	CLOSURE PLAN; Is there a written plan?					Yes	No√attache		
	<ol> <li>Does the plan identify the *MAXIMUM EXT OPERATION which will be unclosed during life of the facility?</li> </ol>			NT OF the	n	o writ Yes	memo ten plan No onsite		
	*Note: The rules [335.213(a)(1)] require that the clother maximum extent of the operation which will the life of the facility. If the plan is base extent of operations to be closed just prior to important to consider whether that represents question.			will be based or ior to cl	l be unclosed <u>during</u> sed on the expected to closure, it is				
	2.	COM	oes the plan identify the steps for PARTIAL and/or OMPLETE CLOSURE [335.213(a)], at any time during the ntended operating life, of						
		a.	surface impoundments?		N/A	Yes	No		
		b.	landfills?		N/A	Yes	No		
		c.	tanks?		N/A	Yes	No		
		d.	other (specify:	_)		Yes	No		
	3.	of v	there an estimate of the MAXIMUM INVENwastes in storage or treatment at any ing the life of the facility?		N/A	Yes	No		
	4.	Doe:	s the plan clearly identify the STEPS SE [335.213(a)]?	TO					
		a.	at any point during the intended operating_life?			Yes	No		
		b.	at the end of the intended operating life?			Yes	No		

TDWR-

Page 24 of 30 of Group II

<sup>\*(</sup>Changed 10/13/83, added question to 1 above; this checklist is for use with "Part A" permit applicants that have not submitted "Part B" application)
\*\*This response column indicates noncompliance.

TDWR-

Page 25 of 30 of Group II

<sup>\*(</sup>Changed 10/13/83, added checklist question No. 10)
\*\*This response column indicates noncompliance.

POS pla	T-CLOSURE PLAN CHECKLIST; Is there a written n?	*N/A	Yes	No_
		n	o wu	tten
*No	te: If no post-closure required, proceed to Cost Estimate Checklist.			on si
1.	Does the post-closure plan provide for 30 years of post-closure care?	N/A	Yes	No
٠	How many years of post-closure care?			
2.	Does the plan clearly identify the ACTIVITIES required in the post-closure care?		Yes	No
3.	Do the MAINTENANCE PLANS for waste containment structures [335.218(a)(2)] include:			
	a. maintaining final cover (erosion damage repair) frequencies [335.344(d)(1)]?		Yes	_ , No
	b. vegetation and fertilizing frequencies [335.218(a)(2)(A)]?		Yes	No
•	c. collecting, removing, and treating leached activities [335.344(d)(2)]?	te N/A	Yes	No
	d. collecting, removing, and treating leacher frequencies [335.344(d)(2)]?	te N/A	Yes <u> </u>	No
	<pre>e. gas collection activities [335.344(d)(3)]?</pre>	N/A	Yes	No
	<pre>f. gas collection frequencies [335.344(d)(3)]?</pre>	N/A	Yes	No
4.	Do MONITORING EQUIPMENT MAINTENANCE plans [335.218(a)(2)(B)] include:			
	a. activities?		Yes	No
	b. frequencies?		Yes	No
5.	Does the plan identify the name, address and phone number of the POST-CLOSURE PERIOD CONTACT	T	Vos	No

II.

Page 27 of 30 of Group II
\*(Changed 10/13/82; added checklist for use with "Part A" permit applicants
that have not submitted "Part B" application)

<sup>\*\*</sup>This response column indicates noncompliance.

6.	add	landfills, does the post-closure plan ress the following objectives and indicate they will be achieved [335.344(b)]?			
	a.	Control of pollution migration via ground water, surface water, and air.	N/A	Yes	No
	b.	Control of surface water infiltration, including prevention of pooling.	N/A	Yes	No
	c.	Prevention of erosion.	N/A	Yes	No
7.	pos obj	land treatment operations, does the t-closure plan address the following ectives and indicate how they will be ieved [335.327(a)]?			
	a.	Control of migration of hazardous wastes and constituents into the ground water.	N/A	Yes	No
	<b>b.</b>	Control of the release of contaminated runoff into surface water.	N/A	Yes	No
	c.	Control of the release of airborne particulate contaminants caused by wind erosion.	N/A	Yes	No
	d.	Protection of food chain crops.	N/A	Yes	No
8.	doe a n fol ing	landfills and land treatment operations, s the post-closure plan include at least arrative statement indicating that the lowing factors were considered in address-the closure objectives [335.327(b), .344(b)]?			
	a.	Type and amount of waste.	N/A	Yes	No
	b.	Mobility and rate of migration.	N/A	Yes	No
	c.	Site location, topography, and surrounding land use.	N/A	Yes	No
	d.	Climate, including precipitation.	N/A	Yes	No
	е.	Characteristics of the cover, including material, final surface contour, thickness, porosity, permeability, slope, vegetation.	N/A	Yes	No

TDWR-

Page 28 of 30 of Group II

<sup>\*(</sup>Changed 9/30/82, added checklist for use with "Part A" permit applicants that have not submitted "Part B" application)

\*\*This response column indicates noncompliance.

f.	"Geological and soil profiles and surface and subsurface hydrology.	N/A	Yes	No
g.	Unsaturated zone monitoring.	N/A	Yes	No
h.	Type, concentration, and depth of hazardous constituent migration as compared to background concentrations.	N/A	Yes	No
9.	Does the plan address the requirement for notice to the local land authority (335.219)?		Yes	No
10.	Does the plan address the requirement for notice in the deed (335.220)?		Yes	No
11.	Post closure plan evaluated 2/29/84 Adequate		Yes	No
COM	MENTS			
V	o written plan onvite			
	o wasen prace orace.		•	<del></del>
		- <u> </u>	· · · · · · · · · · · · · · · · · · ·	
		`		
	-			
	·			

TDWR-


\*\*This response column indicates noncompliance.

Page 29 of 30 of Group II
\*(Changed 10/13/83; added checklist for use with "Part A" permit applicants that have not submitted "Part B" application)

TDWR-

Page 30 of 30 of Group II

<sup>\*(</sup>Changed 10/13/83, added checklist for use with "Part A" permit applicants that have not submitted "Part B" application)
\*\*This response column indicates noncompliance.



# Texas Department of Water Resources

INTEROFFICE MEMORANDUM

APR 2 5 84

TO

: Bryan Dixon, Acting Section Chief,

Solid Waste and Spill Response Section

THRU :

FROM : Jenny Gredell Menard, Environmental Quality Specialist, District 4

SUBJECT: Gould, Inc. - Farmers Branch, Texas

Registration No. 31697

#### ATTENTION: Mike Dick

On February 29, 1984 and April 11, 1984, the writer contacted Mr. William Backus and Mr. E. C. Milton and conducted an annual solid waste inspection at the above-referenced site.

The facility manufactures batteries. All drainage from the interior of the plant flows to a treatment system consisting of two neutralization tanks. The slurry resulting from neutralization is pumped to one of two currently active unlined surface impoundments and the sludge is allowed to settle. The liquid in the impoundments is discharged to the sanitary sewerage system. The sludge is considered hazardous at this point due to leachable lead concentrations. The sludge has, in the past, been chem-fixed and disposed of on-site.

The impoundments are surrounded by a bentonite slurry wall from approximately one foot below the surface on down to shale, approximately 20 feet below the surface, according to Mr. Milton. Outside of this area, five groundwater monitoring wells are located. This office sampled these wells April 11, 1984.

At the time of inspection in February, the company had just completed removal of 200 eighteen-yard truckloads of the sludge that had been fixed with flue dust from the south surface impoundment. The material was shipped to Rollins as hazardous waste.

An unlined pit approximately 100 feet by 25 feet by 15 feet was located west of the surface impoundments outside of the bentonite slurry wall. This area had been used to store chem-fixed sludge from the surface impoundments. Mr. Milton and Mr. Backus stated that approximately 600 truckloads of chem-fixed wastes had been removed from the area and shipped to Louisiana as hazardous waste. Removal of the chem-fixed material created the pit below the groundwater level. At the time of inspection, the company was pumping the groundwater collected in the pit into their surface impoundment for discharge to the sanitary sewerage system. Mr. Milton stated that the company planned to take soil borings in this area to check for lead contamination at a later date. This office was never notified of the closure of this storage area as required by TAC 335.6(f).

Gould, Inc. - Farmers Branch Registration No. 31697 Page 2 April 20, 1984

The two concrete subsurface neutralization tanks in the treatment system can not be emptied to inspect for leaks or ruptures, so the company has installed a plastic liner in the tanks with no space between the concrete and liner. The liner also encloses a PVC pipe near the center of the tank that is to be pumped weekly to detect any leakage of the liner. This lining of the tank has not been approved by Austin, as requested in the compliance agreement.

Mr. Milton stated during the inspection that the company has been submitting the completed white copy of the shipping ticket to Allen Messenger in the Austin office. The company has not filed the required monthly reports. They have been informed of what reports need to be filed by Nancy Villegas in Austin and stated that the reports would be filed.

The company did not have a waste analysis plan, operating record, or closure plan on-site at the time of inspection. They have not submitted the company's annual report to complete the financial test for closure assurance and have submitted no information concerning sudden or non-sudden liability coverage.

All of the above items are being addressed by a compliance agreement with an effective date of March 15, 1984. The adequacy of the company's groundwater monitoring plan is also being addressed by central office.

The company discovered an open subsurface pipe in the battery acid drain system that leaked acid to the ground when the system backed up. The leak was discovered January 28, 1984 and reported January 30, 1984 to Don Eubank of District 4. This is in violation of the maximum 24-hour time allowance to report an accidental discharge, required by the Water Code, Section 26.042. It was requested at that time that the company test the soil for lead contamination and remove any contaminated soil. The spill site was inspected on February 7, 1984 by the writer and Chris Swan of this office. Mr. Bill Backus of the company stated that they had dug 10-11 feet deep in the area surrounding the spill and removed 3-4 yd<sup>3</sup> of soil. This soil was dumped in the waste surface impoundments. Mr. Backus said that rather than test the soil at the time, the company backfilled the excavation with clean soil. They plan to drill soil borings in the future to check for contamination. Mr. Backus stated that the company would submit a written sampling plan within a week of the spill report specifying when and where sampling would occur. This office never received that plan. During the February 29, 1984 inspection, Mr. Backus and Mr. Milton stated that the soil borings would be done in approximately one month. They stated that they would report the results of the borings to this agency.

Quarterly sampling of the groundwater wells was done on April 11, 1984 by Tom Hauessler of Professional Service Industries. Samples were also collected at that time by the writer.

It was noted during the sampling that the west surface impoundment had only nine inches of freeboard on its west side. Water was not being pumped from the former chem-fix pit into the surface impoundment, but the pump and hose were still in place.

Gould, Inc. - Farmers Branch Registration No. 31697 Page 3 April 20, 1984

During the day on April 11, a street sweeper continually swept the paved back parking lot. The sweeper occasionally drove onto the west side of the dike surrounding the surface impoundments and dumped the sweepings, either into the west surface impoundment, or onto the dike.

It was often difficult to obtain access to the groundwater monitoring wells for sampling on April 11, 1984. Discarded conveyors from the manufacturing plant had to be moved to allow sampling of Well 3A. A backhoe blocked the road to Well 2A. Concrete rubble made it difficult to drive to and sample minor well south. Old plant machinery and rubble blocked the path to Well 1A.

North monitoring well was, in the past, hit and damaged. Sampling of this well was difficult because the well casing apparently is not straight. The integrity of this well should be investigated.

This is submitted for your information.

JGM:jc

APPROVED Don Section & SIGNED Jenny Midell Menand

# Complement Monitoring Inspection Reporting Financial Assurance, Closure and Post Closure Worksheet

	be completed if the facility treats, stores or a permit is required <u>or</u> if the facility has	submitte	ed a Pa	irt A A	
nbbA	ility: Gould Inc. (GNB Batteries II) ress: 1880 Valley Varie Lane Frances Brillity Owner/Operator Fiscal Year End: Month	ردن Pe مار Inspe	ermit/R	leg. No late	· 31697 2129184
1.	Preinspection call to Bob Brydson (2041) concurrent financial assurance documents. If yes, check the documents submitted:	firms th	Yes <u>./</u> _	No	N/A
	Sudden liability amount \$ per occur  Non-Sudden liability amount \$ per o  Closure assurance amount \$  Post Closure assurance amount \$	rence, ccurrenc	e, \$	_ annua 	l annual
	Brydson reports documents adequate If no, list problems deficient in audit Alguned for financial test for	- Claic	11-	+78	<u> </u>
For (Gr	the following questions, review appropriate oup I-Major pages 8-10, Non-major-page 3, and	inspecti Group I	on chec I-page:	cklist s 21-27	answers ')
3.	Closure Plan is adequate		Yes	No_✓	N/A
4.	Closure Cost Estimate, amount \$ 1 million is adequate If no, list proper amount \$		Yes	No	N/A
5.	Post Closure Plan is adequate		Yes	No	N/A J
6.	Post Closure Cost Estimate, amount \$is adequate If no, list proper amount \$		Yes	No	N/A <u>/</u>
	Facility has provided financial assurances f closure If yes, date effective Instrument	or Date exp	Yes	No 🗸	N/A
8.	Facility has provided financial assurances f post closure If yes, date effective Instrument	Date exp	Yes ires	No	N/A
<b>9.</b>	Facility has provided appropriate sudden lia coverage If yes, date effective Instrument	bility Date exp	Yes_ ires_	No V	N/A
10.	Facility has provided appropriate non-sudden coverage If yes, date effective Instrument	liabili	Vac	No 🖊	N/A

TDWR-Appendix Page 2 of Group II-Added FY 1984 for use with all TSD facilities

# FORM SUBMITTED

By:	J. Gredell Menard

Date: 4/6/84

		MAJOR FACIL	ITIES STATUS SHE	ET	$d^{(n^{-1})}$
ID	No.: <u>TXD 007</u>	331 <i>879</i> Re	gistration/Permi	t No.: 31697	
Fac	ility Name: <u>680</u>	ld Inc. (G	NB Batteries)0	istrict No.: 4	
۱.	Ground Water Mon	itoring Statu	<u>.</u> <u>s</u>		
	Detection Assessment		Waiver		
2.	Ground Water Mon	itoring Well	System		
	<ul><li>a. Evaluated?</li><li>b. Adequate?</li></ul>	NA YES	NO	DATE EVAL'D.	inted by Kar
3.	Ground Water Sam	pling, Analys	is and Evaluatio	n Program to present	entral office of
	<ul><li>a. Evaluated?</li><li>b. Adequate?</li></ul>	NA YES	NE	DATE EVAL'D	
4.	Notice of Signif	icant Increas	e in Parameter C	oncentrations	
	Submitted?	NA	NO	DATE SUB'D	
5.	Ground Water Qua	lity Assessme	nt Report	. <b>.</b>	·
	<ul><li>a. Submitted?</li><li>b. Evaluated?</li><li>c. Adequate?</li><li>d. Showed hazar</li></ul>	NA NE YES dous waste co YES	NO DATE EVAL NO nstituents in gr		<del></del>
6.	Waiver Demonstra	tion			
,	a. Evaluated? b. Adequate?	NA YES	NE NO	DATE EVAL'D	· 
7.	Ground Water Mon		· ·		
	a. Evaluated?	NA	NE NE	DATE EVAL'D	<del></del>

8.	Activities Subject to Closure/Post-Closure							
•	Landfill Surface Impoundment Waste Pile Land Treatment/Application  Other (Specify)  Meatment tanks							
9.	Closure Plan							
	a. Evaluated? NE DATE EVAL'D 2/29/84 b. Adequate? YES NO NO COOLUL plan							
10.	Closure Cost Estimate							
	a. Evaluated? NA NE DATE EVAL'D 2/29/84 b. Adequate? YES NO J c. Amount: \$ 0 UNKNOWN							
11.	Closure Assurance Instrument(s)							
	a. Evaluated? NA NE DATE EVAL'D 2/29/84 b. Adequate? YES NO NO INSTRUMENT c. Type(s):							
	TRUST FUND FINANCIAL TEST / FINANCIAL BOND CORPORATE GUARANTEE PERFORMANCE BOND STATE GUARANTEE LETTER OF CREDIT OTHER STATE MECHANISM							
12.	Post-Closure Plan							
	a. Evaluated? NA / NE DATE EVAL'D b. Adequate? YES NO							
13.	Post-Closure Cost Estimate							
	a. Evaluated? NA / NE DATE EVAL'D b. Adequate? YES NO UNKNOWN							
14.	Post-Closure Assurance Instrument(s)							
	a. Evaluated? NA / NE DATE EVAL'D b. Adequate? YES NO NO INSTRUMENT c. Type(s):							
	TRUST FUND FINANCIAL TEST FINANCIAL BOND CORPORATE GUARANTEE PERFORMANCE BOND STATE GUARANTEE LETTER OF CREDIT							

# PA-SCORE REFERENCE 5

# SUBSURFACE INVESTIGATION UNDERGROUND EFFLUENT PIPELINE FARMERS BRANCH, TEXAS

Report to

GNB BATTERY, INC. Mendota Heights, Minnesota

Ву

PROFESSIONAL SERVICE INDUSTRIES, INC.
NATIONAL SOIL SERVICES DIVISION
Dallas, Texas

March, 1984



# Professional Service Industries, Inc.

National Soil Services Division

March 29, 1984 PSI Project 45031

GNB Battery, Inc. 1110 Highway 110 Mendota Heights, Minnesota 55165

Attention: Mr. Everett Milton

Supervisor Facilities Planning

SUBSURFACE INVESTIGATION UNDERGROUND EFFLUENT PIPELINE FARMERS BRANCH, TEXAS

Gentlemen:

Presented here is the report of our investigation of soil sufate and pH levels in two boring locations near the recently constructed valve box for the above-referenced project. This study was conducted in general accordance with the verbal request and authorization of Mr. Everett Milton on March 9, 1984.

Two sample borings were advanced to the depth of the underlying shale aquiclude at the approximate locations shown on the Plan of Borings, Plate 1. Descriptions of the soil and rock formations encountered are presented on the logs of boring, Plates 2 and 3. Keys to descriptive terms and symbols used on the logs are presented on Plates 4 and 5.

Soil samples were obtained at the surface and approximately every five feet thereafter to boring termination depths. Samples were submitted to Spectrum Laboratories for analyses of pH levels and total concentrations. Results are presented on Plate 6. In general, these soils do not appear to have any contamination as a result of effluent leakage from the buried pipeline. In accordance with our interpretation of the local groundwater gradients, the sampled locations should be very nearly in line with the projected path of groundwater which moves through the location of the observed pipeline leak.

Based on the findings of this investigation, contaminants which may have entered the groundwater environment through the observed pipeline leak do not appear to have migrated any appreciable distance from the point of escape. Although this investigation is of a limited scope and cannot be considered conclusive, it appears that the soil formations adjacent to the leak are low permeability clays which are capable of effectively containing any effluent which may have leaked from the underground pipeline.

We appreciate the opportunity to be of service. Should you have any questions or require additional assistance, please call.

Very truly yours,


NATIONAL SOIL SERVICES DIVISION

William Prikryl,

Project Engineer

WP/qt

Copies submitted: 3



# LOG OF BORING NO. 8-11

BURIED EFFLUENT PIPELINE GNB BATTERIES, INC. PLANT FARMERS BRANCH TEXAS


X

GNB BATTERIES, INC. PLANT FARMERS BRANCH, TEXAS															
TY	39	ВО	RING: Undistur	bed Sample		CATION	: !		Plar	of	Bori	ngs	, P1a	ate 1	
DEPTH. FT.	SYMBOL	SAMPLES	SOIL	DESCRIPTION			% PASSING NO. 200 SIEVE	LIQUID	PLASTIC LIMIT	MOISTURE CONTENT, %	IN	TON:	STRE S/SQ		UNIT DRY WT
	<b>4</b> 44		Hard light o	rav gravelly	sand								ŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢ		
		1	<u>6" Asphalt (</u>	0.6-1.0'									0	•	
		1	Very stiff tw/small grav	rown sandy o	clay,										] ]
- 5 -			-w/increasin			•								1 - + + +	
											111		$\frac{1}{1}$	+	1 1
			•			!							111		1 ]
		1			-										] ]
-10-			-loose dark	brown							<del>    </del>		++++	11:11	
											++-		╂┼┼		
			-w/iron stai	ns		(CL)					Ш				
			Soft tan to	<del></del>		(02)					+++		<del>                                      </del>	+ + + + + + + + + + + + + + + + + + + +	-
-15-		ħ	weathered (E	agle Ford sl	nale)					-			$\frac{1}{1}$	111.	+ -
		$\parallel$													
Ħ		$\parallel$													
目		$\  \ $								}	+++		+++		$H = \frac{1}{2}$
-20-		$\prod$									╫		╫		
		$\ $													] ]
											<del>    </del>	<u> </u>	$\downarrow \downarrow \downarrow \downarrow$	<u> </u>	4 4
		$\ $							ļ	}	++++		╂┼┼	<del>                                     </del>	1 1
-25-		П								ľ					1 1
						,							$\prod$		]
曰								.		}		╏┼┼┼┤	+ + + +	<del>                                      </del>	-
										ŀ	++++		+++		
-30-		$\  \ $								Ì			Ш		] ]
											1111	$\parallel \parallel \parallel$	$\coprod$		
目									1	ł	++++		+++		+ :
-35								- {	ļ.	į					] ;
鬥			•						1	ſ	Ш		$\prod$		] ]
目										}	$\{ \} \} \}$	HHH	+++	<del>                                     </del>	4 3
	CO	APL	ETION DEPTH			DEPTH	TO	WAT	ER:7	· . 0 ·	- Cav	بللن ed ن	at 1:	2.0	
<u></u>	COMPLETION DEPTH: 15.0' DEPTH TO WATER:7.0 - Caved at 12.0' DATE: 3/12/84 DATE:3/12/84														

#### LOG OF BORING NO. B-12

BURIED EFFLUENT PIPELINE GNB BATTERIES, INC. PLANT FARMERS BRANCH, TEXAS

LOCATION: See Plan of Borings, Plate 1 TYPE BORING: Undisturbed Sample



#### KEY TO SOIL CLASSIFICATIONS AND SYMBOLS

#### SOIL TYPE
















Predominant type shown heavy

#### TERMS DESCRIBING CONSISTENCY OR CONDITION

# COARSE GRAINED SOILS (Major partion retained on No. 200 sieve)

Includes (1) clean gravels and sands described as fine, medium or coarse, depending on distribution of grain sizes and (2) silty or clayey gravels and sands. Condition is rated according to relative density, as determined by laboratory tests or estimated from resistance to sampler penetration.

Penetration Resistance Blows/Foot**	Descriptive Term	Relative Density *
0 - 10	Loose	0 to 40%
10 - 30	Medium dense	40 to 70%
30 - 50	Dense	70 to 90%.
Over 50	Very dense	90 to 100%

\* From tests on undisturbed sand sample

\*\*  $140^{\circ}$  hammer, 30-inch drop

Relative density is also used to describe condition of low plasticity (P 1 $\rightleftharpoons$ 10) fine grained soils such as sandy silts.

# FINE GRAINED SOILS (Major portion passing No. 200 sieve)

Includes (1) inorganic and organic silts and clays, (2) gravelly, sandy, or silty clays, and (3) clayey silts. Consistency is rated according to shearing strength, as indicated by penetrameter readings or by unconfined compression tests for sails with plasticity indices  $\geq 10$ .

Descriptive Term	Compressive Strength Tans/Sq. Ft.						
Very sofr	less than 0,25						
Soft	0,25 to 0.50						
Firm	0.50 to 1.00						
Stiff	1.00 to 2.00						
Very wiff	2,00 to 4.00						
Hard	4,00 and higher						

Note:

Silctensided and fissured clays may have lower unconfined compressive strengths than shown above, because of planes and weakness or shrinkage cracks in the sail. The consistency ratings of such soils are based on penetrometer reedings.

#### TERMS CHARACTERIZING SOIL STRUCTURE

Fissured	<ul> <li>containing shrinkage crocks, frequently filled with fine sand or</li> </ul>		nclined planes of s that are slick and glossy rance.
	silt; usually more or less verrical	Degree of slickenside devel	opment:
Sensitive	<ul> <li>perraining to cohesive sails that are subject to eparaciable loss of strength when remotded</li> </ul>	Slightly slickensided	<ul> <li>slickensides are present at intervals of 1-2 feet and sail does not easily break along these planes</li> </ul>
Lominoted	<ul> <li>commosed of thin leyers of verying color and texture</li> </ul>	Moderately slickensided	<ul> <li>slickensides are spaced or intervals of 1-2 feed and soil breaks easily</li> </ul>
Interbedded	<ul> <li>composed of alternate layers of different soil types</li> </ul>	Extremely stickensided	along these planes,  - slickensides are spaced at intervals 4-12 inches,
Colcareous	<ul> <li>containing appreciable quantities of colcium cerbonare</li> </ul>	•	are continuous and inter- connected. Sail breaks easily along the sliceen-
Weil graded	<ul> <li>having wide range in grain sizes and sub- stantial amounts of all</li> </ul>		sides. Resulting size of broken pieces three to six inches.
	intermediate particle sizes	Intensely slickensided	- slickensides are speced of intervals of lass than
Poorly graced	<ul> <li>predominetely of one grain size, or having a range of sizes with same intermediate size missing</li> </ul>		four inches and are con- tinuous in all directions Soil breaks down along planes into nodules 0,25 - 2 inch in size.

#### KEY TO BOCK CLASSIFICATIONS AND SYMBOLS

#### BOCK TYPE

















Shalbu

Tube



3000

N.

0

Pitcher Borrel

Rock Core

SAMPLE TYPE

.....

## TERMS CHARACTERIZING PHYSICAL PROPERTIES OF ROCK

#### Bedding Characteristics:

occurring in thick bad, free from miner joints and laminations, more than 100 mm.

Thin to mad, 1 -

eccurring in relatively thin layers or laminue, 2 mm, to 100 mm, bedding plana

Pasile

badding which consists of lessings less than 2 mm, in thickness, splits easily along closely spaced parellel planes

errorgement of igninations of strate tre verse or ablique to the main planes of stratification of the strate conc

**Faligrad** 

the feminated structure resulting from see getion of granular and fine minerals into isopen possible to the schietesity (result of the porollel arrangement of platy and ellipseidol mineral grains)

Platy

parallel evergement of broad or flet als als (giving a foliation) by slablike inclusions, by achliaren, or by bands of different -

cornisting of braken material, particularly that which has been moved from its place of origin

#### Lithologic Characteristics:

روال مد Silicoous Sandy, Silly,

Clayey, Shaly, . The lithology is used describing the parent reck such as a shally limporary or cerberoceous shale

Pleatic See

#### Hardness and Degree of Comentations

Very soft or plantic

can be remolded in hand, can consistency up to very stiff in sails

-

can be screeched with fingerspil

can be scretched easily with kalfes cannot be scretched with fingermil

Hard

difficult to sesseth with knife

Very hard

corner be scretched with halfe

Pearly can ar friable

smily crambing

Consessed

bound regether by chamically precipitated meterial occurring in the interation between ellopenic particles of rack - quarts, calcite, mite, siderite and Iran axide are Common comenting materials

Swelling Properties:

Smalling and Man-Smalling

Slating Properties:

Nen-Sighting

States story on expenses

Slakes resultly an expenses

#### Testure:

fine-grained ephenitic recks in which the grain size generally everages less than 0,05 to 0,1 mg.

were then 50% by weight smaller than 0.074 mm. In diameter faces only with a strong hand love or a microscopi

44-44-

empority of grain sizes between 0,074 mm. and 0.5

grain sizes rarge from 0.5 am. to 1.0 am. (crystals are visible to the unsided and

#### Structures

Bodding

Flow (0° to 15%); Gently disping (15° to 30%)

Steeply disping (ID" to vertice)

freehres, SCHOOL OF S

broken surface of minerals or rock which does met auhibit clasvage er bedding planes

fractures, closely speced

shows signs of braken minerals but now in

Procedured

reck made up of kighly angular coanse fragments ntery or formed by crushing or may be seen grinding elong faults

وواط

'fractures in rack, generally more or less vertical or transverse to bedding, elarg which no approciable movement has accurred

fracture or fracture zone along which there has been displacement of the sides relative to one enother persiled to the fracture - the displacement may be a few inches or many miles

Slickersides

polished and stricted (scretched) surface that results from friction along a fault plane

#### Degree of Weathering:

rack in its natural state before being expensed to elementeric ments

Silphely

ted predominantly by color charge with ne

distangement comm complete color charge with zones of slightly

Extremely ---

decreesed rack complete color charge with consistency, he have, and general expensence expressions sail

#### Solution and Vold Conditions:

Solid

contains on wide

Vegay bired Valedar

estitles in rack

containing many small covilies

containing valde, porce, intentices, or other specings which may at may not interconnect

Carltina

solutional concertty in limesture cover, the audies of which is described by a joint or faints - also applied to small hallows in أسا محجوب

containing cavilles or coverns, sen large - must frequent in lineatenes and deterrine



# SPECTRUM LABORATORIES

#### Chemical • Metallurgical • Electron Microscopy

REPORT OF:

Soil

March 22, 1984

REPORT TO:

NFS Services, inc.

Attn:

William Prikryl

P.O. Box 24596 Dallas, TX 75224

DATE RECEIVED:

March 13, 1984

**IDENTIFICATION:** 

As Shown

Sample ID	рH	Sulfate, ppm
B-11 J-2	6.0	4
J-4	7.3	6
J-6	7.3	12
J-8	7.8	14
B-12 J-2	7.4	8
J 3	7.6	. 9
J-5	7.3	14
J-7	8.2	22

**DISTRIBUTION OF REPORTS:** 

2 - NFS Services, Inc.

Attn: William Prikryl

11258

**\$ S** 

Spectrum Laboratories
Gary E. Cude

Director-Analytical Services

RESPECTFULLY SUBMITTED.

Lab Numbers

NOTE: Submitted material will be retained for 90 days unless otherwise notified.

Our letters and reports are for the exclusive use of the client to whom they are addressed. The use of our name must receive our prior written approval Our letters and reports apply to the sample tested and/or inspected, and are not necessarily indicative of the qualities of apparently identical or similar materials.

GNB Batteries Inc.

DATE
TEXAS REGISTRATION #
EPA ID #
LAST REVISION

January 11, 1984 31697 TXD007331879


#### HAZARDOUS WASTE MANAGEMENT

Farmers Branch, Texas

VOL. II SEC. II

Appn/Exh/Page C/ 1/17

OPERATING RECORD
(Texas Hazardous Waste Management Plan)
(Volume II, Section II, Subsection 8)
(Appendix C, Exhibit 1)



#### Appendix N

#### Closure Costs

The authority for this cost is the Closure And Post Closure Plan. Consult that document for the costs.

For reference, the January, 1984 cost is \$1,500,000.

**GNB** Batteries Inc.

DATE
TEXAS REGISTRATION #
EPA ID #
LAST REVISION

January 11, 1984 31697 TXD007331879

HAZARDOUS WASTE MANAGEMENT

Farmers Branch, Texas

VOL. II SEC. II Appn/Exh/Page C/ 1/16

OPERATING RECORD

(Texas Hazardous Waste Management Plan) (Volume II, Section II, Subsection 8) (Appendix C, Exhibit 1)

#### Appendix M

#### Inspection Logs

Maintenance and Inspection logs are maintained in a separate manual.

See Site Inspection Manual and Site Inspection Logs.

# PA-SCORE REFERENCE 6

**GNB Batteries Inc.** 

Automotic Sattery Division

P.O. Box 43140 St. Paul, MN 55164 U.S.A. Telephone: (612) 681-5000



RECEIVED

October 28, 1983

NC' 1 / 183

EMPER LATERATIONS

Mr. Mike Dick
Texas Department of Water Resources
Hazardous Waste Division
Stephen F. Austin Building
1700 North Congress
Austin, Texas

Dear Mr. Dick:

Confirming our phone conversation of today, I would also like to have some further discussion on Item #5 of our October 25 agenda when we meet again on November 7, 1983. I am still having difficulty understanding how that section can apply to anyone who is not disposing. References called from that section are specifically directed toward facilities operating disposal sites.

My specific problem is with the reporting requirements, and the resultant "tracking" of the waste.

Thank you for your assistance.

Yours truly,

GNB BATTERIES INC.

E. C. Milton

Manager, Facilities Engineering

cc: T. Hatterschide

B. Backus

M. Roberts

D. Eubanks - TDWR, Duncanville

/ch

Not to Scale \$100.7 \ MW-1A -74.585 15.1 17.24 Small Bldg. Pond Pond Plant Mixing Pond Pond Bldg. Pit Solids Storage 7..~ Area Fence 44.31 Legend Monitor wells this study - Monitor wells previous study 1.1 2710 7.61 PLAN OF MONITOR WELL LOCATIONS

## LOG OF BORING NO. MW-1A

## MONITOR WELL INSTALLATION

GNB BATTERY PLANT

			FARMER'S BI							
TY	PΕ	во.	RING: Undist. Split Spoon Lo	OCAT	ION	: <u>S</u>	ce P	an c	of Bo	rings, Plate I
DEPTH. FT.	SYMBOL	SAMPLES	SOIL DESCRIPTION		S PER FT.	S VE	IQUID IMIT		MOISTURE CONTENT, %	SHEAR STRENGTH IN TONS/SQ FT.  IN TONS/SQ FT.  1.4 0.7/SAT
			Stiff tan sandy clay, w/3" sand and roots at surface ((	CL)						1   1   1   1   1   1   1   1   1   1
- 5			Loose tan and brown clayey fine sand, w/occasional gravel	SC)	4					
-10-		V A	Medium dense tan fine to coarse-sand, w/gravel		23					
	<u>}</u>		Medium dense gravel, w/sand	SF) GP)						
-15		-X	Soft gray shale, slightly iron stained	01)	37					
-20- -25- -30- -35		<b>X</b>								
	COMPLETION DEPTH: 16.0' DATE: 2/23/83									



#### LOG OF BORING NO. MW-2A

MONITOR WELL INSTALLATION

GNB BATTERY PLANT

FARMER'S BRANCH, TEXAS									
TYPE	TYPE BORING Undist. Split Spoon Sample LOCATION: See Plan of Borings, Plate 1								
DEPTH. FT.	(2)	SOIL DESCRIPTION	·	BLOWS PER FT.		LIQUID		MOISTURE CONTENT, %	SHEAR STRENGTH LATE ON TONS/SO FT. LATE ON STRENGTH LATE ON STRENGTH LATE OF STRENGTH LATE
-10- -10- -15- -15- -20- -30-		Brown clayey fine sand, w/1.0' of chemically fixed solids -w/occasional gravel, clay pockets, iron stains  Very dense brown sandy gravel  -dense  Soft gray shale	(SC)	31   58				W 0	
L	- OMF	DATE: 3/2/83							
									-

#### LOG OF BORING NO. MW-3A


#### MONITOR WELL INSTALLATION GNB BATTERY PLANT

FARMER'S BRANCH, TEXAS

TYPE BORING: Undist. Split Spoon Sample LOCATION: See Plan of Borings, Plate 1

TY.	TYPE BORING Undist Split Spoon Sample LOCATION: See Plan of Borings, Plate 1									
					FT.	S M			₹E I. %	SHEAR 'STRENGTH 3-
FT	X	SAMPLES				3 3	LIQUID	PLASTIC LIMIT	8 -	IN TONS/SQ FT.
	SYMBOL	٦	SOIL DESCRIPTION		BLOWS PER	155	ટ્રેં≅	S =	TUR ENT	
UEP FH.	<del>-</del>	Z			۲۶	200		ごこ	S	
	S	S			ð	% NO. 2	-	a_	MOI	돌의
		4			ಹ	Z				0.5 1.0 15 출근
<b> </b>		7	Brown clayey fine sand, w/gravel,						{	
		· II	occasional clay pockets, cinders	:		}				
			occasional eray poeters, emacra			]		}		
		91				}	}			
		Y					1			<del></del>
F 5 -		1				{		1		
\ <u></u>	1. N.	3		i	j	]	1	}	}	
		31	(Fill)	(SC)	}	i	}		}	
	14	-1	<del>////////</del>	·/-			1			
<b></b>	181	3	Grayish-brown gravelly clay		1	Ì	ļ	ļ	]	
-10-	13	34			1		1			<del>                                      </del>
	18	31			l		}	1		<del>                                     </del>
	91	3			1	1	l	1		
					[		ļ	ŀ	1	
	11	H	-w/numerous gravel	(CL)	ļ					
		ΞX	Soft gray shale		37					1110 121111 11 11 11 1
15		71	Soft stray strays		<del> </del>		<del>                                     </del>	<del> </del>	<del> -</del> -	
		! [								
						1	1	{	1	<del></del>
	i i				ł	}		1	1	
	i	11			}					
-20-	}				1	}	}	Ì		
720	}						ļ	}		
	1				1		1			
					1	İ	1			
	1					l	1			
}	}	11				1	1		}	<del></del>
F25-			·		1	1	}			
	1	11					1			
-	į				1	1	}			
	ì				1					
<b> </b>	}	11					}			
	1					1	1			
-30-						}	1			
<u> </u>		11				}				
[	İ				}				1	
	1	+			-	1				
-35	{	- } }			1		1	ļ '	}	
735	]				}	}	}	]	}	
133	}				1	1		1		
	}				1	i	1		1	
	1						ļ		1	<del>┠╂╏┆╏┸┑╏</del> ┞┼┼┼┞╌┈╌┤
	COMPLETION DEPTH: 15.0'									
Į			DATE: 2/28/83							
			4/20/00							

		::-					<b>^*</b>
	South a	sell				North.	will
	" DH	504				ple	504
117/76	6.7	115				6.7	1072
10/11/76	6.8	• 2			-	<i>6.</i> 7	3.7
1: 177	6.8	1000	_			6.6	323
1/1:10	£. —	454	IA	2 A	2 N	6.9	103
1/28/83	7.4	750	385	670	720	1	640
7/7/72	7.7	806	(1110	974	437	7.7	689
	410						



- web git

2A 3


100-100-100 (16)

100-100-100 (16)

100-100-100 (16)

100-100-100 (16)

100-100-100 (16)



#### TEXAS DEPARTMENT OF WATER RESOURCES

#### CONFERENCE RECORD

Conference date: Oct	ober 25, 1983	Plac	ce: SFA B	uilding, Rm.	1028
Type of conference:	Informal				
	(telephone, other)	staff,	formal or	informal	hearing,
Attendance:					
Name			Agency		
See Attached List					

The meeting was held to request corrective measures necessary for Gould's compliance with the Industrial Solid Waste Rules. Additionally, information was obtained in order for the Department to make a determination on the Company utilization of a recycler to dispose of off-spec materials, and other waste. The company agreed to the following corrective actions:

- 1. Comply with TAC 335.220 by November 30, 1983;
- 2. Comply with TAC 335.114 by November 30, 1983;
- 3. The company is now in compliance with TAC 335.116;
- 4. Comply with TAC 335.173 by November 30, 1983;
- 5. Comply with TAC 335.221-.220 by December 30, 1983;
- The company is no longer utilizing the Class II site/(on-site);
- 7. The company will comply with the freeboard requirement by December 30, 1983;
- 8. The company will comply with 40 CFR, 265.147(a), .147(d) by November 30, 1983;
- 9. The company will immediately comply with TAC 335.264(a)(5); and
- 10. The company will comply with TAC 335.262(d) by December 30, 1983.

Additionally, a meeting was set up for November 2, 1983 with Department geologist and consultants to discuss the ground water problems.

MGD:py

Prepared by: Websel but


TE-VR-0103

# TEXAS DEPARTMENT OF WATER RESOURCES C O N F E R E N C E A T T E N D A N C E

Project: <u>Fours</u> (GA	1B) - SWC # 316	.97	
Conference: 1028	Conf. Rein	Place: SFA	
Name	Representing	Title Function, or Position	Phone No.
Michael Dick	TOWC	StafF	512/475-5511
Dan C. Eybank	TDWR	Dist4	(214)298-67>
Mary Riagin	TOWR	His ich hansel	(214)298-617 (1512)475-7545
DILLIAM A. BACKUS	414 8	MAINTENADOL	
J C MICTON	608	SUPERIN TENING	12/4/14
Fakert Brydson	TDWR	Personale Fac	MAIL MALL

# PA-SCORE REFERENCE 7

OCCURRENCE, AVAILABILITY, AND
CHEMICAL QUALITY OF GROUND
WATER IN THE CRETACEOUS
AQUIFERS OF NORTH-CENTRAL TEXAS
Volume 1



TEXAS DEPARTMENT OF WATER RESOURCES



#### TEXAS DEPARTMENT OF WATER RESOURCES

#### **REPORT 269**

# OCCURRENCE, AVAILABILITY, AND CHEMICAL QUALITY OF GROUND WATER IN THE CRETACEOUS AQUIFERS OF NORTH-CENTRAL TEXAS VOLUME 1

Ву

Phillip L. Nordstrom, Geologist

#### TABLE OF CONTENTS

																					Page
SUM	MARY AND CONCLUSIONS																			•	1
INT	RODUCTION										•										3
	Purpose and Scope								•					•					•		3
	Location and Extent								•		•					٠.					3
	Physiography																	•			3
	Climate				•														•		4
	Population																				4
	Economy																٠.				4
	Previous Investigations				•											•	•				4
	Acknowledgements							•													7
•	Method of Investigation						•								•						7
	Well-Numbering System				•																7
	Metric Conversions									: .											8
GEO	LOGY AS RELATED TO THE OCCU	RRI	ENC	ΕO	F G	RO	UN	D V	VA.	TER	t .					•					9
	Geologic History					٠										•			•		. 9
	Paleozoic								•					•		•	•				9
	Cretaceous															•					9
	Tertiary and Quaternary .																			•	9
	General Stratigraphy													•						•	9
	Structure											•									10
STR	ATIGRAPHY OF THE WATERBEA	RING	G F(	ORN	IAT	101	NS			•											12
	Paleozoic Rocks																				12
	Antlers Formation																				13

water-bearing formations in north-central Texas are of Cretaceous age.

The Cretaceous System is composed of two series, Gulf and Comanche, and each is divided into groups. The Gulf Series is divided into the following five groups: Navarro, Taylor, Austin, Eagle Ford, and Woodbine. The Comanche Series is divided into the following three groups: Washita, Fredericksburg, and Trinity.

The Taylor and Eagle Ford Groups consist predominantly of shale, limestone, clay, and marl and yield only small amounts of water in localized areas. The Navarro and Austin Groups consist of chalk, limestone. marl, clay, and sand and, except for the Nacatoch and Blossom Sands, yield only small amounts of water locally. The Nacatoch Sand of the Navarro Group and the Blossom Sand of the Austin Group yield small to moderate supplies of water to limited areas. The Woodbine Group is the only important aguifer of the Gulf Series in the area covered by this report. It consists of sand, sandstone, and clay and is capable of yielding small to large amounts of water. The Woodbine Group is discussed in detail in the sections covering the stratigraphy of the water-bearing formations and the occurrence and the availability of ground water.

Both the Washita and Fredericksburg Groups of the Comanche Series consist predominantly of limestone, shale, clay, and marl and yield only small, amounts of water to localized areas. The Trinity Group is the principal water-bearing group of rocks in the region and is divided into the Paluxy, Glen Rose, Twin Mountains, and Antlers Formations. The Paluxy consists of sand and shale and is capable of yielding small to moderate amounts of water. The Glen Rose is predominantly a limestone and yields small quantities of water only to localized areas. The Twin Mountains is composed of conglomerate, sand, and shale. It is the principal water-bearing formation of Cretaceous age in the region and yields moderate to large amounts of water. The name Antlers Formation is applied north of the Glen Rose pinch-out, where the Paluxy and Twin Mountains coalesce to form one unit. Water-bearing members of the Trinity Group are discussed in detail in the sections covering stratigraphy of the water-bearing formations and occurrence and availability of ground water.

The relationship, approximate maximum thickness, brief description of lithology, and summary of water-bearing properties of the stratigraphic units are shown in Table 1. Outcrop areas of the various formations are illustrated on the geologic outcrop map (Figure 16). The altitude of the top of the formations

and their net sand thicknesses are shown on Figures 18 through 22, 27, and 29.

Geologic cross-sections are profiles portraying an interpretation of a vertical section of the earth. Five geologic cross-sections were constructed; two are strike sections and three are dip sections. Dip sections are constructed approximately perpendicular to the strike of the beds and parallel to the dip of the beds, while strike sections are constructed parallel to the strike of the beds. These five geologic sections, illustrated on Figures 35 through 39, show the structure and stratigraphic relationships of the geologic units.

#### Structure

Pennsylvanian and Permian rocks in the outcrop along the west edge of the study area dip westward and northwestward at about 40 feet per mile (7.6 m/km). Permian beds probably extend not much farther eastward than Montague County. The Pennsylvanian sediments, which underlie the Gretaceous rocks in most of the remaining area, thicken from the outcrop eastward into the Fort Worth basin. The axis of this basin and many of the other major structural features in or near the report area are shown on Figure 4.


The Cretaceous System forms a southeastward-thickening wedge extending across the area into a structural feature known as the East Texas basin. Thickness of these rocks ranges from zero in the west to nearly 7,500 feet (2,286 m) in the southeast. Regional dip is east and southeast at rates of about 15 to 40 feet per mile (2.8 to 7.6 m/km). The dip rate increases to as much as 300 feet per mile (57 m/km) on the southeastward-plunging ridge called the Preston anticline. This anticline and an associated trough to the south (Sherman syncline) have caused a change in the regional outcrop pattern as shown on the geologic map (Figure 16).

Tertiary System beds dip regionally southeastward from the Mexia-Talco fault system, which extends in a northerly direction along the eastern margin of the report area, at a rate of about 100 feet per mile (19 m/km). Deviations from this dip rate occur locally due to the faulting. These beds attain a thickness of approximately 250 feet (76 m) within the area of study. However, just outside the area of investigation in southern Navarro County they reach a maximum thickness in excess of 1,000 feet (305 m).

Quarternary deposits occur along the floodplains of the Brazos, Red, Sulphur, and Trinity Rivers and

### Table 1.—Stratigraphic Units and Their Water-bearing Properties Yield, in gallons per minute (gal/min): small, less than 100 gal/min; moderate, 100–1,000 gal/min; large, more than 1,000 gal/min.

		· · · · · · · · · · · · · · · · · · ·	···-				
Era	System	Series	Group	Stratigraphic units	Approximate maximum thickness (feet)	Character of rocks	Water-bearing characteristics
	Quaternary	Recent		Alluvium	75	Sand, silt, clay and gravel.	Yields small to large amounts of water to wells
	Clusternary	Pleistocene		Fluviatile terrace deposits			along the Red River
Cenozaic	Y:	Eocene	Wilcox		100	Fine to medium sand with silt and clay	Yields small quantities of water to wells in the eastern part of the area.
	Tertiary	Paleocene	Midway		150	Gray, calcareous clay, in part silty to sandy	Do.
			-	Kemp Clay Corsicana Mari	300	Fossiliferous clay and hard limy mark	Not known to yield water to wells in the area.
		ľ	Navarro	Nacatoch Sand	500	Fine sand and marl, fossiliferous	Yields small to moderate quantities of water near the outcrop.
			Taylor	Maribrook Mari Pecan Gap Chalk Wolfe City - Ozan Formations	1,500	Cley, mari, mudstone, and chalk	Yields small quantities of water to shallow wells.
		Gulf	Austin	Gober Chalk B rownstown Marl B lossom Sand B onham Formation	700	Chalk, limestone, and marl; fine to medium sand, fossiliferous	Yields small to moderate quantities of water to wells in the northeastern part of the area; very limited as an aquifer.
			Eagle Ford		650	Shale with thin beds of sandstone and limestone	Yields small quantities of water to shallow wells.
			Woodbine		700	Medium to coarse iron sand, sandstone, clay and some lignite	Yields moderate to large quantities of water to municipal, industrial and irrigation wells.
Mesozoic	Cretaceous		Washita	Grayson Mari - Mainstreet Limestone Pawpaw Formation - Weno Limestone - Denton Clay Fort Worth - Duck Creek Klamichi Formation	1,000	Fossiliferous limestone, marl, and clay; some sand near top	Yields small quantities of water to shallow wells.
			Fredericksburg	Edwards Limestone Goodland Comanche Peak Formation Limestone	250	Limestone, clay, mari, shale, and shell agglomerates	Do.
		Comenche		Walnut Formation			
}				Paluxy Formation	400	Fine sand, sandy shale, and shale	Yields small to moderate quantities of wate to wells.
			Trinity	Antiers Glen Rose Formation	900   1,500	Limestone, marl, shale, and anhydrite	Yields small quantities of water in localized areas.
				Twin Mountains Formation	1,000	Fine to coarse sand, shale, clay, and basal gravel and conglomerate	Yields moderate to large quantities of water to wells.
Paleozoic				Paleozoic rocks undifferentiated		Sandstone, limestone, shale and conglomerate	Yields small quantities of water in the western part of the area.



# PA-SCORE REFERENCE 8

#### MITRE

26 May 1988

Ms. Lucy Sibold U.S. Environmental Protection Agency 401 M Street, S.W. Room 2636, Mail Code WH-548A Washington, D.C. 20460

Dear Ms. Sibold:

Enclosed is a copy of the draft revised HRS net precipitation values for 3,345 weather stations where data were available. The data are presented by state code, station name, latitude longitude, and net precipitation in inches. A list of state codes is also enclosed.

The net precipitation values are provided to assist the Phase II - Field Testing efforts. It is suggested that the value from the nearest weather station in a similar geographic setting be used as the net precipitation value for a site.

If there are any questions regarding this material, please contact Dave Egan at (703) 883-7866.

Sincerely,

Andrew M. Platt

Group Leader

Hazardous Waste Systems

AMP: DEE/hme

Enclosures

cc: Scott Parrish

#### STATE-NUMBER

Characters 1-2 Cooperative State Code for each State.

STATE CODE LISTIN	G
01 Alabama	28 New Jersey
02 Arizona	29 New Mexico
03 Arkansas	30 New York
04 California	31 North Carolina
05 Colorado	32 Morth Dakota
06 Connecticut	33 Obio
07 Delaware	34 Oklahoma
08 Florida	35 Oregon
09 Georgia	36 Pennsylvania
	37 Rhode Island
ll Illinois	38 South Carolina
12 Indiana	39 South Dakota
13 Iowa	40 Tennessee
14 Kansas	41 Texas
15 Kentucky	42 Utah
16 Louisiana	43 Versont
17 Maine	44 Virginia
	45 Washington
19 Massachusetts	46 West Virginia
20 Michigan	47 Wisconsin
21 Minnesota	48 Wyoming
22 Mississippi	49 Not Used
23 Missouri	50 Alaska
24 Montana	51 Havaii
25 Nebraska	66 Puerto Rico
A4 m	

#### STATION-NUMBER

DATA-CODE

Characters 3-6 Cooperative Station Number Range = 0001-9999.

#### Character 7 Data Indicator Code

26 Nevada

27 New Hampshire

- 1 Maximum Mean Temperature
- 2 Minimum Mean Temperature
- 3 Average (Hean) Temperature
- 4 Heating Degree Days 5 - Cooling Degree Days
- 6 Precipitation (1951-80 Normals only)

67 Virgin Islands

91 Pacific Islands

OBS	SIAIE	NAME	LAINUM	FONNUM	NETPREC
2696	41	LIVINGSTON 2 NNE	30.44	94.56	17.4546
2697	9.1	LLAND	30.45	98.41	3.2401
2698	41	CAMERON FT STOCKION KEST RADIO MADISONVILLE LAMPASAS TLMPLE MC CAMEY BRADY 2 NNW EDEN 1 LUFKIN FAA AP CENTERVILLE	30.51	96.59	6.7802
2699	41	ft Stockion KfSI RADIO	30.52	102.54	0.0006
2700	41	MADISONVILLE	30.57	95.55	12.8990
2701	41	LAMPASAS	31.03	98.11	5.9964
2702	41	TEMPLE	31.06	91.21	8.2039
2103	41	MC CAMEY	31.OR	102.12	0.0235
2104	41	BRADY 2 NNW	31.09	99.21	2.3916
2705	41	EDEN 1	31.13	99.51	1.6053
2106	41	LUFKIN FAA AP	31.14	94.45	14.1069
2707	41	CENTERVILLE	31.16	95.59	13.4505
2708	41	CROCKETT	31.18	95.27	14.7031
2709	ų i	MARLIN 3 MF	31.20	96.51	10.5747
2710	ă i	SAN ANGELO WSO R	31.22	100.30	0.6783
2111	- 41	CENTERVILLE CROCKETT MARLIN 3 NE SAN ANGELO WSO R PECOS GATESVILLE MACO MSO R	31.25	103.30	0.078
2712	Äi	CATERVILLE	31.26	97.46	6.9334
2713	äi	WACO WSO R	31.20		
2714	31	MACO MOO		97.13	6.7548
	41	MEXIA YSLETA BROWNWOOD BALLINGER 1 SW PALESTINE	31.41	96.29	12.6400
2715		PROMINOD	31.42	106.19	0.0144
2716	<u> </u>	BALLAMOTO 1 CL	31.43	98.59	3.6480
2111	41	BALLINGER 1 DW	31.44	99.58	1.8361
2718	51	PALESTINE WINK FAA AIRPORT	31.47	95.39	14.9654
2719	• 41	WINK FAA AIRPORT	31.47	103.12	0.0679
2120	• !	CENTER	31.40	94.10	19.7093
2121	41	RUSK	31.40	95.09	17.1421
2122	91	EL PASO WSO R	31.48	106.24	0.0366
2123	<b>91</b>	COLEMAN	31.50	99.26	2.6019
2124	41	WHITHEY DAM	31.51	91.22	8.7833
2125	41	MIDLAND WSO //R	31.57	102.11	0.1090
2126	41	LA TUNA 1 S	. 31.50	106.36	0.0908
2127	41	IIICO	31.59	98.02	6.6495
2120	41	HILLSBORO	32.01	97.07	9.8798
2129	41	MIDLAND 4 ENE	32.01	102.01	0.1717
2730	41	CORSICANA	12.05	96.28	12.6209
2731	41	DUBLIN	32.06	98.20	6.8356
2732	41	RISING STAR	32.06	98.58	4.4163
2711	41	HENDERSON	32.11	94.46	17.2371
2734	41	BIG SPRING	12, 15	101.27	0.5629
2115	41	CL EBURNI	32.20	91.24	7.9469
2116	41	LA TUMA I S HICO HILLSBORO MIDLAND & ENE CORSICANA DUBLIN RISING SIAR HENDERSON BIG SPRING CLEBURNE WAXAHACHIE	32.24	96.51	11.0671
2131	Äi	ABILINE WSO //R	12.25	99.41	1.9190
2738	61	NOSCOE	32.21	100.32	1.6700
2139	ši	MARSHAL L	32.32	94.21	19.1921
2140	ā i	KAUFMAN 3 SE	32.33	96.16	13.7363
2 /4 i	31	WILLS POINT	32.33 32.47	96.01	17.5271
2142	41				0.3682
2142 2143	41	LAMESA I SSE SMYDER	32.42	101.56	0.3052
2743 2744	41		12.41	100.55	0.3347
2144 2145		SIMINOLE	32.43	102.40	18.6724
	41	GILMER 2 W	32.44	94.59	
2146	41	ALBANY	32.44	99.18	3.2886
2147	41	WI ATHERFORD	32.46	97.49	7.8519
2/46	41	MINIHAL WILLS TAA AP	32.47	98.04	5.6707
2149	41	DALLAS (AA //R	12.51	96.51	9.7708
2750	41	DALLAS-FORT WORTH REG WSO	32.54	91.02	6.7013

her and environment

### PA-SCORE REFERENCE 9



#### SOILS ENGINEERING REPORT

# GROUNDWATER QUALITY ASSESSMENT PLAN GNB BATTERY PLANT FARMERS BRANCH, TEXAS

December 14, 1983 Job No. D-80154-8

Gould, Inc. 1110 Highway 110 Mendota Heights, Minnesota 55165

Attention: Mr. Everett Milton

Supervisor Facilities Planning

#### Gentlemen:

Presented herein is the groundwater quality assessment program required for compliance with Texas Water Development Board Industrial Solid Waste Rules, Texas Administrative Code (TAC), Section 335.194 (relating to Preparation, Evaluation, and Response) for the above-referenced facility. This plan is submitted in accordance with the verbal request and authorization of Mr. Everett Milton, as documented by Purchase Order No. 874-51183 dated November 15, 1983.

#### PURPOSE AND SCOPE

The purpose of this plan is to describe a groundwater quality assessment program that is more comprehensive than that described in TAC Sections 335.192 (relating to Groundwater Monitoring System) and Section 335.193 (relating to Sampling and Analysis) capable of determining:

- 1. Whether hazardous waste or hazardous waste constituents have entered the groundwater;
- 2. The rate and extent of migration of hazardous waste or hazardous waste constituents in the groundwater; and

3. The concentrations of hazardous waste or hazardous waste constituents in the groundwater.

The scope of this plan includes the evaluation of site utilization history, geology, hydrology, topography, containment measures and chemical analysis of both surface water and soil samples. Included in the groundwater quality assessment plan are specifications for:

- 1. The number, location and depth of wells;
- 2. Sampling and analytical methods for those hazardous wastes or hazardous waste constituents handled in the facility;
- 3. Evaluation procedures, including any use of previously gathered groundwater quality information; and
- 4. A schedule of implementation.

#### SITE DESCRIPTION

The project site is located in northeast Dallas County in an area underlain by alluvium and fluviatile terrace deposits in the Trinity River basin. These deposits consist of approximately 15 to 20 feet of silty clay, sand and gravel which are in turn underlain by highly plastic clay shale of the Eagle Ford formation. The site is flat to very gently sloping from north to south with a maximum surface gradient of approximately two percent. The local area has been extensively strip-mined for sand and gravel. Reclamation of the area has required extensive backfilling. Very few of the natural deposits above the groundwater table are believed to be undisturbed throughout the entire plant site. The static groundwater table appears to fluctuate between approximately five and ten feet below present grade. (Interpretations of groundwater contours based on a survey of monitoring well elevation differences and recorded depths of static groundwater elevations at equilibrium for the preceding ten months are presented on Plates I through 4 in the attachments to this submittal).

#### GROUNDWATER QUALITY MONITORING

Groundwater quality monitoring has been conducted on site for several years in two, and more recently, a total of five monitoring wells co-located with the waste management area on site. The two monitoring wells located on the east side and adjacent to the surface impoundment area were recently upgraded to include a surface seal and steel security cover. All five wells have been pumped and sampled quarterly beginning in March of 1982.

Results indicate that the specific conductance levels in representative groundwater samples have consistently been two to three times higher in the two monitor wells located on the east side and adjacent to the surface impoundment area. The concentrations of sodium and manganese have also appeared consistently higher in these same two wells. In general, chlorides and sulfates have been detected in all five wells at levels slightly to well above the Texas State Health Department Primary and Secondary Drinking Water Standards. However, it is significant to note that none of the parameters observed at concentrations above the interim primary or secondary drinking water standards are listed by the U. S. Environmental Protection Agency (U. S. E. P. A.) as being hazardous wastes or hazardous waste constituents.

In accordance with the Texas Administrative Code (TAC) Section 335.194(d)(1), a significant increase (difference) in the concentration or level of specific conductance, sodium and manganese has been detected in representative samples obtained from monitoring wells MW-N and MW-S located east of and adjacent to the waste management area as compared to samples obtained from the upgradient monitor wells, MW-1A and MW-3A. Accordingly, written notification of this observation must be submitted to the Execuive Director of the Texas Department of Water Resources (TDWR) which states that the facility may be affecting groundwater quality. Additionally, the owner or operator is required to develop and submit a specific plan for groundwater quality assessment in accordance with TAC Section 335.194(d).

#### GROUNDWATER QUALITY ASSESSMENT PLAN

The following plan is submitted in accordance with TAC Section 335.194 (relating to Preparation, Evaluation, and Response).

#### Groundwater Gradient Determination

Determination of groundwater gradients should be accomplished to verify or modify the existing groundwater monitoring system by installing several piezometers and monitoring the groundwater elevations in widely dispersed locations within the site boundary. The number of piezometers should be sufficient to allow development of groundwater contours across the entire site. It is recommended that approximately seven piezometers be installed to the depth of the underlying Eagle Ford shale (aquiclude) at the approximate locations shown on Plate 5. A ground level survey of these installations should be performed to document the relative elevation differences. Following equilibration with the static groundwater table, the depth at each location should be recorded and, along with groundwater elevation data obtained from the existing monitoring wells, contours of groundwater elevations should be developed. Should these contours indicate that a minimum of one monitoring well is not located upgradient and that a minimum of three monitoring wells are not located downgradient to the waste management area, the contours should be used to properly locate the required number of new wells.

#### Sampling and Analytical Methods

Installation of each piezometer should include the sampling of soil formations from the surface to the depth of the underlying shale aquiclude. Samples from each location should be visually identified and labeled as to soil type, depth, location and date of acquisition. Each soil sample should be tested for chemical composition in accordance with accepted

U. S. E. P. A. methods and procedures. Chemical analysis should include evaluation of the following parameters:

- 1. ph
- 2. conductivity
- 3. sulfate
- 4. chloride
- 5. lead (leachable)

Should assessment of groundwater gradients identify the need for additional groundwater monitoring wells, the well(s) should be installed as soon as technically feasible and sampled in accordance with TAC Sections 335.193 and 335.194. Analyses should be compared with all previous groundwater quality determinations to assess the need for further studies. Results should be submitted to the Executive Director, TDWR, in accordance with TAC Section 335.195 (relating to Recordkeeping and Reporting).

#### Evaluation Procedures

Evaluation of the results of soil and water sample analyses should be based on the previously reported groundwater quality analyses and the type of waste(s) managed on site. The need for additional sample acquisition and testing should be defined in accordance with the TAC Section 335.194.

Additionally, should the waste management area be identified as a source of contaminants identified in samples obtained during this assessment program, further subsurface sampling may be required to define the vertical and lateral extent of contaminant migration. These additional studies will generally be limited to locations accessible on site. However, should hazardous waste or hazardous waste constituents be identified, the scope of these studies may require evaluation of off-site locations. The scope of such additional studies should be defined in consultation with the TDWR.

#### Implementation Schedule

Implementation of the approved groundwater assessment plan should commence as soon as the results of analyses of downgradient groundwater samples obtained in accordance with TAC Section 335.194(c) confirm a statistically significant increase (or pH decrease) in comparison with the initial background arithmetic mean. A bar chart which indicates the time required for each task identified below and a schedule for completion of the groundwater quality assessment plan as submitted herein is presented on Plate 6. Eleven tasks are identified which include the following:

- 1. Setting piezometers (approximately seven) and obtaining both surface and subsurface samples;
- 2. Performing a surface survey to determine elevation differences between all piezometer locations;
- 3. Laboratory analyses of soil and surface water samples;
- 4. Assessment of laboratory results;
- 5. Piezometer water sample acquisition and testing (if required);
- 6. Development of groundwater contours;
- 7. Installation of additional monitoring wells, if required:
- 8. Sample the new monitoring well(s) and analyze the samples in accordance with TAC Section 335.193;
- 9. Additional sampling to determine the rate and extent of the hazardous waste or hazardous waste constituents in the groundwater, if required;
- 10. Additional chemical analyses, if required; and
- 11. Reporting results and making recommendations as required.

Should the groundwater contours confirm that the existing groundwater monitoring system is adequate, task numbers 7 and 8 will be eliminated. Should the results of soil quality assessment for upgradient locations reveal contaminants present at concentrations roughly equivalent to those observed downgradient to the waste management area, the need

for task number 5 will be eliminated. Should no hazardous wastes or hazardous waste

constituents from the facility be detected in the groundwater environment downgradient to

the on-site waste management area, the need for task numbers 9 and 10 will be eliminated.

The absence of detectable hazardous waste or hazardous waste constituents from the

facility in the groundwater environment will allow the reinstatement of the indicator

evaluation program described in TAC Section 335.193. However, the owner must notify the

Executive Director, TDWR, in the report containing the groundwater quality assessment.

The findings of the groundwater quality assessment investigation in accordance with

this plan must be completed and reported in accordance with TAC Section 335.194(d)(5).

Also, the owner must continue to evaluate the data on groundwater surface elevations at

least annually to determine whether the requirements under TAC Section 335.192 (relating

to Groundwater Monitoring System) for locating the monitoring wells continue to be

satisfied. The owner must immediately modify the number, location, or depth of the

monitoring wells to bring the groundwater monitoring system into compliance should this

evaluation show that TAC Section 335.192 is no longer satisfied.

This groundwater quality assessment plan does not relieve the owner of any

recordkeeping and reporting requirements outlined in TAC Section 335.195.

Should you have any questions or require additional assistance, please call.

Very truly yours,

NFS SERVICES, INC.


William Prikryl, P. E.

Project Engineer

WP/Icr


Copies submitted: 3

ILLUSTRATIONS




.:•.

Not to Scale **→** PB-5 <del>ф</del> рв -4 MW-1A MW-2A 90.65 PB-2 \<del>|</del> PB-1 Legend O Existing monitor wells OCTOBER 21, 1983
INTERPRETED GROUNDWATER CONTOURS Proposed piezometers



Not to Scale



NFS SERVICES, INC. CONSULTING ENGINEERS

O Existing monitor wells

Proposed piezometers

MARCH 25, 1983
INTERPRETED GROUNDWATER CONTOURS

Not to Scale <del>-</del> ₱ ₽В − 5 <del>-ф</del> РВ -4 MW-1A 0 PB-6 → MW-N MW-S PB-3 MW-2A Plant Valley PB-1 \* Optional C Existing monitor wells Proposed piezometers PLAN OF PIEZOMETER LOCATIONS

### PA-SCORE REFERENCE 10



U. S. Environmental Protection Agency Region VI - Water Supply Branch (6W-SP)

CURRENT AND PROPOSED

NATIONAL PRIMARY AND SECONDARY

DRINKING WATER REGULATIONS

AND

HEALTH ADVISORIES
FOR OTHER CONTAMINANTS

JANUARY 18, 1991

## CURRENT AND PROPOSED SECONDARY DRINKING WATER REGULATIONS

CONTAMINANT	MCL	
Aluminum (proposed)	0.05 to 0.2	mg/l
Chloride	250	mg/l
Color	15 (color un	nits)
Copper	1.0	mg/l
Corrosivity	noncorrosive	
Fluoride	2.0	mg/l
Foaming Agents	0.5	mg/l
Iron	0.3	mg/l
Manganese	0.05	mg/l
Odor	3 threshold	odor number
DH	6.5 - 8.5	
Silver (proposed)	0.1	mg/l
Sulfate	250	mg/l
Total Dissolved Solids (TDS)	500	mg/l
Zinc	5	mg/l

#### HELPFUL PHONE MURCHERS

EPA NQ. Washington, D. C. Safe Drinking Water Notline	600-426-4791
EPA REGION 6 Dallas TX 24 Hour Emergency Hotline Water Supply Branch (PTS Profix is 255)	214-655-2222 214-655-7155
APKAKSAS DEPARTMENT OF MEALTH 24 Hour Emergency Number Director, Division of Engineering	501-661-2136 501-661-2623
LOUISIANA DEPARTMENT OF MEALTH AND MOSFITALS Director, Division of Engineering	<del>504-568-</del> 5100
MEW MEXICO ENVIRONGEMENT INPROVEMENT DIVISION- Health Program Manager, Drinking Nater Section	505-427-2778
OKIAHOMA STATE DEPARTMENT OF MEALTH Administrative Chief, Meter Quality Service	405-271-5205

	CONTAMINANT	MCLG	MCL		RISK AT MCL
A	Lead		0.05		
	*Lindane	0.0002		•	
	Mercury	0.002	0.002		
	*Methoxychlor	0.04	0.04		
	*Monoch l'orobenzene	0.1	0.1		
	Nitrate	10	10		·
	*Nitrate plus Nitrite	10	10	•	
	*Nitrite	1	1		
	*PCBs	0	0.000	<b>)</b> 5	100E-6
	Radium 226 & 228		5.0	(1)	20E-6
	*Selenium	0.05	0.05		
	*Styrene	0.1	0.1		
	_*Tetrachloroethylene	0	0.005	j	7E-6
	*Toluene Total Trihalomethane *Toxaphene Trichloroethane 1,1,1- Trichloroethylene Vinyl chloride *Xylene	1 0 0.20 0 0	1 0.10 0.003 0.20 0.005 0.002	10	16E-6 65E-6 2E-6 30E-6
	Note: Units are milligrams pe (1) Picocuries per liter (2) Millirem per year (3) 0.05% dosed at 1 mg/	•			

(4) 0.01% dosed at 20 mg/l
\*Effective July 1992, supercede current MCLs for Cd-0.01, Cr-0.05, Se-0.01, 2.4.5-TP-0.01, 2,4-D-0.1, Lindane-0.004, Methoxychlor-0.1 and

Toxaphene-0.005 (all in mg/l).

### PA-SCORE REFERENCE 11



### QUARTERLY GROUND WATER MONITORING REPORT FOR HAZARDOUS WASTE FACILITIES

TWC Requestion No. or TSD Faculty Parms N

31697

T X 10 00 7 3 3 1 8 7 9

Comment was to M WI A

	Cone	•	*** 40		1 : 6
5-ad-a 1U er D1	Ų,	"	90	:=== {	0 1

TABLE 1 - SAMPL	E EVENT INFORM	ATION		_	(INTERIM P	ERMIT STATUS)		- Grapent IU	a. 01 [1] And 88 [3[0] \$20000 0 1
Sample Oate I.IM-O.D-Y.Y		Parameter ethod Code	Groundwater Elevation (ft.)				manage hazardous was	he owner/operator of a surface impoundment, landfill, or land to be. (See reverse side for instructions.)	ealment facility which is used to
03 - 09 :- 90	8 4 0 7 7 S	P: U   7202	0 428,20		•		Company Name: GNE 1880	Valley View Ln., Farmers Branch, Tx	75234
TABLE 2 - CONTA	MINATION INDIC	ATOR PARAMETE	ERS				Business Address:	z.	• — — — — —
Replicate Replicate Replicate Replicate Meso Variance T Valor Annest Meson Variance Theoretical Services Theoretical Services	Parameter   Para	Standard U   Grab	Pursettr   Code	Grab    3 5 00 0     3 2 5 0 0     3 2 5 0 0     3 3 9 0 0     1 8 3 3 3 3     -10 1 3 9 8 6 0     1 1 4 3 6 1 2     Persentir	Total Organic Carloss	077	Total Organic Halayan Grab    01   4  5     02   4  5     03   4  5     04   4  5     05   6  6  6  6    07   07     08   07     09   07     09   08     09   08     09   08     00   08	SAMPLE ANALYSES QUE  1) Were all samples filtered prior to analysis? Q yes If no, indicate which samples were not filtered.  2) Wes total organic Halogen measured with a DX20 in If no, explain	Strument? □ yes 3E no
ABLE 4 - PRIMAR Portmeter Code T 10 37 Portmeter Code T 10 37 Portmeter Code T 9 4 37 Portmeter Code 1 1 27 Portmeter Code 1 27 Portmeter Code 2 27 Portmeter 2 27 Portmete	SO DRINKING WAA Arresit and Carlo Ca	TER STANDARDS  Personeter Code 1 1 10 0 123 28 64 Personeter Code 0 0 8 29 Personeter Code 0 1 1 0 0 20 As Personeter Code 0 1 1 0 0 30 As	Barien mg/l Grab States	remeter Code 10 2 11 02	Personatur	bremisch gericht der State	Grid Grid Grid Grid Grid Grid Grid Grid	Personner   Code   Co	

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that breed on my inquiry of those individually immediately, responsible for obtaining the information. I believe that the submitted information is true, occurate and complete.

April 26, 1990

Separate of Authorized Agent

THE COTO (P.S., 10-0



#### TX D 00 7 3 3 1 8 7 9

GROUND WATER MONITORING REPORT FOR HAZARDOUS WASTE FACILITIES

T. D. C C	E EVENT INFORMATION			(INTERIM PERMI	T STATUS!		Gradual II	or 01 D vom 18 90 1 1 more 0
TABLE I - SAMPLE	E EASUL WALCHWALLOW		٦	•				13 19 19
Sample Oute	Parameter Sample Param	Groundweter Groundweter			r.		er/operator of a surface impoundment, landfill, or land t e reverse side for instructions.)	treatment facility which is used to
1.1M-DO-YY	Code Method Cod	de Elevation (ft.)	1			•		214 247 1011
03 - 09 - 90	8 4 0 7 7 SPUN 7 2 0	20 14127 62	7		C	omeenv Name: GNB, Inc	ey View Ln., Farmers Branch, Tx	Phone: (214)243-1011 75234
21	30 30 41		=		8.	usiness Address:	ey rica bill, t at more breaken, the	L·o:
TABLE 2 · CONTAI	MINATION INDICATOR PARAM	ETERS						
	Parameter	PH Parameter	Conductivity Parameter	Total Organic Carbon	Parameter T	Fotal Organic Halogen	SAMPLE ANALYSES QU	ESTIONS
į l	ESI Code	rd Units Code	μ mhes Code	mg/l	Code	/¹    1)	Were all samples filtered prior to analysis? I yes	S no
		16 74 0 0 0 9 S	Grab 	Grab TT 1911 3 1		Grab	If no, indicate which samples were not filtered	<del></del>
Replicato				┥┠ <del>┆╏╏╬╬┩╗┋╘</del> ┪	}	<del>- 1111</del> 1		<del> </del>
Replicate	0 2 0 0 4 0 0 1 1 1	6 76 00095	3300 0068	┫┞ <del>╏╏╏╏</del>	<del>    </del>	1 0 0 0 4 1 2	Was total occasic Halosen measured with a OX20 i	instrument? 7 ves 7 no
Replicate	04 004 00	6 76 00095	34dd 0068	┪┞ <del>┆┆╏</del> ╀╬┼┼┼	} <del></del>	<del>                                      </del>	Was total organic Halogen measured with a OX20 in the property of the Used DX-15 instrument	
Mean	$\vdash$	6 76 00095	111113300 0000	<del>                                  </del>	i	0 0 4 2 5		
Variance	7 1 0 0 4 0 0 1 1 0	) . P D D	0.007 008	1 10 0000		. D D D D D Z 5	Which method was used for the Coliform Bacteria	and D same Char
T Value		03,00 0005	1-6246.2 0068	19265 237	H17	1 15 0000 3	fermentation tube other None	(ett. D membrane miter
*Annual Mean	90 00400	7 27 00005	3735 0008	1 12 65		0 3 3		
al Variance	91 00400	0 08 00005	683988 0068	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		0 376		
* See Instruction 68	21 24 30		17 68	4	76 81			
TABLE 3 - GROUN	D WATER QUALITY INDICATO	RPARAMETERS	· · · · · · · · · · · · · · · · · · ·					
Parameter Code	Chloride mg/l Cod	es Grab	Parameter Code Crab	Personeter Code	Greb	Purameter Sodin	Code mg/l	La <del>ž</del> vija
	TY DRINKING WATER STANDA	RDS PARAMETERS		75 67	•4			
Parameter Code T 1 0 0	Arsanic mg/l Code T 1 0 0	Barium mg/l Grab	Code Cadroium mg/l Grab	Pursaneter Chroming/ Chroming/ Code Crob	Cade	1 997	Persontar Code Grab Grab 112 123	
	Marcury mg/l Purameter Cade Gtb U 0 6 38 Mathewythler mg/l Persenser	Grab	2,4-0	Parameter   Code   Crob   Cr	Code T 9 3 8	Gree Gree	Personator Code   Tight   Tigh	•
T 9 4  21  27  Peramotar  Code	Grab Code TS 4 38 Gram Alpha Grab Code D150	as SE Gross Alpha Counting Error	773 Green Boto Code Green Green Green	Code Gross  72  Pursanting Counting Code Counting C350	99 bru Peremete		Code Counting Error 0 3 115 0 115 0 117 15 0 1 127 15 0 1 127 15 0 1 127 15 0 1 127 15 0 1 127 15 0 1 127 15 0 1 127 15 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
3, 2,	39	1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.		72 18	•••	96	108 112 123	5.3. T.

d certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all stached documents and that based on my indury of those individuals immediately responsible for obtaining the information. I believe that the submitted information is true, accurate and complets.

April 26, 1990

Procedure of Authorised Agrical Agri

TABLE 1 - SAMPLE EVENT INFORMATION



### QUARTERLY GROUND WATER MONITORING REPORT FOR HAZARDOUS WASTE FACILITIES (INTERIM PERMIT STATUS)

or TSD Facility Parms 1

311697

TX 007 33 18 7 9

Comment well No M W3 A

Gree.em; IV e: 01 U	19 910 1000	<u> </u>
 familiar and treatment facilities		

Sample Date RIM-DD-YY	Parameter Code	Sample Method	Parameter Cade	Groundwater Elevation (ft.)					monage hazardous was	to, (See	reverse tide for instructional.  Phone: (214)243-1011
03 - 09 :- 90	8 4 0 7 7	SPUN	72020	4[2]8; 218;						Valle	v View Ln., Farmers Branch, Tx 75234
ABLE 2 - CONTAI	MINATION IN	DICATOR	PARAMETERS	<u> </u>					Business Address:		Zio:
	Number Number Co	1.1	PH Standard Units Grab	Parameter Code	Conductivity Lanket Grab	Parameter Code	Total Organic Carbon mg/l Grab	Parameter Code	Total Organic Hulopen mg/l Grab	1,j	SAMPLE ANALYSES QUESTIONS  Were all samples filtered prior to analysis? ② ves □ no
legicate	0 1 0 0		1		11750	0068	311.51		0.02	į	If no, indicate which samples were not filtered.
leplicate	0 2 0 0				11750	0088		<u> </u>	0,011		
leplicate Replicate	0 3 0 0 4		61.	93 00095	<del>                                     </del>	0068	1 1 1 1 1 1 1 1		0:-02	21	Was total organic Hatogen measured with a DX20 instrument? □ ves 型 no tf no, exolain Used DX-15 instrument
Aeen	7 0 0 0		1 16	66 0005	11750	0061					
/arisaça	7 1 0 8 4	00		02 0 0 0 9 5	0.007	0068	10.0000		-22.517	33	Which method was used for the Coliform Bacteria test?   membrane filter
Value	7 2 0 0 4	<del></del>		30 00005	-43478	0068	1235 422		0.08	"	☐ fermentation tube ☐ otherNone
Annual Mean	9 0 0 0 4		<del>                                     </del>	35 00005	3 1 0 8 3	0068	116-25		<del>                                   </del>	l	
** SI Variance	21 24	<del>'</del> -	111119	140 8 8 8 8 3	111134464	54	1 1 1 4 4 - blot 1 7	76	ורודודודוווו	L	
ABLE 3 - GROUN	D WATER OU	ALITY IND	CATOR PAR	AMETERS							
Perameter Code	Chleri my/ Grab			Iron	Porsmeter Code	Mangasess mg/l Greb	Parameter Code	Phenots sug/i Grab	Personeter Code 099 92 93	Sedimo mp/I Grab	Parameter Sufface mg/1 Code Crob 118
ABLE 4 - PRIMAR	Armeis	$\neg$		Bring	Ceda		Chrem				ا لــــــــــــــــــــــــــــــــــــ
Code T 1 0 0	mg/l Grab	Peram Co	de L	Grab	Code Gr	<u>,                                     </u>	Code Gra	n [ ]	Personeter Personeter mg/l Code Greb	Ш	Parimeter
Parameter Code	Mercury medi Grete	Po 200 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Netrate mg/l Grab		Museum p/1 ab	Costs Costs	<u> </u>	Parameter Code Grab		Parameter Undered Option Code Code Code Code Code Code Code Code
Cade	Marthan yethlor mapt Grat	7 9 4		Grad	Code G:				Personatur Code 11503 95	Ш	106
	Gross Algeba pCits Grass	Param Cod 0151	<u>.    </u>	surrang Error	Coort G.	<u> </u>	Cook Caseming	Error .	Percenture Code Code 2159		Lead, HGA Coda 113  Lead, HGA 0 4 123

errify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that based on m unity of shose individual immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete.

Tec-0010 (ha., 10-03-05)

Cade

Com

T 9 4

008

Paramen Code

0150

T 9 4



### FOR HAZARDOUS WASTE FACILITIES

TX 00073311879

		MIN	. 5
	 ~•	,	**

GROUND WATER MONITORING REPORT (INTERIM PERMIT STATUS) TABLE 1 - SAMPLE EVENT INFORMATION Sample Date Elevation (ft.) Code NM.DO.YY Code Merhad Phone: (214)243-1011 75234 03 - 09 - 90 8 4 0 7 7 SPUN 7 2 0 2 0 14261-1221 1880 Valley View Ln., Farmers Branch, Tx TABLE 2 - CONTAMINATION INDICATOR PARAMETERS Tetal Organic SAMPLE ANALYSES QUESTIONS Parameter Parameter Carbon mg/l Standard Units Code Code Code Code Were all samples filtered prior to analysis? I ves I no Cost Cesh If no, indicate which samples were not filtered. .. 0.09 1 6 6 6 Replicate 0 0 4 0 0 00095 .... 1 16.184 0.09 6.70 Replicate 0 0 4 0 0 0 0 0 9 5 0053 0.14 Was total organic Halogen measured with a DX20 instrument? ves in o if no, explain Used DX-15 instrument 0088 0.3 0 0 4 0 0 00095 Replicate 0 0 0 9 5 0068 Reglicate 04 00400 0 . 0 0 1 0 2 5 0 . 1 3 2 7 5 0 . 3 3 3 0 . 3 7 6 7 0 0061 00400 0 0 0 8 5 Mean 00400 0065 Which method was used for the Coliform Bacteria test? 

membrane filter 0 0 4 0 0 T Veloe 0061 90 00400 \*Annual Mass 0068 · I Variance 0058 \* See Instruction 68 21 24 30 41
TABLE 3 - GROUND WATER QUALITY INDICATOR PARAMETERS O Replicate Parameter mg/l Grat mg/l mg/l mg/1 -----/ Code Code Code Code Code Code Grab Creb Crak Genh 0094 00940 T104 T105 T 2 7 3 TABLE 4 - PRIMARY DRINKING WATER STANDARDS PARAMETERS Fluorida mg/1 Grah 0 1 mg/l Grab Cade Code Code < | i | 0.005 T10 T100 11.11 T100 T102 T103 0095

T107

Carde

Code

0350

Paramet Code

T839

Code

11503

Personal Code

3150

-

11504

der penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that based on those individualy immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete.

April 26, 1990

0360

шиш

TU4

Cardo

1973



### QUARTERLY GROUND WATER MONITORING REPORT FOR HAZARDOUS WASTE FACILITIES

TWC Repetration No to ISS Facility Parms No 3 1 6 9 7

Tx 0007331879

Campony well No M W- N

TABLE I - SAMPLE	E CUENT INSC	BMATION					(INTERIM PERM		TIES		Grammar (U. gr O) D Year 18 90 Samper 0.
Sample Date AIM-0 D-YY	Parameter Code E 4 0 7 7	Sample Method S P! U )	Paremeter Cade 7 2 0 2 0	Groundwater Elevation (ft.)					menage hazardous well Company Name: GNI	10. (See 3. LOC.	//operator of a surface impoundment, lendfilb, or land treatment facility which is used to reverse tide for instructional.    Phone: (214)243-1011
Replicate Replicate Replicate Replicate Replicate Aprec Verticate Area T Value **Annual Meso **at Variance **at Va	MINATION INI  THE STATE OF THE	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	FM Standard Units Great	Permeter Code (9 5) (9 3) (0 0 0 9 5 (9 3) (0 0 0 9 5	Conductivity  µ mater  Grab  55500  55500  55500  0.00744  42743  37556683988	Personetter Code  0.068 0.068 0.068 0.068 0.068 0.068	Total Organic Carbon may!    S	Parameter Code	Total Organic Hotopyol - Grah    O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O    - O   O   O   O   O    - O   O   O   O   O    - O   O   O   O   O    - O   O   O   O   O    - O   O   O   O   O   O    - O   O   O   O   O   O    - O   O   O   O   O   O    - O   O   O   O   O   O   O    - O   O   O   O   O   O   O   O    - O   O   O   O   O   O   O   O   O   O	2)	SAMPLE ANALYSES QUESTIONS  Were all samples filtered prior to enalytis? **\$\text{\$\texitt{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\te
See Instruction 68 TABLE 3 - GROUN  Parameter Code 0 1 0 0 9 4 0	D WATER QU. Chloris uspf	ALITY INC	Parameter Code T 1 0 4	AMETERS  tros  mg/l  Grab	Personter Code T105 08	Managements mg/l Grab	Parameter Code T273 81	Phoneis mg/l Grab	Purmetur Code	Sodium mg/l Grah	Parameter   Subtree
Personeter Code T100 1 27 Personeter Code T20 27 Personeter Code T30 27 Personeter Code T30 27 Personeter Code T30 27 T30 27 T31 27 T31 27 T32 27 T33 27 T34 27 T35 27 T37	Artenic mg/l Grab  i       Marcury mg/l Grab          Marcury mg/l Grab          Grab Grab Grab	Pursa Co	ode 0 an an an an an an an an an an an an an	Grab  Mitrata mg/l Grab  Mitrata mg/l Grab  Ya.185/hore mg/l Grab  Grab  Grab  Grab  Grab  Grab  Grab  Grab  F  Grab  Grab  Grab  F  Grab	resmeter Code (7)	O O O O O O O O O O O O O O O O O O O	78 Personeter Code T107 78 Forumeter Code Code Code Code Code Code Code Code	Short of the state	Parameter Code   Parame		Persureter   Code   Cone   Cone   Code   C

certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that based on migury of those individuals immediately responsible for obtaining the information. I believe that the submitted information is true, acquiate and complete.

April 26, 1990

TWC-0810 (Rev., 10-03-65)

### PA-SCORE REFERENCE 12

#### **RECORD OF COMMUNICATION**

Reference 12

TYPE:

Telephone Call

DATE:

2/2/93

TIME:

1010

TO:

Richard Cannon, Water Dept., City of Farmers Branch (214)

FROM:

B. Kendrick, Geologist, ICF

Technology, Inc. (214) 979-

3905

919-2597


SUBJECT: Water Supply for the City of Farmers Branch

#### **SUMMARY OF COMMUNICATION:**

Water is purchased directly from the City of Dallas. Farmers Branch distributes the water to connection within the city boundaries. The City of Dallas receives its water supply from surface water reservoirs. There are no municipal water wells. There may be a few private water wells within the city boundaries, but he does not have specific information concerning their existence.

### PA-SCORE REFERENCE 13

Herschfield. D.M., 1961, Rainfall Frequency Atlas of the United States. U.S. Weather Bureau Technical Paper No. -0.



# TEXAS WATER COMMISSION / Permanent Rule Changes

Chapter 307

### Texas Surface Water Quality Standards

\$\$307.2-307.10

Effective: July 10, 1991

- 1. Purpose. This change transmittal provide new adoptions to the Texas Water Commission Volume of Permanent Rules.

  2. Explanation. The Texas Water Commission adopted the repeals
- 2. Explanation. The Texas Water Commission adopted the repeals of \$\$307.2-307.10 and new \$\$307.2-307.10, entitled "Texas Surface Water Quality Standards." New \$\$307.2-307.6, 307.8-307.10 were adopted with changes to the proposed text as published in the December 25, 1990, issue of the Texas Register (15 TexReg 7495). Section 307.7 was adopted without changes. Please replace the existing Chapter 307 with the attached Chapter 307. Also attached is a Chapter 307 index reflecting a new printing date and any new changes brought about by this adoption.

anaerobic condition that supports the growth and regeneration of hydrophytic vegetation. The term "hydrophytic vegetation" means a plant growing in: water or a substrate that is at least periodically deficient in oxygen during a growing season as a result of excessive water content. "wetland" does not include irrigated acreage used . as farmland; a man-made wetland of less than one acre; or a man-made wetland not constructed with wetland creation as a stated objective, including but not limited to an impoundment made for the purpose of soil and water conservation which has been approved or requested kby soil and water conservation districts.

- Zone of initial dilution The small area at the immediate point of discharge where initial dilution with receiving waters occurs, "and which may not meet certain criteria applicable to the receiving water A zone of initial dilution is substantially smaller than a mixing zone. The state of the s
- Abbreviations. The following abbreviations apply to this chapter: his chapter:
  (1) AP - aquifer protection.

  - (2) BMP best management practices.
  - (3) AS - agricultural water supply.
  - 一年 经国际管理的 医电影 (4) CFR - Code of Federal Regulations.
  - (5) CR contact recreation.
  - (6) CPP continuing planning process. The state of the s
  - (7) DO dissolved oxygen.
  - (8) E exceptional quality aquatic habitat.
  - Environmental (9) EPA - U.S. Environmental Protection Agency.

  - (10) °F degree(s) Fahrenheit.
    (11) ft<sup>3</sup>/s cubic feet per second.
  - A CONTRACTOR OF THE PROPERTY O (12) H - high quality aquatic habitat.

- (13) I intermediate quality aquatic habitat.
- (14) IS industrial water supply.
- (15) L limited quality aquatic habitat.
- (16) mg/l milligrams per liter
- (17) ml milliliter.
- (18) N navigation.
- (19) NCR noncontact recreation.
- (20) NPDES National Pollutant Discharge Elimination system, as set out in the Clean Water Act, §402 (33 United States Code 1342).
- (21) O Oyster Waters.
- (22) PS public water supply.
- (23) 7Q2 seven-day, two-year low flow.
  - (24) TDS total dissolved solids.
  - (25) USFDA U.S. Food and Drug Administration
  - (26) USGS U.S. Geological Survey.
  - (27) WQM water quality management.


### §307.4. General Criteria.


Application. The general criteria set forth in this (a) section apply to surface water in the state and specifically apply to substances attributed to waste discharges or the activities of man. General criteria do not apply to those instances in which surface water, as a result of natural phenomena, exhibit characteristics beyond the limits established by this section. General criteria are superseded by specific exemptions stated in this section or in \$307.8 of this title (relating to the Application of Standards), or by site-specific water quality standards for classified segments. Provisions of the general criteria remain in effect in mixing zones or below critical low-flow conditions unless specifically exempted in \$307.8 of this title (relating to the Application of Standards).

				ES		CRITERIA							
Secreent Number	TRINITY RIVER BASIN SECHENT NAME	KECKLION	AQUATIC LIFE	DOGESTIC WATER SUPPLY	CTHER	CHLORIDE (mg/L) Annual sverege not to exceed	SULAIE (ng/l.) Amual sverage not to exceed	TOTAL DISSOLVED SOLIDS (mg/L) Amuel everage not to exceed	DISSOLVED OXYCEN (mg/L)	pe rance	FECAL COLIFORM (0/100 mL) Thirty-day geometric maen not to exceed	IDPERATURE (°F) Hoe eo excess	
0801	Trinity River Tidel	CR.	198				ر.		4.0	6.5-9.0	200	95	
0802	Trinity River Below Lake Livingston	CR	00	PS.		125	100	600	5.0	6.5-9.0	200	93	
0803	Lake Livingston	CR.	111	PS		150	50	500	5.0	6.5-9.0	200	93	
0804	Trinity River Above Loke Livingston	CB.	81.		3	150	150	. 600	5.0	6,5-9.0	200	93	
0805	Upper Trinity River.	CB .	O .			. 175	175	850	ş,0°	6,5-9.0	200	95	
0806	West Fork Trinity River Below Lake Worth	CI.	80	^P8		100	100	500	5.0	6,5-9.0	200	93	
0807	Loke Horth	CR	Н.	. P8	*	100	100	500	5,0	6.5-9,0	200	91	
0808	West Fork Trinity River Below Regle Hountain Reservoir	, CR		. P8	4,5	→ 100	100	.5. <b>500</b>	5.0	-6,5-9.0	200	91	
0809	Ragle Hountain Reservoir	CR.	H	. PS .		75	., . 75	300	5.0	6.5-9.0	200	94	
0810	West Fork Trinity River Below Bridgeport Reservoir was	.ca.,	ب. B	PS	وحوصو	. 100	100	<b>500</b>	5.0	6.5-9.0	200	90	
0811	Bridgeport Reservoir	, CR	II	. P8 🖏	-	162°.75	<b>75</b>	.; <b>300</b>	5,0	6.5-9.0	200	90	
0812	West Fork Trinity River Above Bridgeport Reservoir	į CR	s H	∴ PS :		100	100	500	5.0	6.5-9.0	200	88	
0813	Houston County Lake	, CR		PS		. 75	, 75	300	5.0	6.5-9.0	200	93	
0814	Chambers Creek Above Richland-Chambers Reservoir	.CR	OR .	PS	,	, <b>90</b>	160	500	5.0	6.5-9.0	200	90	
0815	Bardwell Reservoir	CR.	R .	PS		. 50	50	300	5.0	6.5-9.0	200	91	
0816	Lako Waxahachio	CR	98 .	PS	9.3	50	50	300	5.0	6.5-9.0	200	91	
0817	Navorro Milla Lake	CR	H	PS		50	75	300	5.0	6.5-9.0	200	90	
0818	Cedar Creek Reservoly	CR.	14	P8	·	. 50	. 50	200	5.0	6.0-8.5	200	93	
0819	East Fork Trinity River	CR	I			75	50	400	4.0	6.5-9.0	200	121	
2000	Lake Ray Hubberd	G	H	PS		40	50	400	5.0	6.5-9.0			

dissolved oxygen criterion in Segment 0805 shall be 3.5 mg/L beadwater flow at USCS Coging Station 08048000 learners of the second oxygen criterion in Segment 0805 shall be 3.5 mg/L beadwater flow at USCS Coging Station 08048000 learners of the second oxygen criterion in Segment 0805 shall be 3.5 mg/L beadwater flow at USCS Coging Station 08048000 learners of the second oxygen criterion in Segment 0805 shall be 3.5 mg/L beadwater flow at USCS Coging Station 08048000 learners of the second oxygen criterion in Segment 0805 shall be 3.5 mg/L


\$ 2"





# Water Resources Data Texas Water Year 1989

Volume 1. Arkansas River Basin, Red River Basin, Sabine River Basin, Neches River Basin, Trinity River Basin and Intervening Coastal Basins



U.S. GEOLOGICAL SURVEY WATER-DATA REPORT TX-89-1 Prepared in cooperation with the State of Texas and with other agencies

### CONTENTS

	Page
Preface	iii
are published	
Introduction	
Cooperation	
Hydrologic conditions	3
Streamflow	3
Water quality	· · · · <u>5</u>
Special networks and programs	7
Explanation of the records	8
Station identification numbers	8
Downstream order numbering	8
Records of stage and water discharge	9
Data collection and computation	9
Data oresentation	
[dentifying estimated daily discharge	13
Accuracy of the records	13
Other records available	14
Records of surface-water quality	14
Classification of records	14
Arrangement of records	15
On-site measurements and sample collection	15
Water temperature	16
Sediment	16
Laboratory measurements	16
Data presentation	17
Remark codes	18
Access to WATSTORE data	18
Definition of terms	19
Publications of techniques of water-resources investigations	31
rubications of techniques of water-resources investigations	33
Gaging-station records	
Discharge at partial-record stations and miscellaneous sites	492
Low-flow partial-record stations	492
Crest-stage partial-record stations	493
Discharge measurements at miscellaneous sites	495
Index	497

### IILUSTRATION

Figure	1.	Area of Texas covered by volume 1 and location of selected	
3		streamflow and water-quality stations in volume 1	4
	2.	Comparison of monthly mean discharge at four long-term	
•		representative gaging stations during the 1988 water year	
		with median of the monthly mean discharge for the period	
		1951-80	- 6

### 08055500 ELM FORK TRINITY RIVER NEAR CARROLLTON. TX

LOCATION.--Lat 32°57'57". long 96°56'39", Dallas County, Hydrologic Unit 12030103, near left bank at downstream side of bridge on Sandy Lake Road, 40 ft upstream from Carrollton Dam, 0.3 mi downstream from Denton Creek, 1.0 mi upstream from St. Louis Southwestern Railway Lines bridge, 2.3 mi northwest of Carrollton, and 18.2 mi upstream from mouth.

DRAINAGE AREA . -- 2.459 mi2.

PERIOD OF RECORD.--January 1907 to current year. Monthly discharge only for some periods, published in-WSP 1312. Prior to November 1923, published as "near Dallas".

REVISED RECORDS.--MSP 788: 1924. MSP 1148: Drainage area at former site. MSP 1632: 1908(M). WSP 1922: Drainage area.

GAGE (revised).--Water-stage recorder and concrete control. Datum of gage is 431.40 ft National Geodetic Vertical Datum of 1929. Prior to November 1923, nonrecording gage at site 15.5 mi downstream at different datum. Nov. 1, 1923, to Nov. 13, 1934, nonrecording gage, and Nov. 14, 1934, to July 6, 1938, water-stage recorder at present site and datum. July 7, 1938, to Apr. 14, 1939, nonrecording gage at site 9.3 mi downstream at datum 22.94 ft lower. Apr. 15, 1939, to Sept. 30, 1955, water-stage recorder at site 8.5 mi downstream at datum 22.94 ft lower. Oct. 1, 1955, to Sept. 30, 1987, water-stage recorder at present site and at datum 2,00 ft higher.

REMARKS..-No estimated daily discharge. Records good. Flow is largely regulated by Lewisville Lake (station 08052800) since November 1954, and by Grapevine Lake (station 08054500) since July 1952. The city of Dallas diverts water from the pool at gage and from the river 14 mi downstream for municipal use. A water treatment plant returns water to the river below this station. In addition, Dallas Power and Light Co. diverts water from pool at gage into North Lake for cooling water at their electric generating plant. Several observations of water temperature were made during the year. Gage-height telemeters at station.

AVERAGE DISCHARGE. --47 years (water years 1908-54) prior to regulation by Lewisville and Grapevine Lakes, 818 ft'/s (592,600 acre-ft/yr); 35 years (water years 1955-89) regulated, unadjusted, 744 ft'/s (539,000 acre-ft/yr).

EXTREMES FOR PERIOD OF RECORD (revised).--Maximum gage height, about 19 ft May 25, 1908, present site and datum, from information by local resident; estimated discharge, 145,000 ft²/s, at site 8.5 mi downstream (from information by U.S. Army Corps of Engineers); maximum gage height subsequent to 1908, 16.5 ft Apr. 26, 1942, present site and datum, from observation by National Neather Service; discharge at site 8.5 mi downstream, 90,700 ft²/s; no flow at times. Flood in 1866 reached about the same stage as flood of May 25, 1908.

EXTREMES FOR CURRENT YEAR. -- Maximum discharge, 8,720 ft 3/s May 17 at 0900 hours (gage height, 9.73 ft); no flow Dec. 3-

DISCURDES CHRIS SEET DER SECOND MATER VEAR SETTRES LOSS TO SCRIPTURES LOSS

		DISC	ARGE, CUB	IC FEET PER	SECOND,	, WATER YEAR 4EAN VALUES	OCTOBE	R 1988 T	O SEPTEMBE	R 1989		
DAY	OCT	NOV	DEC	JAN	FEB	HAR	APR	HAY	JUM	JUL	AUG	SEP
1	45	105	. 77	3.6	189	271	330	125	1380	6730	5290	118
2	67	96	172	7.8	69	270	299	124	1840	6850	5310	125
2 3 4	43	92	40	3.8	50	274	275	419	2650	7220	5320 5250	190
	36	96	.00	4.2	25	290	626	161	4500	4570	5250	140
5	41	166	29	24	26	293	1300	878	1310	5210	5140	171
6	48	142	36	40	45	301	1590	142	195	6290	4760	258
7 B 9	84	128	79	31	34	307	1600	184	5090	6610	4450	197
8	88 98	119	44	54	27	296	1620	145	3970	6750	4030	151
.9	98	104	99	66	29	289	1640	149	482	6750	3640	195
10	90	78	59	34	18	280	1630	124	184	6730	3600	86
11	64	77	64	62	35	277	1570	92	323	6730	3280	432
12	101	100	17	118	62	268	1260	85	1570	6680	2420	149
13	107	85	24	41	71	267	1100	122	3800	6640	2100	762
14	68	87	32	37	46	266	989	135	5030	6660	1950	183
15	41	100	16	35	261	222	129	141	5480	6740	1680	217
16	71	50	18	32 28 32	593	166	687	1320	4980	6680	1670	164
17	93	64	19	28	2500	140	645	7380	3850	6640	1870	123
18	108	7.9	20	32	828	139	333	1330	2950	6600	1790	127
19 20	129	136	17	43	95	154	210	159	2320	6580	1750	165
20	61	49	21	93	47	184	122	39	1750	6560	1720	89
21	56	37	14	119	45	513	112	159	1350	6540	1640	133 133
21 22 23 24 25	95	81	21	196	47	428	107	115	1060	6350	1470	133
23	126	86	11	204	115	368	112	75	1140	6080	1400	155
24	191	81	7.1	210	142	188	149	87	2350	6020	1380	135
25	225	82	11	499	259	141	149	100	3720	5700	1340	119
26	209	103	7.9	722	272	149	116	75	4030	5570	1220	9 <del>9</del> 102
26 27 28 29 30	169	94	46	94	275	172	85	130	5420	5350	1160	102
28	156	86	21	1300	272	3780	95	366	5910	5250	1160	54
29	134	85	6.0	440		908	116	344	6380	5280	1140	117
30	112	80	8.2 5.3	87		98	107	423	6570	5300	722	202
31	120		5.3	240		300		906		5270	209	
TOTAL	3076	2768 92.3	1041.50	4900.4	6477	11999	19703	16034	91584	192930	79861 2576	5291
MEAN	99.2	92.3	33.6	158	231	387	657	517	3053	6224		176
MAX	225	166	172	1300	2500	3780	1640	7380	6570	7220	5320	762
MIN	36	37	.00	3.6	18	98	85	39	184	4570	209	54 -
AC-FT	6100	5490	2070	9720	12850	23800	39080	31800	181700	382700	158400	10490
CAL VO	1988	TOTAL .	41418.50	MEAN 11	MAX E	801 MIN	.00	AC-FT	82150			

CAL YR 1988 TOTAL 41418.50 MEAN 113 MAX 801 MIN .00 AC-FT 82150 WTR YR 1989 TOTAL 435664.90 MEAN 1194 MAX 7380 MIN .00 AC-FT 864100

### 08057000 TRINITY RIVER AT DALLAS. TX

LOCATION.--Lat 32°46'29°, long 96°49'18°. Dallas County, Hydrologic Unit 12030105, on right bank (levee) 90 ft downstream from Commerce Street viaduct in Dallas, 5.2 mi downstream from confluence of West and Elm Forks, and at mile 500.3.

DRAINAGE AREA. -- 6.106 mi .

PERIOD OF RECORD.--October 1898 to December 1899 (gage heights only published in WSP 28 and 37), July 1903 to current year.

REVISED RECORDS.--MSP 850: 1903-6 (monthly and annual means). WSP 1732: 1937(M). WSP 1922: Drainage area. WDR TX-73-1: 1972.

GAGE.--Water-stage recorder. Datum of gage is 368.02 ft above National Geodetic Vertical Datum of 1929. Oct. 1.
1898. to Dec. 31. 1899. nonrecording gage at site 2 mi upstream at different datum. July 1. 1903. to July 20.
1930. non-recording gage at present site and datum. July 21, 1930, to Sept. 30, 1932, nonrecording gage at site 6 mi downstream at datum 3.08 ft lower.

REMARKS..-No estimated daily discharges. Records good. At times, flow is affected by storage in seven upstream reservoirs, combined capacity 1,703,000 acre-ft, of which 846,200 acre-ft is for flood control. The city of Dallas diverts water for municipal use from Elm Fork, Lake Ray Hubbard (on the East Fork), and Lake Tawakoni (on the Sabine River), and purchases water from North Texas Municipal Water District (from the East Fork). Sewage effluent is returned to the river downstream from this station. The Trinity River Authority discharges sewage effluent into the river upstream from the station. For additional information on diversions and effluent returns upstream from this station, see stations 08048000, 08049200, and 08049500. Several observations of water temperature were made during the year. Gage-height telemeters at station.

AVERAGE DISCHARGE.--86 years, 1,553 ft<sup>2</sup>/s (1,125,000 acre-ft/yr).

EXTREMES FOR PERIOD OF RECORD.--Maximum discharge. 184,000 ft³/s May 25, 1908 (gage height, 52.6 ft), from rating curve extended above 109,000 ft³/s; minimum observed for periods 1903-6, 1920-75, 1.2 ft³/s July 4, 1953, result of storage behind temporary dam 4 mi upstream.

Maximum stage since at least 1840, that of May 25, 1908.

EXTREMES OUTSIDE PERIOD OF RECORD .-- Flood in 1866 reached about the same stage as that of May 25, 1908.

EXTREMES FOR CURRENT YEAR.--Maximum discharge, 58,700 ft<sup>3</sup>/s May 17 at 1930 hours (gage height, 43.31 ft); minimum daily, 318 ft<sup>3</sup>/s Dec. 2.


		DISCHAF	GE. CUBIC	FEET PER	SECOND,	, WATER YEAR MEAN VALUES	OCTOBER	1988 TO	SEPTEMBER	1989		
DAY	OCT	NOV	DEC	JAN	FEB	HAR	APR	MAY	JNM	JUL	AUG	SEP
1 2 3 4 5	1650 1120 639 486 441	469 426 395 390 383	320 318 347 320 332	409 375 370 356 346	655 860 1820 830 551	643 615 618 666 789	3650 1930 1280 1080 1480	1130 1060 4000 6370 16400	4540 5650 8150 10900 14400	11300 11700 14800 13600 10300	4900 5000 5410 5120 4920	521 470 468 459 469
6 7 8 9	428 413 417 423 407	375 375 375 370 360	331 371 504 487 844	344 329 325 323 326	487 638 805 466 453	1030 1220 1030 999 837	1810 2000 2040 1990 1980	16900 13700 9160 4850 2910	12000 13500 22800 21100 16500	10000 10900 11500 12100 11800	5270 6390 6700 4630 3790	469 487 491 487 497
11 12 13 14 15	400 392 388 376 377	364 540 495 409 581	1770 1060 492 406 383	328 423 680 613 449	437 491 638 558 873	687 650 641 636 630	1960 1810 2080 6390 4030	2430 2160 2310 2510 2230	14800 16800 26200 42100 37800	11000 10200 9850 8660 9280	3560 3200 2620 2370 2210	1490 2530 2970 3840 1180
16 17 18 19 20	373 381 379 373 372	826 461 398 811 1210	350 336 338 341 350	376 359 344 338 340	3180 7990 13600 6750 2850	581 567 523 515 533	1920 1470 1220 922 799	6220 37500 43000 28100 21000	29800 26000 22600 19300 16800	8170 7580 7370 7080 6890	2130 2850 4470 2530 2170	629 552 477 458 408
21 22 23 24 25	366 362 366 365 366	491 354 348 340 365	336 569 755 554 374	334 344 358 371 472	1600 1490 1620 1390 954	1050 1380 938 802 654	783 750 734 717 707	18100 15900 12900 10800 9760	15000 13100 10900 9120 7840	7030 6570 6320 6060 5850	2050 1950 1760 1690 1640	409 395 357 377 373
26 27 28 29 30 31	401 595 615 709 690 525	452 412 348 340 325	333 542 1290 822 427 429	4140 2410 3580 7630 2950 1300	846 753 715 	633 631 7540 16300 14000 7650	707 694 667 1000 1020	9140 8700 7910 5920 4220 3870	6930 7390 9390 9720 10900	5710 5610 5360 5070 4940 4900	1570 1450 1400 1400 1270 786	369 356 354 359 358
TOTAL MEAN MAX MIN AC-FT	15595 503 1650 362 30930	13788 460 1210 325 27350	16431 530 1770 318 32590	31642 1021 7630 323 62760	54300 1939 13600 437 107700	2129 16300 515	1654 6390 667	331160 10680 43000 1060 656900	16070 42100 4540	267500 8629 14800 4900 530600	97206 3136 6700 786 192800	23059 769 3840 354 45740

CAL YR 1988 TOTAL 199911 MEAN 546 MAX 7120 MIN 277 AC-FT 396500 WTR YR 1989 TOTAL 1448319 MEAN 3968 MAX 43000 MIN 318 AC-FT 2873000

**Special Studies** 

Series P-23. No. 156

# Estimates of Households, for Counties: July 1,1985





U.S. Department of Commerce BUREAU OF THE CENSUS

Table 1. Estimates of Households, for Counties: July 1, 1985-Continued

(A dash (-) represents zero or rounds to zero. Estimates are consistent with special censuses since 1980. Corrections to 1980 census counts are not included. See text concerning rounding and average population per household)

		Househ	alda		popule	erage stion per		<b>9</b>	•	
State and county		nousen	J.C.S			enold	<u> </u>	Popular	lion .	
,	July 1.	April 1,	Change, 1	980-85	July 1, 1985	April 1,	July 1.	April 1.	Change, 1	980-85
	1985	1980			(esti-	1980	1985	1980		
	(estimate)	(census)	Number	Percent	mate)	(census)	(estimate)	(CONSUS)	Number	Percen
Continued				)		}		Ì		
Sestrop.	12,200	8,719	3,500	39.8	2.75	2.78	34,300	24,728	9,600	38.
Baylor	2,100	2,027		2.4	2.25	2.39	4,700	4,919	-200	-3.
300	8,700	8.181	500	6.0	3.00	3.06	26.900	26,030	800	3.
	63.700	52,661 320,639	11,100 57,600	21.0 18.0	2.59 2.92	2.79 2.98	174,900 1,139,100	157,889	17.000	10.
Bessar Banco	378.300 2.200	1.825	400	20.0	2.53	2.52	5.600	988,800 4,681	150,300 1,000	15. 20.
Borden	300	299	100	-1.3	2.97	2.87	900	859	1,000	20.
Bosque	5,900	5.513	400	6.7	2.34	2.36	14,100	13.401	700	5.
lowie	30,200	27,449	2.700	9.9	2.63	2.70	80.500	75.301	5.200	6.
Prazoria	59.900	53.907	6,000	11.1	2.99	3.00	187,200	169,587	17,600	10.
3re <b>2</b> 0e	43,300	32.488	10.800	33.2	2.57	2.60	121,500	93.588	27,900	29.
Provistor	2.900	2.694	200	5.8	2.60	2.63	7.900	7.573	400	23.
Briscoe	900	967	-100	-9.0	2.59	2.67	2.300	2.579	-300	-11
Brooks	2.900	2.614	300	10.3	3.16	3.20	9,200	8,428	800	8.
Prown.	13,100.	12,308	800	6.3	2.54	2.56	34,500	33.057	1,500	4.
Burleson	5,300	4,459	800	18.0	2.79	2.73	14,800	12,313	2.500	20.
Surnet	8,800	6,951	1,900	26.7	2.57	2.53	22,900	17,803	5,100	28.
aldwell	9,000	7,361	1,700	22.4	2.73	2.85	27,800	23,637	4,200	17.
Calhoun	7,500 4,800	6,469 4,150	1,000	15.7 15.6	2.86 2.57	3.01 2.61	21,600 12,500	19,574 10,992	2,000 1,500	10. 13.
				· ·	_	1	11			•
Carneron	73,900	58.418	15,500	26.6	3.37	3.56	252,000	209,727	42,300	20.
Camp	3,700	3,404	300 100	8.7 2.9	2.68	2.70	10,000	9,275	700	7.
Carson	2,500 10,900	2.395 10.515	400	4.0	2.72 2.75	2.73 2.76	6,800 30,500	6,672 29,430	200 1,100	2. 3.
Cass Castro	3.100	3,136	-100	-2.6	3.36	3.34	10.300	10.556	-200	-2.
Chambers	6.600	6.248	400	5.8	2.96	2.96	19.600	18.538	1.100	5.
Cherokee	14.500	13.627	900	6.4	2.63	2.67	39.700	38.127	1.500	4.
Childrens	2.600	2.778	-200	-6.4	2.44	2.46	6,500	6.950	-500	-7.
Zev	3,700	3.607	•	1.3	2.62	2.62	9,700	9.582	100	1.
Cochran	1,400	1,515	-100	-4.4	3.22	3.12	4,800	4,825	-100	-1.
Coke	1,400	1,257	200	12.2	2.42	2.47	3,500	3,196	300	9.
Colemen.	4,300	4,243	100	2.5	2.35	2.41	10,400	10,439	•	<b>-0</b>
Collin	65,000	46,373	18,600	40.2	2.98	3.08	195.900	144,576	51.300	35.
Collingsworth	1.600	1,790	-200	-13.4	2.54	2.56	4,000	4,648	-700	-14.
Colorado	7,300	6,938	400	5.4	2.71	2.67	20,200	18.823	1,300	7.
Cornel	16.800	12,958	3,800	29.5	2.74	2.77	46,600	36,446	10,100	27.
Comenche	5,200	4,973 1,091	200 -100	4.2 -5.9	2.44	2.48 2. <b>6</b> 4	12,900 2,800	12,617   2,915	300 -100	2.: -3.
Concho	1,000 10,500	10.078	500	4.7	2.70	2.68	29,100	27,656	1,500	-3. 5.
Cooke Coryeti	14.800	14,080	700	5.1	3.04	3.06	59,300	56,767	2,500	4.
•		ı					l <b>!</b>	2.947	-300	
Cottle	1,000	1,164 1,552	-100 100	-12.8 9.2	2.57 2.90	2.49 2.95	2,700 4,900	4.600	300	-9. 7.
Crane	1,700 1,600	1,558	100	5.3	2.83	2.93	4.700	4.608	100	1.
Crockett	2.900	2,920	.00	-0.3	2.84	3.00	8,400	8.859	-500	-5.
Culberson	1,100	987	100	9.5	3.11	3.35	3,400	3.315	100	1.
Dallarn	2.400	2,386		1.8	2.73	2.74	6,600	6,531	100	1.
Dallas	689.600	577,701	111,900	19.4	2.57	2.66	1,794,000	1,556.390	237.600	15.
Dawson	5,700	5,483	300	4.8	2.81	2.93	16,300	16,184	100	0.
Deed Smith	6.300	6,487	-200	-3.2	3.18	3.24	20,100	21,165	-1,100	·5.
Delta	1,900	1,932	•	-1.8	2.44	2.45	4,700	4,839	-100	-2.
Denton	66,700	49,134	17,500	35.7	2.72	2.77	188,700	143,126	45.600	31.
De Witt	7,400	7,056	300	4.7	2.65	2.61	20,000	18,903	1,100	5.
Dickens	1,200	1,369	-200	-15.2	2.65	2.56	3,100	3,539	-400	-12.
Dimmit	3,400	3,135	200	6.9	3.47	3.58	11,800	11,367	400	3.
Donley	1,600	1,608	•	-2.6	2.45	2.43	4,000	4,075	•	-1.
	, ,			•	•		. ,			

### **MEMORANDUM**

Reference 17

TO:

File

FROM:

S. Bret Kendrick, Task Manager

DATE:

February 4, 1993

RE:

Measurements and Calculations for GNB

The following measurements were calculated directly from U.S.G.S. 7.5-Minute topographic series maps.

### 15-Mile In-Water Segment

Rawhide Creek is approximately 3,000 feet south-southeast of the site (PPE).

Rawhide Creek flows approximately 1.57 miles from the PPE before entering the Elm Fork of the Trinity River.

The Elm Fork of the Trinity River flows approximately 11.24 miles from Rawhide Creek before entering the Trinity River.

The remaining 15-mile in-water segment is contained within the Trinity River.

### Identified Features on the Topographic Maps within Defined Radii

0 - 1/4 Mile Radius

2 houses

1/4 - 1/2 Mile Radius

13 houses

1/2 - 1 Mile Radius

37 houses

1 - 2 Mile Radius

3 schools

1 park

Memorandum to File Measurements and Calculations for GNB February 4, 1993 Page 2

### 2 - 3 Mile Radius

4 schools 2 parks

### 3 - 4 Mile Radius

2 schools 1 country club

### Calculations for Populations

Populations within 1 mile of the site were calculated by conducting a house count and multiplying the number of houses by the average population per household for Dallas County. The average population per household for Dallas County is 2.57 (Ref. 16).

### 0 - 1/4 Mile Radius

2 houses x 2.57 persons/household = 5.14 persons

### 1/4 - 1/2 Mile Radius

13 houses x 2.57 persons/household = 33.41 persons

### 1/2 - 1 Mile Radius

37 houses x 2.57 persons/household = 95.09 persons

STATE	CITY NAME	FIPSCODE	LATITUDE	LONGITUDE		
ТX	DALLAS	48113	32.9317	96.8750		

Press RETURN key to continue ...

CENSUS DATA

GNB Inc.

LATITUDE 32:55:12 LONGITUDE 96:54:58 1990 POPULATION

KM 0.00-.400 .400-.810 .810-1.60 1.60-3.20 3.20-4.80 4.80-6.40 TOTALS

S 1 0 0 79 9404 29788 28342 67613

RING 0 0 79 9404 29788 28342 67613

TOTALS

Press RETURN key to continue ...
Esc for Attention Home to Switch

Esc for ATtention, Home to SWitch | Capture Off | On: 00:07:41

TYPE: Telephone Call DATE: 2/4/93 TIME: 1115

TO: Agetha Benjeman, RCRA FROM: B. Kendrick, Geologist, ICF

Enforcement, EPA (214) 655- Technology, Inc. (214) 979-

6745 3905

**SUBJECT:** Current Regulatory Status of GNB

### **SUMMARY OF COMMUNICATION:**

A Consent Decree was signed on January 31, 1993 for the installation of additional monitoring wells in an effort to receive a certified clean closure of the surface impoundments.

### **MEMORANDUM**

Reference 20

TO:

File

FROM:

S. Bret Kendrick, Task Manager

DATE:

February 4, 1993

RE:

On-Site Reconnaissance Inspection of GNB, Inc.

The on-site reconnaissance inspection was conducted on January 14, 1992. The MK/ICF team consisted of Alex Zocchi, Team Leader and Brad Cune, Site Safety Officer. The team met with Mr. Bill Backus and Mr. Richard Thompson of GNB. The team made a visual inspection of the closed impoundments. The impoundments appeared to have been inactive for a long period of time and they were highly vegetated. Also noted during the inspection were two monitoring wells. The team received from site representatives sampling results collected by the Texas Water Commission from monitoring wells in March, 1990.

The above information was taken directly from the log book entries made by Mr. Alex Zocchi.



### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VI 1201 ELM STREET DALLAS, TEXAS 75270 January 8, 1982

•

TXD007331879

Attn: Everett Milton

P.O. Box 43140 St, Paul MN 55164 1880 Valley View Lane Farmers Branch, Texas

The RCRA permit application submitted on the above facility was returned to you a few weeks ago with a request for clarification of information, and to date we have received no response. In order to continue the processing of your application, we must receive the following information:

Process Information: TO2 can only be in gallons per day or liters per day Waste Information: Please explain page 3 of 5 T23, T44, and D85

To prevent further delay in processing, please provide this information to us within ten days of the date of this letter. Return the information to:

EPA - 6EP RCRA Activities 1201 Elm Street Dallas. Texas 75270

Should you have questions, please contact Mr. Dwight Corley at (214) 767-2765, or at the above address.

Thanks very much for your cooperation.

Sincerely,

Fred B. Woods, Chief Administrative Branch

cc: File/Referenced Facility

Part A, Permit Process --- Internal Checklist

Defende	PHASE ONE	Indicate by	Valid
Refer to Form No:	Interim Regulatory Recuirements	your initials: — Yes No	Pralg <u>Qate?</u>
1 .	T/S/D'Facility? (If No, return to respondent.)	MM -	
3 , ".	Form 1 received?	MM	
<b>-1</b>	Form 3 received?	MM	
1 & 3	Postmarked on or before November 19, 1980?	MM	
3	Date of operation entered?		•
<b>3</b>	Date of operation on or before November 19, 1980?	MM	
Notif.	Notifier?	MM -	- ·-
, ecol a	Notified on or before August 18, 1980?	MM	
1	Form 1, XIII B signed?	mn	
3	Form 3, IX B Signed?	Marie	
. •	ment and indicate the trigger date here:  PHASE TWO	j	٠.
1 .	Unsure if regulated or non-regulated?	GT	
3	New facility?	6-7	
1 & 3	Core items missing? If Yes, indicate which items:		
	Facility name; location; mail address; op	erator info;	
	certification; process info; waste infoX;	owner; sigs	
	PHASE THREE	•	
1 & 3	Non-core items missing? If Yes, indicate which ite	ens:	
•	Maps; photos; drawings; lat/long	•	
	Other observations and comments:	•	
		Received Date St.	emp
	•	onlula	
Log out/Log		1011111	
on reverse	side.	(Stamp forms also	2)

ITINUED FROM THE FRONT	EPA I.D. NUMBER: TXD007331879 / 7
. SIC CODES 14-digit, in order of priority)	
A. FIRST	B. SECOND
3 6 9 1 Batteries, Storage	7
(specify)	D. FOURTH
19 - 19	7
OPERATOR INFORMATION	
A. NAME	B. Is the name listed in Item VIII-A also the
GOULD INC	owner?
<u> </u>	56
C. STATUS OF OPERATOR (Enter the appropriate letter into the answ	
= FEDERAL M = PUBLIC (other than federal or state) = STATE O = OTHER (specify) = PRIVATE	(specify)
E, STREET OR P.O. BOX	
D B O X 4 3 1 4 0	
F. CITY OR TOWN	G.STATE H. ZIP CODE IX, INDIAN LAND
T PAUL	M N 5 5 1 6 4 Is the facility located on Indian lands?
<del></del>	YES LANO
XISTING ENVIRONMENTAL PERMITS	40 41 42 47 - BI
······································	ns from Proposed Sources)
	<del>- 1 - 1 - 1 - 1 - 1 - 1</del>
20 70 10 17 10	
E. OTHE	ER (specify)
	(specify)
(a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	ER (specify)
	(specify)
10 10 10 10 10 10 MAP	10
outline of the facility, the location of each of its existing and	to at least one mile beyond property bounderies. The map must show proposed intake and discharge structures, each of its hazardous waste jects fluids underground. Include all springs, rivers and other surface nts.
Manufacture of Lead Acid Automotive Storage 1	Batteries
•	
pertify under penalty of law that I have personally examined and achiments and that, based on my inquiry of those persons implication, I believe that the information is true, accurate and col	am familiar with the information submitted in this application and all mediately responsible for obtaining the information contained in the mplete. I am aware that there are significant penalties for submitting t.
techments and that, based on my inquiry of those persons imm	mediately responsible for obtaining the information contained in the mplete. I am aware that there are significant penalties for submitting t.
ertify under penalty of law that I have personally examined and actiments and that, based on my inquiry of those persons implication; I believe that the information is true, accurate and coles information, including the possibility of fine and imprisonment	mediately responsible for obtaining the information contained in the mplete. I am aware that there are significant penalties for submitting t.
restify under penalty of law that I have personally examined and sachments and that, based on my inquiry of those persons immolication, I believe that the information is true, accurate and conse information, including the possibility of fine and imprisonment where a official TITLE (type or print)  Vice President, General Manager  MMENTS FOR OFFICIAL USE ONLY	mediately responsible for obtaining the information contained in the implete. I am aware that there are significant penalties for submitting t.  C. DATE SIGNED  11/18/80
sertify under penalty of law that I have personally examined and achiments and that, based on my inquiry of those persons immolication, I believe that the information is true, accurate and conse information, including the possibility of fine and imprisonment where a official TITLE (type or print)  Vice President, General Manager	mediately responsible for obtaining the information contained in the implete. I am aware that there are significant penalties for submitting t.  C. DATE SIGNED  11/18/80

		CHURCH							Form Approve	d ON'S No	158-5800	ን:	_
		HAZARE	SWAST						L EPA LD.	NUMBER	<del></del>		
	PA		Consolidated	i Permits Pro	grain					0 0 7 3	3 1 8	7,9	
بر	AL USE ONLY				40.00	70							7
11071	DATE HECCIVED						co	MMENTS					_
	1	-		···		<del></del>	-						
II. FIRST OR	REVISED APPL	ICATION				ر به در شومه				्र विक्रम् स		-	9
rev.sed application	the appropriate box on. If this is your fi or in Item I above.	irst application a	n <b>a you</b> arrestay k	ingw your ta	icitity.	theth SEP	er th 4 1.0	os is the first: ), Number, or	if this is a revised	re submittin   application	g for your , enter you	facility or ir facility's	3
A. FIRST APP	LICATION (place)	e an "X" below ( See instructions Complete item b	for definition of	appropriate ( "existing"	date) ocility				2.NEW FAC		plete item		<u></u>
8 700	1 0 2 iune	EXISTING FACE PATION BEGA the boxes to the	N OR THE DAT								ROVIDE T M, MO, L I ION BEGA XPECTED	HE DATE (ay) OPER IN OR IS	r A
B. REVISED A	APPLICATION (		ow and complete	e Item I abou	re)			<del></del>	2. FACILIT	Y HAS A R	CRA PERN	41T	_
71	ES - CODES AN		PACITIES				स्तु का सुरक्ष		1,	Version Control	4		ाषु
entering code describe the p B. PROCESS DE 1. AMOUNT	DDE — Enter the cos. If more lines are process lineluding its ESIGN CAPACITY — Enter the amound MEASURE — For	e needed, enter the design capacity  — For each code nt.	e code(s) in the ) in the space potential in the space potential in column to the colu	space provided on the min A enter t	led, if he form the cap	a pr n (/te sacity	ocess em II I of t	s will be used (1-C). The process.	that is not includ	ed in the lis	t of codes t	uclow, ther	1
measure u	sed. Only the unit		are listed below OPRIATE UNIT		sed.				PRO-	A PPR OP	RIATE UN	IITS OF	
200	CESS	CESS MEAS	URE FOR PRO	CESS			D.C.	OCESS.	CESS	MEASUR	RE FOR PE	ROCESS	
Storage:	ICESS	CODEDE	SIGN CAPACIT	<del></del>	Treat			ROCESS	CODE	DE91	GNLCAPA	-1 L.L	•
	(barrel, drum, etc.)		NS OR LITERS		TAN				TOI	GALLONS LITERS P		/ OR	
WASTE PILE		503 CUBIC CUBIC	YARDS OR METERS					POUNDMEN		CALLON LITERS P	CP CAY		
SURFACE IMP	OUNDMENT .	SO4 GALLO	NS OR LITERS	ı	INCI	NEH	A 1 C			METRIC 1	THOUSER TONS PER SPER HOL	HOUR.	
INJECTION W	ELL	D80 ACRE-I would c depth o	NS OR LITERS FEET (the volum over one acre to f one foot) OR RE-METER	e that	them proce	ral o	r bio. not i	for physical, e logical treatm occurring in to adminit or in	ent inks,		ER HOUR SPER DAY		
LAND APPLIC OCEAN DISPO SURFACE IMP	SAL	DB1 ACRES DB2 GALLO LITERS	OR HECTARE! NS PER DAY O PER DAY NS OR, LITERS	R	ators	De	scrib	e the processe ided; Hom H	s in				
		UNIT OF	•					NIT OF				UNIT OF	
UNIT OF MEA	SURE	MEASURE CODE	UNIT OF	MEASURE				CODE	UNIT OF M	EASURE		MEASUR CODE	Ε
				ER DAY					ACRE-FEET HECTARE-				- ;
CUBIC YARDS		<del>Y</del>	METRIC	ONS PER H	IOUR.			w	ACRES HECTARES			8	į
GALLONS PE	COMPLETING IT	U	LITERSP	ER HOUR .				H					. i
ther can hold 40	00 gallons. The foc	ility also has an i	ncinerator that	can burn up	to 20	olle	ns pe	r hour.	rage turks, onex	ank can no.	u 200 gano	ns sna me	: 
	DUP	7/4 6			//	/	/		[.].]			1//	
A. PRO-	B. PROCESS	DESIGN CAP	ACITY		~	A. P	RO.	B. PR	OCESS DESIG	N CAPAC	TY	500	
CESS CODE (from list obove)		OUNT cify)	2. UNIT OF MEA- SURE (cnter code)	FOR OFFICIAL USE ONLY		CE CO (from	SS DE List		1. AMOUNT		2. UNIT OF MEA- SURE (enter code)	OFFICE USE ONLY	
!S 0 2	600	)	-2   23   3   G		2	s n	3	19		77			
3703	. 20	)	E		6	- }	4	1.0	6.700		U		
T 0 1	150,0	000	U	111	7	7			0.000				
т 0 2	3,500,0	000	G		8								
s 0 4	Include	ed above			9								
S 0 3	4,5	500	Y		10	$\prod$							
\ Form 3510-				PAGE						00	NTINUE O	NEVER	i i E

portable chemical fixation process, erected and operated on site periodically as required by the accumulated volume of process sludge.

. OR DESCRIBING OTHER PROCESSES (code "TO

Chemical fixation is used to treat process sludge to prepare it for ultimate disposal.

The chemical fixation process has a design capacity of approximately 100,000 gallons per day.

DESCRIPTION	OF HAZARDOUS	WADILD .

let be referen EPA HAZARDOUS WASTE NUMBER - Enter the four-digit number from 40 CFR, support U for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristies and/or the toxic contaminants of those hazardous wastes.

ESTIMATED ANNUAL QUANTITY - For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/ that will be handled which possess that characteristic or contaminant.

UNIT OF MEASURE - For each quantity entered in column 8 enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH	ш	N	Ľ	Ľ	Q	E.	M	ĮΕ	Α	S	Ц	B	E	_	_		_	_	_	_	_	۷	C	וםנ	E
POUNDS.																					•	•		F	
TONE																								-	

CODESON

METRIC UNIT OF MEASURE 

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

### **PROCESSES**

### PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code/s/ from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant,

Note: Four spaces are provided for entering process codes, if more are needed; (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

OTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardor's wastes that can be described by ore than one EPA Hazardous Waste Number shall be described on the form as follows:

- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

KAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds er year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes e corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 20 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill

1.					C. UNIT OF MEA- SURE (enter code)			D. PROCESSES												
h			10	B. ESTIMATED ANNUAL QUANTITY OF WASTE			1. PROCESS*CODES (enter)												2. PROCESS DESCRIPTION (if a code is not entered in D(1),	
1	٨	0	5	4	900	P		T	0	3	D	8	3 0		Τ_					;
T	D	0	0	2	400	P		T	0	3	D	5	3 0		1	T-		7-	T	
1	D	0	0	1	. 100	P		T	0	3	D	8	3 0		T	1		1	_	·
Ţ,	D	0	0	2	<del></del>				1	T		T	7-		7	T		Т		included with above

, completing if you have more than 26 wastes to list. Form Approved OMB No. 158-S80004 FOR OFFICIAL USE ON 8 W 3 3 DUP ESCRIPTION OF HAZARDOUS WASTES (continued) D. PROCESSES A. EPA HAZARD. WASTENO (enter code) B. ESTIMATED ANNUAL QUANTITY OF WASTE SURE (enler code) 1. PROCESS CODES
(enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) S 0 4 Т plalois 300 See Note 1 D006 Included with above D004 Included with above D|0|0|2 Included with above 5 6 T T 2 3 D 8 5 DIOIOI2 105,300 See Note 2 7 8 T See Note 3 13,000 (seenote 3) (one time only 10 11 12 13 14 s|contained|in process sludge| Material At periodic intervals 15 \$ection III.C) | sludge is processed using chemical 16 fixation. Resultant sludge is not a hazardous waste and can be 17 landfill. disposed of as 18 reatment is disposed of by POTW. Note 2: Liquid effluent from 19 This material is listed for reference only, since it was in Note 3: 20 Subsequent qualification tests have determined original submission. 21 is not a hazardous waste Material is chemically fixed material 22 from previous operating periods. Material can be process sludge 23 disposed of as andfi 24 25


26

3

9

DOUS WASTES		OM ITEM D(I) ON PAGE 3.		
THE ADDITIONAL P	ROCESS CODES FA	OM TIEM D(I) ON PAGE 3.		
and the second second		•		
		•		
	•			
•				
•				
	•			;
•				
		•		:
		•		•
				ļ
•				ı
	•	•		•
				;
				:
EPA I.D. NO. (enter from page 1)			•	· }
TXD0073318796				;
FACILITY DRAWING		NAME OF THE PERSON OF THE		200
I existing facilities must include in the space provided	i on page 5 a scale drawi	ing of the facility (see instructions	for more detail.	المنسة
PHOTOGRAPHS	<b>经理机制理</b>	大学の開始を選択し		7
Il existing facilities must include photographs	(aerial or ground—lev	el) that clearly delineate all ex	kisting structures; existing storage,	
eatment and disposal areas; and sites of future	storage, treatment or	r disposat areas (see instructio		
II. FACILITY GEOGRAPHIC LOCATION				issi
LATITUDE (degrees, minutes, & sec	onds)	LONGITUD	E (degrees, minutes, & seconds)	<del></del>
32 55 012	•	l bk	8 5 4 0 5 8	}
III. FACILITY OWNER				magnet 1
_	A			السمات
A. If the facility owner is also the facility operato skip to Section IX below.	r as listed in Section VII	I on Form 1, "General Information	on", place an "X" in the box to the left and	į
		. <b>.</b>		1
8. If the facility owner is not the facility operator	as listed in Section VII	I on Form 1, complete the follow	ving items:	1
1. NAME OF F	ACILITY'S LEGAL OW	NER	2. PHONE NO. (area code & n	0.1
				1.
16			<u>,, 10 , 10 , 10 , 10 , 10 , 10 , 10 , 1</u>	<del></del>
3. STREET OR P.O. BOX		4. CITY OR TOWN	. S.ST. 6. ZIP CODE	
•	녆			- 1
Of Mary Const	49 19 14	CAN SAFFAS I DAMEST FOR A SECOND	12-12-12-12-12-12-12-12-12-12-12-12-12-1	170
COWNER CERTIFICATION				
certify under penalty of law that I have person ocuments, and that based on my inquiry of tho				1
ibmitted information is true, accurate, and con	nplete. I am aware th	at there are significant penalti	ies for submitting false information,	- 1
cluding the possibility of fine and imprisonme		•	•	1
. NAME (print or type)	B. SIGNATURE		C. DATE SIGNED	$\neg$
dies Drosidant Onematica		7 ( Deen	1	
ice President, Operations	11/10		5/11/81	]
OPERATOR CERTIFICATION	<b>建筑区域</b>		ACTIVITY OF THE PARTY OF THE PA	
certify under penalty of law that I have person	ally examined and an	familiar with the information	n submitted in this and all attached	
ocuments, and that based on my inquiry of the	nse in <del>dividuals imme</del> d	liately responsible for obtaining	ng the information, I believe that the	]
ubmitted information is true, accurate, and con ocluding the possibility of fine and imprisonme		at there are significant penalti	ies for submitting false information,	1
				1
· NAME (print or type)	B. SIGNATURE		C. DATE SIGNED	
				}
A Form 3510-3 (6-80)			CONTINUE ON PA	ل
7 1 9 M 9 3 1 4 3 10 4 0 1	0405	A OF 5	231111101 0:114	

PAGE 4 OF 5



SCALE: 1": 300'

			1	LAN	<b>-&gt;</b>	GOU	LD	AU	AUTOMOTIVE BATTERY DIVISION ST. PAUL, MINNESOTA				
			DALLAS,	· · · · ·		℃, CH.			DRAWING NO.				
A	5/12/81	ADDED TO 4 FIXATION SYS	S GOULD HAS PROPRIETARY RIGHTS	TOLERANCE UNLESS OTHERWISE SPECIFIED .000:	PART N	10-27-80 NO.	8	7	4	A-	125	A	
SSUE	DATE	REVISION	IN THIS MATERIAL	FRACTIONS 1				<u> </u>	'	,		, ,	